



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 15/05/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	olr acted	reset	16:40:00	16:50:00	
2	OHP	co 50	olr acted	reset	17:50:00	18:05:00	
3	OHP	wobr on co 6A	Lt not working,local PB acted	released	18:40:00	18:55:00	
4	OHP	TBS on co 24	LT not working,M4 olr acted	reset	20:55:00	21:10:00	
5	CHP	CC 33 SCR2	boom position physically in GVM side but it shown in ohp side,	bypass in i/o	15:20:00	15:30:00	bypass removed @1740
6	CHP	CC 43	olr acted	reset	15:40:00	15:45:00	
7	CHP	CC 125	mpd acted	reset	21:20:00	21:25:00	
8	WT	OP7	no fwd movement,Ls2 acted	striker bend,LS2 bypassed	19:50:00	20:00:00	
9	WT	OP6	no movement,bottom pad not proper connected to bus bar due to plant obstruction	@col no 35,obstruction cleared,and made proper connection	16:50:00	17:10:00	
10	WT	OP3	no movement,d3 olr acted	D3 coil connection removed and given clearance	21:45:00	22:10:00	
11	IOSA	1-28hvmcc6	i/c1 tripped due to UV	reset and made on	14:50:00	15:20:00	