



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 23/06/2026

Incharge(s): K SANKARA RAO

Shift: B

| Sl No | Area | Equipment       | Problem                                                                              | Action                 | From                 | To                   | Remarks |
|-------|------|-----------------|--------------------------------------------------------------------------------------|------------------------|----------------------|----------------------|---------|
| 1     | OHP  | WOBR ON CO-29   | LUFFING OLR ACTED                                                                    | RESET DONE             | 14:10:00             | 14:20:00             |         |
| 2     | OHP  | BRC ON CO-30    | REPORTED B/W -1 NOT RUNNING FOUND WIRE LOOSE AT OLR                                  | PROPERLY FIXED THAN OK | 20:30:00             | 21:00:00             |         |
| 3     | OHP  | CO-53           | CONTROL MCB FAILD                                                                    | MCB REPLACED THAN OK   | 20:30:00             | 21:00:00             |         |
| 4     | CHP  | CC-58           | OLR ACTED                                                                            | RESET DONE             | 17:30:00             | 17:40:00             |         |
| 5     | CHP  | CC-51           | MPD TRIP                                                                             | RESET DONE             | 16:50:00<br>17:00:00 | 16:55:00<br>17:05:00 |         |
| 6     | CHP  | S2 ON CC 39 B/C | ZSS CAGE PIN LOOSE                                                                   | PROPERLY FIXED         | 14:20:00             | 14:30:00             |         |
| 7     | CHP  | CC 43           | OLR ACTED                                                                            | RESET                  | 16:45:00             | 16:50:00             |         |
| 8     | CHP  | SCR 9 ON CC 106 | B/C                                                                                  | OPERATOR FAULT         | 20:50:00             | 21:00:00             |         |
| 9     | WT   | OT-4            | HYDRALIC PUMP NOT RUNNING EARTH FAULT IN CONTROL SUPPLY DUE TO MCB TRIP IN PLC PANAL | MCB MADE ON            | 18:10:00             | 18:40:00             |         |