



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 04/07/2026

Incharge(s): G Eswara Rao

Shift: A

| Sl No | Area | Equipment      | Problem                                                          | Action                                  | From                 | To                   | Remarks |
|-------|------|----------------|------------------------------------------------------------------|-----------------------------------------|----------------------|----------------------|---------|
| 1     | OHP  | CO 29          | TRIPPED ON OLR                                                   | RESET DONE                              | 06:20:00<br>09:40:00 | 06:30:00<br>09:50:00 |         |
| 2     | OHP  | TT 1 ON CO 14  | LT NOT TAKING PLACE                                              | CONTROL FUSE BLOWN(110V AC)             | 07:05:00             | 07:25:00             |         |
| 3     | OHP  | TBS ON CO 22   | LBC NOT RUNNING/ZSS PROBE DIRECTED                               | PROBE REPLACED THEN OK                  | 08:40:00             | 09:00:00             |         |
| 4     | OHP  | WOBR ON CO 26  | LT NOT TAKING PLACE/                                             | FAULT RESET DONE                        | 08:50:00             | 09:10:00             |         |
| 5     | OHP  | WOBR ON CO 26  | BC NOT RUNNING/CHUTE SENSOR ACTED                                | PROBE CLEANED THEN OK                   | 10:15:00             | 10:30:00             |         |
| 6     | CHP  | CC-201         | OLR ACTED                                                        | REST DONE                               | 13:00:00             | 13:10:00             |         |
| 7     | CHP  | CC-54          | OLR ACTED                                                        | RESET DONE                              | 09:50:00             | 10:00:00             |         |
| 8     | CHP  | CC-58          | CURRENT SP FAULT                                                 | REST DONE                               | 09:30:00             | 09:40:00             |         |
| 9     | CHP  | SCR-3 ON CC-37 | REPORTED B/C STOPPING ON ZSS CHECKED AND FOUND ZSS PROBE DAMAGED | ZSS PROBE REPLACED WITH NEW ONE THAN OK | 06:20:00             | 06:35:00             |         |
| 10    | CHP  | SCR-2 ON CC-33 | LT NOT TAKING PLACE DRIVE TRIP                                   | RESET DONE                              | 12:35:00             | 12:45:00             |         |
| 11    | WT   | OP-4           | DRIVE -2 TRIP                                                    | RESET DONE THAN OK                      | 09:50:00             | 09:55:00             |         |