TES SECURITY SERVICES

NON-CONFORMANCE REPORT

I-001

Generated: 21/03/2026

Closed | High | Major

TITLE
Fire Alarm Activation - Main Entrance

SITE
Main Entrance, Gate 1

CATEGORY
Fire

DEPARTMENT
Security Operations

REPORTED BY
b68df2ca-d54f-42aa-ba25-aab137fb9f09

ASSIGNED TO
—

DATE LOGGED
21/03/2026

DUE DATE
N/A

DESCRIPTION

Fire alarm activated at main entrance at 14:32. Security guard on duty responded immediately. All personnel evacuated in orderly manner. Fire brigade attended site within 8 minutes. Investigation confirmed false alarm caused by steam from nearby kitchen. All clear declared at 15:10. No injuries reported. Site manager notified.

ROOT CAUSE

False alarm caused by steam from kitchen ventilation system near detector

REMEDIAL ACTION TAKEN

Relocate smoke detector away from kitchen ventilation. Brief all security staff on evacuation procedures.