Boxmaker Parameters

Height, Width, and Depth define the size of the box.

These values must be given in millimeters (mm).

