Conduit routing inspection, Z12, 2025-09-04

Document number	INS-Z12-20250904-1
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Teague Bresk
Approved by	-
Date	2025-09-04

Inspection type	Conduit routing inspection
Zone	Z12
Date	2025-09-04
Inspector	Teague Bresk
Number of findings	7

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Weld porosity	Deck 71, frame 37	Minor	Grind out and re-weld; repeat inspection.	2025-09-11
F-02	Missing fastener	Deck 10, frame 138	Minor	Install fastener per drawing and record torque.	2025-09-07
F-03	Weld porosity	Deck 74, frame 171	Minor	Grind out and re-weld; repeat inspection.	2025-10-04
F-04	Missing fastener	Deck 11, frame 206	Critical	Install fastener per drawing and record torque.	2025-10-04
F-05	Missing fastener	Deck 61, frame 279	Critical	Install fastener per drawing and record torque.	2025-10-04
F-06	Conduit chafing	Deck 32, frame 158	Minor	Add protective sleeve and re-route.	2025-09-07
F-07	Plate misalignment at seam	Deck 52, frame 14	Minor	Re-shim and re-torque the seam.	2025-10-04

Assessment

2 critical findings; non-conformance reports raised.