# Fastener torque audit, Z23, 2024-09-04

| | |
|---|---|
| Document number | INS-Z23-20240904-1 |
| Revision | 1 |
| Status | APPROVED |
| Classification | INTERNAL |
| Author | Rain Calder |
| Approved by | - |
| Date | 2024-09-04 |

| | |
|---|---|
| Inspection type | Fastener torque audit |
| Zone | Z23 |
| Date | 2024-09-04 |
| Inspector | Rain Calder |
| Number of findings | 6 |

## Findings

| ID | Finding | Location | Severity | Action | Due |
|---|---|---|---|---|---|
| F-01 | Damaged insulation | Deck 38, frame 152 | Minor | Replace insulation segment. | 2024-09-11 |
| F-02 | Sealant gap | Deck 52, frame 239 | Minor | Clean and re-apply sealant; leak check. | 2024-10-04 |
| F-03 | Corrosion spot | Deck 37, frame 61 | Minor | Treat and re-coat the area. | 2024-09-11 |
| F-04 | Conduit chafing | Deck 42, frame 243 | Minor | Add protective sleeve and re-route. | 2024-09-11 |
| F-05 | Plate misalignment at seam | Deck 43, frame 116 | Major | Re-shim and re-torque the seam. | 2024-09-11 |
| F-06 | Weld porosity | Deck 50, frame 79 | Minor | Grind out and re-weld; repeat inspection. | 2024-10-04 |

## Assessment

No critical findings. Release after the actions are closed.