Pressure seal inspection, Z23, 2024-12-31

Document number	INS-Z23-20241231-1
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Saela Dallan
Approved by	-
Date	2024-12-31

Inspection type	Pressure seal inspection
Zone	Z23
Date	2024-12-31
Inspector	Saela Dallan
Number of findings	8

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Incorrect torque	Deck 50, frame 87	Minor	Re-torque to drawing value.	2025-01-07
F-02	Weld porosity	Deck 61, frame 41	Minor	Grind out and re-weld; repeat inspection.	2025-01-07
F-03	Incorrect torque	Deck 77, frame 293	Major	Re-torque to drawing value.	2025-01-03
F-04	Corrosion spot	Deck 57, frame 119	Minor	Treat and re-coat the area.	2025-01-30
F-05	Plate misalignment at seam	Deck 35, frame 75	Minor	Re-shim and re-torque the seam.	2025-01-30
F-06	Missing fastener	Deck 57, frame 94	Minor	Install fastener per drawing and record torque.	2025-01-30
F-07	Conduit chafing	Deck 75, frame 126	Minor	Add protective sleeve and re-route.	2025-01-30
F-08	Conduit chafing	Deck 25, frame 102	Minor	Add protective sleeve and re-route.	2025-01-14

Assessment

No critical findings. Release after the actions are closed.