Stress vs Strain of Specimen 40A3 50 Strain-Stress Curve Min. Stress Point 0 Stress Min.: -425.80 MPa Strain at Min.: -0.0187 -50 Compressive Stress [MPa]

Script Compressive Stress [MPa]

Compressive Stress [MPa]

Compressive Stress [MPa] -350 -400 -450 -0.002 -0.004 -0.006 -0.008 -0.01 -0.012 -0.014 -0.016 -0.018 Strain Mean over Region of Interest [-]