Stress vs Strain of Specimen 3A1 100 Strain-Stress Curve Min. Stress Point 0 Stress Min.: -839.55 MPa Strain at Min.: -1.3454 -100 Compressive Stress [MPa] -200 -300 -400 -500 -600 -700 -800 -900 -0.2 -0.4 -0.6 -0.8 -1.2 0.2 0 Strain Mean over Region of Interest [-]