




Wire Connections



A. Motor Connection (X/Y/Z/Extruder)

Χ	25 CM	PH	2510
		(Pin Number)	(Pin Number)
		1	1
		2	NC
		3	2
		4	3
		5	NC
		6	4
Υ	35 CM	PH	2510
		(Pin Number)	(Pin Number)
		1	4
		2	NC
		3	3
		4	2
		5	NC
		6	1
Z	50 CM	PH	2510
		(Pin Number)	(Pin Number)
		1	2
		2	NC
		3	3
		4	1
		5	NC
		6	4







Extruder	90 CM	PH	2510
		(Pin Number)	(Pin Number)
		1	3
		2	NC
		3	2
		4	4
		5	NC
		6	1

B. ENDSTOPS Connection

X	25 CM
Υ	35 CM
Z	20 CM

XH	XH
(Pin Number)	(Pin Number)
1	1
2	2
3	3
4	4

C. Extruder (Heater END)

90 CM

XH	2510
(Pin Number)	(Pin Number)
1	1
2	2
3	3
4	4