


Display Cutout and Mounting Holes – Setup Sheet




WORK ZERO POINT

Z0 – top of part

X0 – center of part


Y0 – far edge of part

TOOL - 1/6 ballmill <https://tinyurl.com/00625BALL>



3 Operations: Contouring opening, C-sink, hole
Machining time ~ 2:30 min

File: O1001.NC



Part drawing