SOUTH AUSTIN AUTO A/C

Auto Air Conditioning · Diagnostics · General Repair
4501 S. Lamar Blvd, Austin, TX 78745 · (512) 555-0147

REPAIR ESTIMATE

Estimate # SA-24-1087
Date Oct 24, 2026

CUSTOMER	VEHICLE	MILEAGE
Dev (demo customer)	**2010 Toyota Corolla S**	**171,000 mi**
VIN	TECHNICIAN	PROMISED
2T1BU4EE••••••••	**R. Alvarez, ASE A7**	**1 business day**

DIAGNOSIS

Customer reports A/C blowing warm air and a grinding noise when the A/C engages. Found compressor clutch bearing failure and internal compressor wear. Low system pressure confirmed with gauges. Recommend compressor replacement and full system service.

DESCRIPTION	QTY / HRS	AMOUNT
A/C system diagnosis	1	$95.00
A/C compressor assembly (remanufactured)	1	$545.00
Receiver / drier	1	$68.00
Expansion valve	1	$52.00
Refrigerant R-134a evacuate & recharge	1	$120.00
Labor: replace compressor, drier, valve	4.0 @ $130	$520.00
Shop supplies & disposal	1	$50.00

ESTIMATE TOTAL $1,450.00

Estimate valid for 30 days. Parts warranty 12 months / 12,000 miles. Labor warranty 12 months.

Customer approval: _____ Date: _____