

HOT WORK SAFETY RULES

WELDING, CUTTING AND GRINDING SAFETY

AUTHORIZE • PREPARE • PREVENT FIRE

01

VERIFY THE PERMIT

- Do not start without a valid hot work permit.
- Confirm the permit conditions and work boundaries.

02

REMOVE COMBUSTIBLES

- Move flammable materials to a safe distance.
- Protect materials that cannot be removed.

03

TEST THE ATMOSPHERE

- Verify required atmospheric and gas testing.
- Repeat testing if conditions change.

04

ASSIGN A FIRE WATCH

- Confirm a trained fire watch is present.
- Ensure continuous observation of the work area.

05

INSPECT EQUIPMENT

- Inspect cables, hoses, regulators and connections.
- Keep a suitable extinguisher immediately available.

06

CHECK AFTER COMPLETION

- Inspect for sparks, embers and hidden combustion.

STOP WORK IMMEDIATELY

- ✓ The permit is invalid
- ✓ Gas readings are unsafe
- ✓ No fire watch is present
- ✓ Combustibles are unprotected