

Manufacturing Action Plan - ISSUE-20260514-D03A8E

Issue ID: ISSUE-20260514-D03A8E | Generated: 2026-05-14 16:47 UTC
Generated by Manufacturing Issue Resolution System - Confidential

Verdict: Stabilize

Detected Anomalies

- temperature_c=305.493 breached > 90 for LINE-A / CNC-MILL-11.
- temperature_c=286.221 breached > 90 for LINE-A / CNC-MILL-11.
- output_units_per_hour=392 breached < 700 for LINE-B / PRESS-VALVE-23.
- vibration_mm_s=7.254 breached > 4.0 for LINE-A / CNC-MILL-11.

Root Cause Hypotheses

- Thermal anomaly likely caused by lubrication or cooling degradation. (86%)

Recommendations

{'stabilize': ['Reduce line speed or pause production if the anomaly persists.', 'Notify shift supervisor and maintenance lead.'], 'investigate': ['Review current sensor trend against prior incidents and maintenance notes.', 'Inspect the affected machine and verify sensor signal integrity.'], 'prevent_recurrence': ['Add automated alerting for early threshold drift.', 'Update preventive maintenance checklist for the affected asset.']}

Shift Handoff Note

{'title': 'Shift Handoff: LINE-A Production Anomaly', 'summary': 'LINE-A reported HIGH_VIBRATION, OUTPUT_DROP, TEMPERATURE_SPIKE.', 'current_status': 'Keep line in controlled operation until maintenance checks are complete.', 'actions_completed': ['Scanner Agent detected and classified the anomaly.', 'Investigator Agent reviewed relevant operational context.'], 'open_actions': ['Inspect CNC-MILL-11.', 'Verify sensor signal integrity and recent maintenance records.']}

Maintenance Request

{'priority': 'HIGH', 'asset': 'CNC-MILL-11', 'line_id': 'LINE-A', 'request': 'Inspect, test, and restore the affected equipment to normal operating range.', 'reason': 'Thermal anomaly likely caused by lubrication or cooling degradation.'}

Corrective Action Plan

{'problem': 'temperature_c=305.493 breached > 90 for LINE-A / CNC-MILL-11.; temperature_c=286.221 breached > 90 for LINE-A / CNC-MILL-11.; output_units_per_hour=392 breached < 700 for LINE-B / PRESS-VALVE-23.; vibration_mm_s=7.254 breached > 4.0 for LINE-A / CNC-MILL-11.', 'containment': 'Reduce speed or pause operation until readings return to stable range.', 'root_cause_analysis': 'Thermal anomaly likely caused by lubrication or cooling degradation.', 'corrective_action': 'Repair or recalibrate affected equipment, then validate recovery with live readings.', 'preventive_action': 'Add early-warning alert and update preventive maintenance

checklist.}

Compliance References

- Follow line-specific SOP before returning to full-speed production.
 - Document investigation evidence under ISO 9001 controlled production requirements.
-