

LICENSED PLUMBER INSPECTION · JOB 5521

Property: 118 Cedar Hollow Rd, Unit 4

Findings: Claimant reports a sudden supply-line burst. However, fittings show long-term corrosion and the subfloor staining indicates a slow, pre-existing leak that predates the reported incident date by several weeks. Damage to the cabinets and subfloor is real and extensive, but the cause is gradual wear, not a sudden accidental discharge.

Inspector: License #PL-7782