

```
add x5, x1, x2
lw  x6, 0(x1)
sw  x6, 4(x1)
custom0_Inst
```

R-type instruction

