Initialize Machine Load Port F Data Isolate Switch Pins & Clear Them Move Switch Bits to same position Test if either is open (ORR) move resulting bit to Red LED port toggle the bit again 3 Move it to green LED port Insert new Values into Portf Data Store Port F Data into Port F

loop