

SITE INSPECTION NOTE

Inspection date: 3 September 2026

Inspector: Anita Rao

The north boundary wall has a crack of 2.5 metres.

Fire extinguishers in Block B expired in July 2026.

Recommended action: replace extinguishers within 7 days.