

FIELDNOTE · OFFICIAL INSPECTION DOSSIER

CATEGORY: ELECTRICAL INSPECTION | REPORT ID: rep-hero-001

HIGH PRIORITY / SAFETY HAZARD DETECTED

Critical thermal load and loose terminals pose immediate fire hazard

SITE / LOCATION:

Kukatpally Metro Site

PANEL / ASSET ID:

PANEL-204

INSPECTOR:

K. S. Rao (Field Eng #104)

GPS: 17.4947° N, 78.3996° E (Metro Pillar 742, Kukatpally, Hyderabad, Telangana)

Executive Field Summary

3 loose connections detected on Terminal Block B with severe thermal oxidation. Phase R feeder cable has chafed insulation exposing conductor. Immediate torquing and sleeve replacement mandated before morning shift.

లాజ్ కనెక్షన్లు గమనించబడ్డాయి (Loose connections verified on site)

Findings & Extracted Hazards (2)

[HIGH] Electrical Terminals

3 loose connections detected on Terminal Block B lugs with severe thermal discolouration.

[HIGH] Cable Integrity

1 damaged cable insulation sheath on incoming Phase R 16 mm² feeder conductor.

Mandatory Action Items (2)

• Tighten all 3 terminal lugs with calibrated torque wrench (18 Nm) before morning shift

Assignee: K. Rao (Electrical Team Lead) | Status: PENDING

• Replace damaged 16 mm² heat-resistant cable sleeve on Phase R

Assignee: S. Reddy (Field Technician) | Status: PENDING

Attached Photographic Evidence (2 tags)

- Photo Ref: Thermal discoloration and loose terminal lug on Phase B (17:13:10)

- Photo Ref: Phase R damaged insulation exposing copper core (17:14:05)

SHA-256 IMMUTABLE LEDGER SEAL: VALID

Hash: fe8eb3960b40f00477d4824fb5486135...

Timestamp: 2026-09-21T13:34:40.896Z

On-device Cryptographic Ledger Seal