

Laboratory Report

Pressure & Refrigeration

Submitted by:	Sakariye Abiikar	K2371673
	Alireza Alishahi	K2333243
	Naim Alrifai	K2459662
	Munachi J Atuegbu	K2463699
	Ehsan Haque	K2453799
	Abdul Mueed	K2454880
	Abdelrahman Shehata	K2426523
	Varley, Freddie	K2311322

Key Dates: Date of practical: Wednesday 19th March, 2025

Deadline: Tuesday 3rd April, 2025

Last Updated: Friday 21st March, 2025 15:50



Contribution Table

Student	Course	Contribution	Picture
Sakariye Abiikar	Mechanical Engineering		
Alireza Alishahi	Mechanical Engineering		
Naim Alrifai	Mechanical Engineering		
Munachi J Atuegbu	Mechanical Engineering		
Ehsan Haque	Mechanical Engineering		
Abdul Mueed	Mechanical Engineering		
Abdelrahman Shehata	Mechanical Engineering		
Varley, Freddie	Mechanical Engineering		1

Table of Contents

1	Abstract
2	Introduction
3	Method & Experimental Procedures 3.1 Operating Procedure
4	Theory
5	Data, Calculations and Results95.1 Pressure Calibrator Readings9
6	Discussion of Results
7	Conclusions
8	Recommendations
9	References
10	Appendix



1 Abstract

In this experiment, we calibrated and compared the performance of multiple pressure-measuring devices, including two Bourdon gauges, a Budenberg pressure gauge and a Hg glass manometer, in tandem with a reference pressure calibrator (DPI-603 Portable Pressure Calibrator), which served as the baseline for pressure measurements and as the source of the applied pressure. The devices were connected to the DPI-603 Portable Pressure Calibrator, enabling us to apply both positive and negative pressures in increments of approximately ±5 kPa. Through this process, we were able to get an exhaustive dataset that demonstrated notable differences in the pressure-measuring devices' performance. [Placeholder breif results findings]. These results highlighted the importance of selecting appropriate devices based on precision requirements and operating conditions, as well as the potential impact of human error in reading analog instruments like the Bourdon gauges and Hg manometer.



2 Introduction

In engineering and scientific applications, pressure measurement is essential, playing a critical role in fields such as fluid dynamics, meteorology, and industrial control. Over time, pressure-measuring instruments have evolved, from early liquid column manometers to modern mechanical and digital gauges, each designed to provide accurate measurements under varying conditions.

A key distinction in pressure measurement is between **absolute** and **gauge** pressure ¹. Absolute pressure is measured relative to a vacuum, while gauge pressure is measured relative to atmospheric pressure. This distinction influences the design and function of pressure-measuring devices.

Historically, the invention of the Bourdon gauge by Eugène Bourdon in 1849 marked a significant advancement in pressure measurement. It provided a robust and reliable means of monitoring pressure in industrial settings, where durability and consistency were paramount. On the other hand, liquid column manometers, particularly those using mercury, have been essential in laboratory settings due to their precision in measuring small pressure differences.

Despite the advantages of different pressure-measuring devices, each has limitations, such as calibration errors and environmental influences.

Previous studies have highlighted various challenges and findings related to pressure measurement devices. For example, a study by Hodgkinson et al. (2020) found that the accuracy of home blood pressure monitors varied significantly, with validated monitors showing a higher pass rate in static pressure tests compared to unvalidated ones. This emphasizes the importance of validation and calibration in ensuring the accuracy of pressure-measuring devices.

In this experiment, we aimed to evaluate the performance and accuracy of various pressure-measuring devices under controlled conditions, comparing their responses to varying pressure levels.

differential pressure i decided to redact in the context of our lab though it would be among this list



3 Method & Experimental Procedures

We are first given a table to record our findings as shown:²

#	Reference Value	Pressure Calibrator Bourdon Gauge 1			Bourdon Gauge 2		Bundenberg Pressure Gauge		Hg Glass Manometer (+) MAX 32 cm Hg						
		kPa	bar	bar P_{abs}	psi	bar	bar P_{abs}	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}	cm Hg	bar	bar P_{ab}
1															
3															
4															
5															
6															
7															
8															
9															
10															
#	Reference Value	Pressure Calibrator Bourdon Gauge 1			Bourdon Gauge 2			Bundenberg Pressure Gauge		Hg Glass Manometer (+) MAX 32 cm Hg					
														AA 32 CII	Hg
	Ref	kPa	bar	$bar\; P_{abs}$	psi	bar	bar P_{abs}	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}	cm Hg	bar	
1	Ref	kPa	bar	bar P_{abs}	psi	bar	bar P_{abs}	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}			
2	Ref	kPa	bar	bar P_{abs}	psi	bar	bar P_{abs}	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}			
2	Ref	kPa	bar	bar P_{abs}	psi	bar	bar P_{abs}	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}			
2 3 4	Ref	kPa	bar	bar P_{abs}	psi	bar	bar P_{abs}	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}			bar P_{ab}
2	Ref	kPa	bar	bar P_{abs}	psi	bar	bar P _{abs}	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}			
2 3 4 5	Ref	kPa	bar	bar P_{abs}	psi	bar	bar P _{abs}	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}			
2 3 4 5 6	Ref	kPa	bar	bar P_{abs}	psi	bar	bar Pabs	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}			
2 3 4 5 6 7	Ref	kPa	bar	bar P _{abs}	psi	bar	bar Pabs	kN/m²	bar	bar P_{abs}	bar	bar P_{abs}			

Figure 1: Form for recording pressure measurements

We are then told the ropes of what the lab is, the steps we outlined as follows:

² We started of in the lab by doing the refrigerator but this is redacted as its not a part of this lab report, following this we did the pressure lab experiment.



3.1 Operating Procedure

- 1. Visual check test rigs pneumatic connections.
- 2. Open the instruments vent valve.
- 3. Select between positive (+) or negative (-) as required. (This is the selector on the front of the DPI-603 (±VE on Figure 2), located between the hand pump and the volume adjuster.)

We started with the positive pressure (Excess).

- 4. Switch on the unit, pressing the power.
- 5. Select Pressure Units, i.e., in Hg or bar, etc, by cycling through clicking the button shown in Figure 2, we went with kPa.
- 6. Close Vent valve and zero instrument using Vent Valve.

It was determined that due to the sensitivity of the vent valves, the instructure must perform this.




Figure 2: DPI-603 Portable Pressure Calibrator

- 7. Using the hand pump pressurize the system to the required value ($\approx \pm 5$ kPa).³ Vent air using the vent valve and adjust pressure by pumping air using the hand pump. Use the volume control to fine-tune the pressure.
- 7. Once the required Obtain data from all relevant pressure gauges.
- 9. Reverse procedure for Vacuum.

³ Caution is required when using the mercury (Hg) glass manometer. The maximum pressure should not exceed 32 cm Hg to prevent damage to the glass. In this experiment, pressure increments of 5 kPa were recorded, totaling 50 kPa, which remains safely within both the 32 cm Hg limit and the 75 kPa threshold. Therefore, the calibration was performed without exceeding the safe pressure limits.



4 Theory



5 Data, Calculations and Results

Thus, as explained in the Method & Experimental Procedures Section 3, we have gathered a simple dataset for the corresponding pressure gauges. Our goal now is to make calculations, illustrate trends, etc., and simply produce another dataset from which we can draw fair conclusions from. Here, I first describe the baseline data that was collected and recorded on the table that was made available for use in the lab (Figure ??).

5.1 Pressure Calibrator Readings

ki		
+	-	+
0.0	0.0	1.0
5.7	-5.6	2.0
10.4	-12.1	2.6
16.0	-18.0	3.4
21.1	-21.8	4.1
27.7	-25.4	5.0
34.2	-29.3	6.0
40.0	-33.6	6.8
46.1	-37.6	7.6
52.2	-41.7	8.5

Table 1	Pressure	Cal-
ibrator	11000010	Cui

psi					
+	-				
1.0	1.2				
2.0	0.4				
2.6	-0.5				
3.4	-2.0				
4.1	-2.8				
5.0	-4.0				
6.0	-6.0				
6.8	-7.1				
7.6	-8.3				
8.5	-9.5				

Table 2: Bourdon Gauge 1

kN/m^2					
+	-				
1.0	2.5				
8.0	-1.0				
14.0	-9.0				
20.0	-15.0				
25.0	-20.0				
30.0	-23.0				
39.0	-27.0				
45.0	-32.0				
50.0	-36.0				
57.0	-40.0				

Table 3: Bourdon Gauge 2

Dai					
-					
-0.05					
-0.10					
-0.16					
-0.24					
-0.27					
-0.30					
-0.35					
-0.40					
-0.44					
-0.49					

har

Table 4: Budenberg Pressure Gauge

cm	cm Hg				
+	-				
0.4	0.4				
3.5	-0.7				
5.3	-3.7				
7.4	-5.4				
9.4	-6.8				
11.6	-8.2				
14.2	-9.6				
16.4	-11.3				
18.7	-12.8				
21.0	-14.4				

Table 5: Hg Glass Manometer



6 Discussion of Results



7 Conclusions



8 Recommendations



9 References

1. Hodgkinson, J.A. et al. (2020). Accuracy of blood-pressure monitors owned by patients with hypertension (ACCU-RATE study): a cross-sectional, observational study in central England. British Journal of General Practice, [online] 70(697), pp.e548—e554. Available at: https://bjgp.org/content/70/697/e548.



10 Appendix