

1 Unstable window
2 Decomposition
3 Stiffer SAW
4 Indicator
unstable
DFT
0
−0.06
ΔGdemix (eV/atom)
Fe–36Cr
0
0.5
1
xCr
Fe
Cr
random
α + α′
random
decomposed
0.50
0.45
fSAW (GHz)
+5.7%
C′ ↑
shear stiffening of Cr-rich α′
fSAW ↑
non-destructive signal
K/G ↓
embrittlement (Pugh)