

FS 0CPP 0001 - DSP Principal 4.2.3

Release note

Version 1.0.1

February 10, 2012

Warning

The information contained in this document is the property of Kinova. Except as specifically authorized in writing by Kinova, the holder of this document shall keep the information contained here confidential and shall protect same in whole or in part from disclosure and dissemination to third parties and use same for evaluation, operation and maintenance purposes only. This document is not an engagement of Kinova to develop, implement or design the product or techniques described here.

Revisions & Approval

Version	Primary Author(s)	Description of Version	Date Completed
1.0.1	S. Latour	First version	2012-02-10

Requirements Specification Approval History

Approving Party	Version Approved	Signature	Date

Contents

REVISIONS & APPROVAL 2

CONTENTS 3

1 INTRODUCTION 4

1.1 PURPOSE 4

2 BUG CORRECTION 5

2.1 BUG # 81 5
2.2 BUG # 82 5

1 Introduction

1.1 Purpose

This document is used as a release note on JACO's DSP principal Version 4.2.3 0001

2 Bug Correction

2.1 Bug # 81 Corrected

- The arm would sometime freeze on start up when immediately put in angular mode, or when the arm would be in a singularity position due to a bad initialization.

2.2 Bug # 82 Corrected

- In some extremely rare case where the Jaco was put in a certain (very unusual) position, the arm would move a little by itself.