

F10 — Envelope permeability sensitivity: the result depends strongly on a quantity Australian practice does not routinely measure

Both measured points are the same engine, the same building and the same weather, one correction apart: $q_{50} = 4.0$ is the +Infiltration envelope area state, $q_{50} = 14.0$ is +AU q_{50} recalibration. Apt 305 was completed in 2006 but built to pre-2006 practice, so the case adopts the 1991–2005 band. A blower-door measurement would override the table outright — none exists for this building.

