



(a) Beginning phase (0-1.5 s) — tool near clamped edge



(b) Middle phase (~ 10.2 s) — tool at center



(c) End phase (18.9-20.4 s) — tool near free edge

