



Make vs. Buy Cost Estimate

2026/10/06

CES-009

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/1/2022 3:18:02PM

Make vs Buy Code

MB795

Detailed Description

NOVA ROAD SIDE LED MIRROR ASSEMBLY

List Of Vehicles

NOVA LF 40FT (3330-3369) LB75	NOVA LF 40FT HYBRID (3400) LB62	NOVA LF 40FT HYBRID (3401-3454) L
NOVA LF 40FT HYBRID (3455-3569) L	NOVA LF 40FT HYBRID (3570-3654) L	NOVA LF 40FT (3100-3179) LB45
NOVA LF 40FT (3180-3329) LB28		

MMS Buy Code

074012

S.O.P. Number

Keyword

MIRROR

Job Number 92114

LABOUR TASK SUMMARY

<u>Task</u>	<u>CC</u>	<u>Labour Definition</u>	<u>Freq. Of Use</u>	<u>Time</u>	<u>Wrench Time</u>
OVERHAUL	05H1	UNIT BUILDER	100 %	1:30	1:15
			TOTAL	1:30	1:15

LABOUR HOURS SUMMARY

<u>Cost Centre</u>	<u>Total Hours</u>
05H1	1:30
Total Labour Hours	1:30

MATERIAL COST SUMMARY

<u>Cost Centre</u>	<u>Total Cost</u>
05H1	\$296.71
Total Material Cost (Excl Tax)	\$296.71

Labour Total (Incl. Non Productive Adj.):	\$65.54
Labour Overhead	\$47.84
Total Material Cost (Excluding tax)	\$296.71
Core Cost (Excluding tax)	\$0.00

Total Cost (Excluding tax): **\$410.09**

Total Tax: \$0.00

Total Cost with Tax: **\$410.09**

Remanufactured Cost (Excluding tax): \$0.00

Buy New Cost (Excluding tax): \$830.05



Make vs. Buy Cost Estimate

2026/10/06

CES-010

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/1/2022 3:18:02PM

Make vs. Buy Code

MB795

Detailed Description

NOVA ROAD SIDE LED MIRROR ASSEMBLY

MMS Buy Code 074012

S.O.P. Number

Keyword MIRROR

Job Number 92114

Rebuilt Parts Material List

<u>STOCK CODE</u>	<u>DESCRIPTION</u>	<u>UNIT COST</u>	<u>QTY</u>	<u>USAGE (%)</u>	<u>TOTAL</u>
-------------------	--------------------	------------------	------------	------------------	--------------

TOTAL REBUILT PART MATERIALS COST

Stock Coded Material List

<u>STOCK CODE</u>	<u>KEYWORD/ DESCRIPTION</u>	<u>UNIT COST</u>	<u>CC</u>	<u>QTY</u>	<u>USAGE (%)</u>	<u>CORE COST</u>	<u>TOTAL</u>
064755	GLASS ROR HEAD ASM)	\$36.65	05H1	1	90.00 %	\$0.00	\$32.99
051185	ACTUATOR RROR	\$68.37	05H1	1	20.00 %	\$0.00	\$13.67
070432	HOUSING IDE & CURBSIDE RV MIRRORLOCATION: MIRRORBUS: SR2304; SR2382	\$56.26	05H1	1	10.00 %	\$0.00	\$5.63
051179	CLAMP TYPE: OPEN SIDE MIRROR EXTERIOR CLAMPOTHER: USED ON ORION 7 HYBRID NG BUSSIZE: 1/2"LOCATION: AT EXTERIOR HEATED SPLIT MIRROR	\$12.22	05H1	4	10.00 %	\$0.00	\$4.89
074169	CARRIER TYPE: FLAT MIRROR GLASS CARRIERAREA: CLOSED SIDE MIRROR CARRIER	\$28.31	05H1	1	10.00 %	\$0.00	\$2.83
071256	COWLING V LED AMBER MARKET LAMP INSTALLEDRELATED TTC CODE: 051187 - COWLING WITHOUT LED MARKER/SIGNAL LAMP	\$99.59	05H1	1	60.00 %	\$0.00	\$59.75
074126	BRACKET TYPE: REAR VIEW MIRROR ARM BRACKETLOCATION: ROAD SIDE (LH)RELATED TTC CODE; SC (IR-013988) MOUNTING KIT	\$369.36	05H1	1	40.00 %	\$0.00	\$147.74
074168	MIRROR TYPE: FLAT MIRROR GLASSLOCATION: CLOSED SIDE MIRROR GLASS****CODE CLOSED USE 064479 DUPLICATE***	\$29.49	05H1	1	90.00 %	\$0.00	\$26.54

TOTAL STOCK CODED MATERIAL COS **\$294.04**



Make vs. Buy Cost Estimate

2026/10/06

CES-010

Make vs. Buy Code

MB795

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/1/2022 3:18:02PM

Detailed Description

NOVA ROAD SIDE LED MIRROR ASSEMBLY

MMS Buy Code 074012

S.O.P. Number

Keyword MIRROR

Job Number 92114

Non Stock Coded Material List

<u>SUPPLIER NUMBER/ SUPPLIER NAME</u>	<u>KEYWORD/ DESCRIPTION</u>	<u>UNIT COST</u>	<u>CC</u>	<u>QTY</u>	<u>USAGE (%)</u>	<u>CORE COST</u>	<u>TOTAL</u>
23.L15.LC LUCERIX	CARRIER LOWER GLASS CARRIER	\$26.65	05H1	1	10.00 %	\$0.00	\$2.67
TOTAL NON STOCK CODED MATERIAL COS							\$2.67

Total Rebuilt Material Cost	\$0.00
Total Stock Coded Material Cost	\$294.04
Total Non Stock Material Cost	\$2.67
Total Material Cost	\$296.71
Total Core Cost	\$0.00
Total Material Cost	\$296.71



Make vs. Buy Cost Estimate

2026/10/06

CES-010

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/1/2022 3:18:02PM

Make vs. Buy Code

MB795

Detailed Description

NOVA ROAD SIDE LED MIRROR ASSEMBLY

MMS Buy Code 074012

S.O.P. Number

Keyword MIRROR

Job Number 92114

Rebuilt Parts Material List

<u>STOCK CODE</u>	<u>DESCRIPTION</u>	<u>UNIT COST</u>	<u>QTY</u>	<u>USAGE (%)</u>	<u>TOTAL</u>
-------------------	--------------------	------------------	------------	------------------	--------------

TOTAL REBUILT PART MATERIALS COST

Stock Coded Material List

<u>STOCK CODE</u>	<u>KEYWORD/ DESCRIPTION</u>	<u>UNIT COST</u>	<u>CC</u>	<u>QTY</u>	<u>USAGE (%)</u>	<u>CORE COST</u>	<u>TOTAL</u>
064755	GLASS	\$36.65	05H1	1	90.00 %	\$0.00	\$32.99
	ROR HEAD ASM)						
051185	ACTUATOR	\$68.37	05H1	1	20.00 %	\$0.00	\$13.67
	RROR						
070432	HOUSING	\$56.26	05H1	1	10.00 %	\$0.00	\$5.63
	IDE & CURBSIDE RV						
	MIRRORLOCATION: MIRRORSBUS:						
	SR2304; SR2382						
051179	CLAMP	\$12.22	05H1	4	10.00 %	\$0.00	\$4.89
	TYPE: OPEN SIDE MIRROR EXTERIOR						
	CLAMPOTHER: USED ON ORION 7						
	HYBRID NG BUSSIZE:						
	1/2"LOCATION: AT EXTERIOR						
	HEATED SPLIT MIRROR						
074169	CARRIER	\$28.31	05H1	1	10.00 %	\$0.00	\$2.83
	TYPE: FLAT MIRROR GLASS						
	CARRIERAREA: CLOSED SIDE MIRROR						
	CARRIER						
071256	COWLING	\$99.59	05H1	1	60.00 %	\$0.00	\$59.75
	V LED AMBER MARKET LAMP						
	INSTALLEDRELATED TTC CODE:						
	051187 - COWLING WITHOUT LED						
	MARKER/SIGNAL LAMP						
074126	BRACKET	\$369.36	05H1	1	40.00 %	\$0.00	\$147.74
	TYPE: REAR VIEW MIRROR ARM						
	BRACKETLOCATION: ROAD SIDE						
	(LH)RELATED TTC CODE; SC						
	(IR-013988) MOUNTING KIT						
074168	MIRROR	\$29.49	05H1	1	90.00 %	\$0.00	\$26.54
	TYPE: FLAT MIRROR						
	GLASSLOCATION: CLOSED SIDE						
	MIRROR GLASS****CODE CLOSED USE						
	064479 DUPLICATE***						
TOTAL STOCK CODED MATERIAL COS							\$294.04



Make vs. Buy Cost Estimate

2026/10/06

CES-010

Make vs. Buy Code

MB795

LAST MODIFIED BY: BMOONEY

LAST MODIFIED ON: 6/1/2022 3:18:02PM

Detailed Description

NOVA ROAD SIDE LED MIRROR ASSEMBLY

MMS Buy Code 074012

S.O.P. Number

Keyword MIRROR

Job Number 92114

Non Stock Coded Material List

<u>SUPPLIER NUMBER/</u> <u>SUPPLIER NAME</u>	<u>KEYWORD/</u> <u>DESCRIPTION</u>	<u>UNIT COST</u>	<u>CC</u>	<u>QTY</u>	<u>USAGE (%)</u>	<u>CORE COST</u>	<u>TOTAL</u>
23.L15.LC LUCERIX	CARRIER LOWER GLASS CARRIER	\$26.65	05H1	1	10.00 %	\$0.00	\$2.67
TOTAL NON STOCK CODED MATERIAL COS							\$2.67

Total Rebuilt Material Cost	\$0.00
Total Stock Coded Material Cost	\$294.04
Total Non Stock Material Cost	\$2.67
Total Material Cost	\$296.71
Total Core Cost	\$0.00
Total Material Cost	\$296.71

