


LT1999

Op amp + resistor for voltage measurement

Or resistors with capacitors for voltage measurement

High impedance resistor divider

Look at voltage sensing of 469 board



Schematic notes:

Fix LDOs

Bypass op amp in case it doesn't work

Bootstrap + gatedriver circuit

Keep 469 pcb for nwo

Current MEasurement

Voltage Sensing

Light Sensor

MCU

Output Connectors

Inputs into the mcu:

voltage_sense1

voltage_sense2

voltage_sense3

Current_sense

light_sense1

light_sense2

Spray

Brush

Motor controller (x3) (for motion)

Usb

Antenna

Manual commands (right left up down) (4 of them)

Outputs from mcu

PWM

Bluetooth pin