

In-PAD vias have a manufacturing cost :



-> Add a custom rule to detect them with DRC :



```
(rule via_in_pad
    (constraint physical_hole_clearance (min 0.1mm))
    (condition "B.Pad_Type == 'SMD'")
)
```

