Name: Saud Saad Allahyani

Task: 1 (stepper motor)

Introduction:

Stepper motors, due to their unique design, can be controlled to a high degree of accuracy without any feedback mechanisms. The shaft of a stepper, mounted with a series of magnets, is controlled by a series of electromagnetic coils that are charged positively and negatively in a specific sequence, precisely moving it forward or backward in small "steps".

There are two types of steppers, Unipolars and Bipolars, and it is very important to know which type you are working with. For each of the motors, there is a different circuit. The example code will control both kinds of motors. See the <u>unipolar</u> and <u>bipolar</u> motor schematics for information on how to wire up your motor.

The stepper is controlled by with digital pins 8, 9, 10, and 11 for either unipolar or bipolar motors. The Arduino board will connect to a <u>U2004</u> <u>Darlington Array</u> if you're using a unipolar stepper or a <u>SN754410NE H-Bridge</u> if you have a bipolar motor.

The circuit diagram:




Figure: 1 (I used this circuit Design with Tinkercad)

The components:

- 1- Board
- 2- Arduino uno
- 3- Potentiometer
- 4- Stepper
- 5- Wires

The code used:

MotorKnob

A stepper motor follows the turns of a potentiometer (or other sensor) on analog input 0.

```
#include <Stepper.h>
// change this to the number of steps on your motor
#define STEPS 100
// create an instance of the stepper class, specifying
// the number of steps of the motor and the pins it's
// attached to
Stepper stepper(STEPS, 8, 9, 10, 11);
// the previous reading from the analog input
int previous = 0;
void setup() {
 // set the speed of the motor to 30 RPMs
 stepper.setSpeed(30);
}
void loop() {
 // get the sensor value
 int val = analogRead(0);
 // move a number of steps equal to the change in the
 // sensor reading
 stepper.step(val - previous);
 // remember the previous value of the sensor
 previous = val;
}
```

StepperOneRevolution

The motor should revolve one revolution in one direction, then one revolution in the other direction.

```
#include <Stepper.hconst int stepsPerRevolution = 200; // change this to
fit the number of steps per revolution// for your motor// initialize the
stepper library on pinsthrough11:SteppermyStepper(stepsPerRevolution,
8, 9, 10, 11); void setup() {// set the speed at 60
rpm:myStepper.setSpeed(60);// initialize the serial
port:Serial.begin(9600);
}
void loop() {
 // step one revolution in one direction:
 Serial.println("clockwise");
 myStepper.step(stepsPerRevolution);
 delay(500);
 // step one revolution in the other direction:
 Serial.println("counterclockwise");
 myStepper.step(-stepsPerRevolution);
 delay(500);
}
```