PERFECT WIRELESS EXPERIENCE

Linux_LogCapture Release Notes

V1.1

Disclaimer

Any action you take in the course of using this document is at your own risk, and Fibocom shall not be liable for any damages or losses under any circumstances. Due to product version upgrade or other reasons, Fibocom reserves the right to modify any information in this document at any time without prior notice and any responsibility. Unless otherwise agreed, all statements, information and suggestions in this document do not constitute any express or implied guarantee.

This document may include the third-party information covering products, services, software, data, and so on. Fibocom does not control and assumes no responsibility for the third-party content, including but not limited to the accuracy, compatibility, reliability, availability, legitimacy, appropriateness, performance, non-infringement, and status update, unless otherwise specified in this document. Fibocom does not provide any guarantee or authorization for the third-party content mentioned or referenced in this document. If you need a third-party license, obtain it in an authorized or legal way, unless otherwise specified in this document.

Copyright Notice

Copyright © 2025 Fibocom Wireless Inc. All rights reserved.

Unless specially authorized by Fibocom, the recipient of the documents shall keep the documents and information received confidential, and shall not use them for any purpose other than the implementation and development of this project. Without the written permission of Fibocom, no unit or individual shall extract or copy part or all of the contents of this document without authorization, or transmit them in any form. Fibocom has the right to investigate legal liabilities for any offense and tort in connection with violation of confidentiality obligations, or unauthorized use or malicious use of the said documents and information in other illegal forms.

Trademark Statement

Fibocom The trademark is registered and owned by Fibocom Wireless Inc.

Other trademarks, product names, service names and company names appearing in this document are owned by their respective owners.

Contact Information

Website: https://www.fibocom.com

Address: 10/F-14/F, Block A, Building 6, Shenzhen International Innovation Valley, Dashi First Road, Xili Community, Xili Subdistrict, Nanshan District, Shenzhen

Tel: 0755-26733555

Contents

Applicable Model 4
Change History 5
1 Overview 6
1.1 Purpose 6
2 Release Notes 7
2.1 Fibocom_Linux_LogCapture_V1.5.0.0 7
2.2 Fibocom_Linux_LogCapture_V1.4.0.6 7
2.3 Fibocom_Linux_LogCapture_V1.4.0.5 8
2.4 Fibocom_Linux_LogCapture_V1.4.0.0 9
2.5 Fibocom_Linux_LogCapture_V1.3.0.0 10
2.6 Fibocom_Linux_LogCapture_V1.2.2.0 10
2.7 Fibocom_Linux_LogCapture_V1.2.0.0 11
2.8 Fibocom_Linux_LogCapture_V1.1.0.0 12

Copyright © Fibocom Wireless Inc.

Applicable Model

No.	Applicable Model	Description
1	L716/L718	ZTE V3E/T
2	L61x/LC61x/MC61x/LG61x	UNISOC 8910
3	MC66x/MG66x	UNISOC 8850
4	FG650/FG652/FM650	UNISOC UDX710
5	FG621	UNISOC SL8563
6	NL668/MC116/LC116	QCOM MDM9X07
7	MA510/MC109/MC100E	QCOM MDM9X05
8	FM101/FG101	QCOM X12
9	FM150/FG150	QCOM X55
10	FM160/FG160	QCOM X62
11	LE170/LE270	EC618/EC718
12	FM190/FG190	QCOM X75
13	FG131/FG132	QCOM X35
14	FG170/FM170	QCOM X65
15	FG180/FM180	QCOM X75
16	FM550	SAMSUNG S5300

Copyright © Fibocom Wireless Inc.

Change History

V1.1 (2025-02-26)	Compatible with Samsung platform.
V1.0 (2024-09-27)	Initial version.

Copyright © Fibocom Wireless Inc.

1 Overview

1.1 Purpose

This document records detailed change history and description of each version of the LogCapture tool.

Copyright © Fibocom Wireless Inc.

2 Release Notes

2.1 Fibocom_Linux_LogCapture_V1.5.0.0

Name	Fibocom_Linux_LogCapture_V1.5.0.0
Version	V1.5.0.0
Release Date	2025-02-26
Applicable Project	FG101, FG150, FG160, FG621, FG650, FG652, FM101, FM150, FM160, FM650, FM550
Software Baseline Version	N/A
Modification	Resolved the following issues: • Compatible with Samsung platform. • MBB0678-979 [Stability] In the Linux environment, after the upgrade and restart, the Fibocom_Linux_LogCapture_V1.5.0.0 tool cannot correctly identify the port and cannot catch valid information. • Resolved the problem that logs on the Samsung platform cp side contain tcpdump logs.
Function Description	Normalized Linux log tool
Script Configuration Description	N/A

2.2 Fibocom_Linux_LogCapture_V1.4.0.6

Name	Fibocom_Linux_LogCapture_V1.4.0.6
Version	V1.4.0.6
Release Date	2024-12-13
Applicable Project	FG101, FG150, FG160, FG621, FG650, FG652, FM101, FM150, FM160, FM650
Software Baseline Version	N/A
Modification	Resolved the following issues: • MBB0120-687 [Function] [Fibocom_Linux_LogCapture_V1.4.0.5] [Linux] Use Log tool ./logtool -a 0 -s path -m 1024 -n 3 to capture packets, the subpackage is not subcontracted according to the set 1024M, or the default 500M subpacking. • In the PCIE environment, the function of capturing AP and CP logs at the same time is optimized.

Copyright © Fibocom Wireless Inc.

Function Description	Normalized Linux log tool
Script Configuration Description	N/A

2.3 Fibocom_Linux_LogCapture_V1.4.0.5

Name	Fibocom_Linux_LogCapture_V1.4.0.5
Version	V1.4.0.5
Release Date	2024-09-27
Applicable Project	FG101, FG150, FG160, FG621, FG650, FG652, FM101, FM150, FM160, FM650
Software Baseline Version	N/A
Modification	Resolved the following issues: • MBB0291-475: The PC is connected to both UNISOC and Qualcomm modules. After a dump is triggered, ./logtool -t 3 fails to capture the dump log. • MBB0126-247: The whole module fails to capture the dump log locally. • MBB0047-586 [Fibocom_Linux_LogCapture_Guide_V1.9]: The English document has some format issues: Tables and figures do not have titles and the table title is below the table, which are inconsistent with the Chinese document. • MBB0120-503: Packets are lost when the logtool is used to capture CP logs. • MBB0120-493: In whole machine mode, packets are lost when capturing logs using a proxy. • MBB0120-492: The tool reports errors (core dumped) when capturing AP logs over TFTP. • MBB0201-84: When parameters -a 0 and -s -m -n are both configured, the capture command is successfully issued but log capture and log generation encounter exceptions: The -s -m -n parameters do not take effect (no relevant logs are generated). • MBB0297-370: The Sahara protocol failure is reported when capturing dump logs on Android 7.x and 8.x systems. • MBB0656-207: VID/PID 2cb7:0116 is added to ports 45 and 46 but the logtool and option driver are not adapted to the new port and the tool cannot be used. You need to adapt the logtool and option driver. Added the following features: • UDX710 and SL8563 platforms: Supports local capturing and TFTP capturing of AP dump files. • Added the VID and PID port configuration file. • Removed the FTP function for the UNISOC platform and added AP/CP log

	capturing over TFTP.
Function Description	Normalized Linux log tool
Script Configuration Description	N/A

2.4 Fibocom_Linux_LogCapture_V1.4.0.0

Name	Fibocom_Linux_LogCapture_V1.4.0.0
Version	V1.4.0.0
Release Date	2024-05-11
Applicable Project	FG101, FG150, FG160, FG621, FG650, FG652, FM101, FM150, FM160, FM650, L610, L716, L718, LC116, LC610N, LE170, LE270, LG610, MA510, MC100E, MC109, MC116, MC610, MC660, MC661, MC665, MC667, MC669, MG661, MG662, NL668, NL668T
Software Baseline Version	N/A
Modification	Resolved the following issues: • MBB0282-621: The tool fails to obtain the dump log. • MBB0297-368: An exception occurs when capturing logs over FTP. • MBB0297-370/MBB0297-369/MBB0280-535: Failed to obtain dump logs in some Android and Linux systems. • MBB0055-783: Dump logs cannot be obtained for some customer whole machines. • MTC0601-172: An exception occurs when the logtool specifies ports on some platforms. • Packets are lost when the logtool captures logs from some customers' whole machine. Added the following features: • Supports using the -t option to configure the tool to preferentially search and match a platform. • Added the function to obtain AP dump files from UDX710/SL8563 platform modules.
Function Description	Normalized Linux log tool
Script Configuration Description	N/A

2.5 Fibocom_Linux_LogCapture_V1.3.0.0

Name	Fibocom_Linux_LogCapture_V1.3.0.0
Version	V1.3.0.0
Release Date	2023-11-25
Applicable Project	FG101, FG150, FG160, FG621, FG650, FG652, FM101, FM150, FM160, FM650, L610, L716, L718, LC116, LC610N, LE170, LE270, LG610, MA510, MC100E, MC109, MC116, MC610, MC660, MC661, MC665, MC667, MC669, MG661, MG662, NL668, NL668T
Software Baseline Version	N/A
Modification	Added the following features: • Added the function to obtain logs from LE170/LE270/FG621 modules. • Added the dump log capture and FTP log upload functions for Qualcomm platform (MDM9X07/MDM9205 are not adapted). • Added the FTP log upload function for Qualcomm platform (MDM9X07/MDM9205 are not adapted). • Added the function to obtain logs using proxy (ZTE V3E/T are not adapted). Resolved the following issues: • MBB0063-692: The FM650 log storage directory supports only relative paths. • MBB0063-677/MBB0011-2283/MBB0076-238/MBB0080-494: In some usbmode, the log tool prompts that the module cannot be found. • BB0063-676/MBB0076-239/MBB0080-496/MBB0046-333: Tool compilation for some kernel versions of Linux systems keep reporting errors and cannot be compiled.
Function Description	Normalized Linux log tool
Script Configuration Description	N/A

2.6 Fibocom_Linux_LogCapture_V1.2.2.0

Name	1.1 Fibocom_Linux_LogCapture_V1.2.2.0
Version	V1.2.2.0
Release Date	2023-06-12
Applicable Project	FG101, FG160, FG650, FM101, FM160, L610, L716, L718, MA510, MC116, MC660, NL668
Software Baseline Version	N/A

Modification	Resolved the following issues: • MBB0126-41: Failed to capture OTA logs over the PCIe interface. • MBB0063-594: When capturing UDX710 platform logs, the prompt "warning, fifo buf is full now" may occasionally appear, indicating that the cache is full. • MBB0074-986/MBB0080-401: ./logtool -m 1024 -n 10 is executed to capture logs. When the packet size is greater than 512 MB, the log will be split according to the default packet size. • MBB0063-571: Enter the tool directory to capture logs (./logtool -m 100M -n 10). When the log splitting mechanism takes effect, the AP log will be deleted. • MBB0063-565: The CP logs captured using the tool is incomplete. Some logs are lost. • MBB0063-566: After using the tool to capture logs for a period of time, the memory occupied by the logtool process is about 33 MB, which does not meet expectations. • IRP-20230300315: The logtool cannot run in the background when obtaining logs from UNISOC 8910 platform modules. • MTC0181-150/MTC0230-422/MTC0623-649/MTC0039-746/MBB0080-407/MBB0080-409/MBB0074-987: Logs cannot be obtained for certain VID/PID. Added the following features • Supports independent or mixed compilation of the logtool for each platform. • Supports FTP log capture on UX710 platform.
Function Description	Normalized Linux log tool
Script Configuration Description	N/A

2.7 Fibocom_Linux_LogCapture_V1.2.0.0

Name	Fibocom_Linux_LogCapture_V1.2.0.0
Version	V1.2.0.0
Release Date	2023-01-18
Applicable Project	FG101, FG160, FG650, FM101, FM160, L610, L716, L718, MA510, MC116, MC660, NL668
Software Baseline Version	N/A
Modification	Resolved the following issues: • MBB0153-4: Tool compilation error in Ubuntu 20.4. • MBB0063-521: Added the following descriptions to the tool user guide document: The UNISOC UDX710 platform does not use the -p parameter,

	and the Diag and Log ports will disappear after the tool is run. • MBB0063-522: Added the following description to the tool user guide document: To use the logtool to capture logs from the UNISOC UDX710 platform, you need to specify the log port. • MBB0080-325: The tool fails to capture logs if the GTUSBMODE is 24 (VID/PID is 2cb7:010b). • The tool occasionally reports errors during log capturing of the whole UDX710 module. Added the following features and optimizations: • MBB0080-326: Added descriptions of parameters -f and -h to the tool user guide document. • IRP-20230100088: Some customized software versions can automatically identify V3E/V3T and use the correct log rule file. • IRP-20230100089: The 8850 platform has been modified. It does not split packets by default. • Added the function to obtain AP logs for the UDX710 platform. • Optimized the log acquisition performance of the Zxic platform and reduced log loss caused by poor host computer performance and untimely scheduling of file writing threads.
Function Description	Normalized Linux log tool
Script Configuration Description	N/A

2.8 Fibocom_Linux_LogCapture_V1.1.0.0

Name	Fibocom_Linux_LogCapture_V1.1.0.0
Version	V1.0.0.0
Release Date	2022-12-07
Applicable Project	FG650, L610, L716, L718, MA510, MC116, MC660, NL668
Software Baseline Version	N/A
Modification	Main functions in the initial version of the normalized Linux log tool: • The log tool is normalized to adapt to the modules of different platforms. Supported platforms include Qualcomm MDM9x07, Qualcomm MDM9205, Zxic V3E, Zxic V3T, UNISOC 8850, UNISOC 8910, and UNISOC UDX710. • Supports specifying the log size, quantity, and storage path by using parameters and supports loop coverage. Note: • The UNISOC UDX710 platform currently obtains only CP logs (AP logs are

	saved inside the module and do not need to be obtained). • Changing the log file names for the Zxic and UNISOC platforms will cause parsing errors. You are advised to retain the default file names. • The file loop coverage function is temporarily not supported on UNISOC 8850 and 8910. The reason is that these two platforms currently use UNISOC xlog to obtain logs and xlog independently manages files. This function is planned in next version.
Function Description	Normalized Linux log tool
Script Configuration Description	N/A