Distrust memo: what not to trust in the TyreSense pack

6 Nov 2026 · Scope: 12 briefs, 6 trucks, 1 Jun to 15 Jul 2026

Bottom line. The pack is written summaries, not the 28,000 to 69,000-row exports behind them. I could not recompute findings from raw data, so treat every number as the brief's claim and every cause as a hypothesis.

Do not trust

1. **Currency.** The data ends 15 Jul; today is 6 Nov, about 16 weeks later. "Replace 2RO now", "4LI near 20% in five weeks" and the open 5RO leak have probably been resolved or have already failed. Nothing here shows today's state.
2. **Sampling interval.** Several briefs say readings arrive "about every 2 minutes". One brief corrects this to about 18 seconds moving and 2 minutes parked, and the counts agree (about 2,200 readings on working days against 720 on parked Sundays). So every "% of readings above X°C" is weighted toward driving time, not elapsed time.
3. **Causes.** "Deliberate bleed-down", "top-up", "repair and sensor swap", "slow leak", "brakes dragging" and "operating cause" are inferred from curves. No leak test, maintenance log, trip or load record supports them.
4. **Thresholds.** There is no specified PSI or temperature limit. The 85 PSI cut-off, the 70°C concern and the 5 PSI dual gap are rules of thumb, applied to trucks running about 100, 112 and 125 PSI. "Low" and "hot" are relative.
5. **Identity and labels.** "KA25B4471" versus KA25AB4471. The KA25AE2016 June brief calls itself different from KA25AC1182 and cites a 5RI event "on the other vehicle" that happened in July. KA48AF9054 is called "a third vehicle" in a pack of six. On KA25AB4471 the 3LO and 3RO batteries changed together on 28 Jun, so tyre-level history may be swapped.
6. **Duplication.** July files repeat 12 hours of June (30 Jun 18:00 to 1 Jul 06:00). Summing or trending across the join double-counts events and battery drain.
7. **Missing.** No raw data, alert settings, loads, routes, workshop log, or tyre age and make. GPS gaps of 13 to 19% on two trucks are unexplained. Some text is corrupted ("~99–102The lowest", a stray "2").
8. **Overreach.** KA48AF9054's "no confirmed leaks" sits beside a 5 to 7 PSI cold-pressure decline. The fleet-wide 10 PSI drop on KA22AD7730 (5 to 8 Jun) is unexplained.

What I did

- Kept each truck and each window separate; I never merged June with July or averaged across the overlap.
- Used only figures the briefs state. I recomputed nothing from raw data, apart from checking cadence from reading counts and drain rates for 2RO and 3LO against their start and end values (they agree).
- Treated “KA25B4471” as KA25AB4471 and flagged it.
- Put the missing specification first among the five questions, and kept “low” relative.
- **Where I fell short:** my deck and findings page present actions as current without the staleness caveat, repeat the 2-minute interval without checking it, and state the heat as an operating cause more firmly than the evidence allows. Correct these before sharing.