

- Connect 3.3V to programming header

- Use some surface mount displays

- Move to Micro-USB or USB-C power

- Maybe try the continuous version with the modifications to the EN line?