



Service Bulletin: Robot disconnected with wifi after upgrading

Product: 105C

Issue: After upgrading to version 9.4.8, the robot will be disconnected with WI-FI

1. Affected Modes of Operation

- All 105C device that have upgraded to Version 9.4.8

2. Customer Reported Symptoms

Customers may report one or more of the following:

- After updating the firmware, the robot will be disconnected with the APP, and try connect again, it will be failed.
- Robot is disconnected and cannot Connect WIFI again.

3. Initial Troubleshooting

This is because of an abnormal signal transmission in the network module, please try these following steps:

1. Please Reboot the Robot.
2. Please Reset via enter in Roomba Robot plugin page-Robot Settings-About Roomba -Factory Reset& Remove Robot at the last in the APP.
3. Reset to factory manually via long pressing cleaning button and home button until reset the robot.
4. Reconnect the wifi

If obstruction is cleared and issue remains → Provide operation video and SN, and then escalate to Technical team.
