NIHVA
NIHVA TECHNOLOGIES PVT. LTD.

Conceptual Image for Gantry System :-



Process Flow Chart

NIHVA
NIHVA TECHNOLOGIES PVT. LTD.

Manually Raw Material Putting for Press Operation

First Y Axis(Beam) Move Forward Direction.

Z Axis (Beam) Move Towards Downward Direction.


Pick Part with Help Of Gripper Mechanism.

Y Axis(Beam)Move Towards Reverse Direction.

Z Axis(Beam) Moves Towards Upward Direction

Place Part on Table.

Y and Z Axis (Beam) Comes in origin Position.



NIHVA
NIHVA TECHNOLOGIES PVT. LTD.

Technical Aspect :-

- AS there is Pit Infront of Press machine we suggest **H Type Gantry System** for Part Pick and Place on Table.
- Gantry system Include X,Y and Z Beam.
- Movement of this System is done by Rack and Pinion Mechanism along with servo Motor.
- Gantry system include Gripper for part Pick and Place.
- PLC with HMI is used for control the Gantry System.
- H Type Gantry system is safety oriented system having Mechanical and Electrical Safety Equipment.
- For More Safety We can used Fencing Enclosure with Electromechanical Equipment.

NIHVA
NIHVA TECHNOLOGIES PVT. LTD.

Reference video :-

https://youtu.be/On4W70604ck