





WRS	Name	Start	Finish	Work	Duration	Slack	Cost	Assigned to	% Complete
1	Init Capping Station	Jun 7	Jun 8	1d 21h	1d 4h	4d 2h	0	/ Issued to	10
1.1	Init P&P	Jun 7	Jun 7	6h	6h	5d	0		0
1.1.1	Open Gripper	Jun 7	Jun 7	1h	1h	2d 4h	0	Gripper	0
1.1.2	Ver home	Jun 7	Jun 7	3h	3h	2d 4h	0	Ver Cyl	0
1.1.3	Hor Home	Jun 7	Jun 7	2h	2h	2d 411 2d 23h	0	Hor Cyl	0
1.2	Init Supply	Jun 7	Jun 7	9h 50min	9h 50min	4d 19h	0	Tior Cyr	0
1.2.1	Cyl home	Jun 7	Jun 7	1h 30min	1h 30min	2d 18h	0	Cyl	0
1.2.2	Motor on	Jun 7	Jun 7	10min	10min	2d 18h	0	SupplyMotor	0
1.2.3	Wait for Cap	Jun 7	Jun 7	8h	8h	2d 18h	0	PartPresence	0
1.2.4	Motor off	Jun 7	Jun 7	10min	10min	4d 19h	0	SupplyMotor	0
1.3	Init Transport	Jun 7	Jun 8	1d 5h	1d 4h	4d 2h	0	эарргут юсь.	0
1.3.1	Close Inlet	Jun 7	Jun 7	8h	8h	2d 1h	0	InletStopper	0
1.3.2	Release Index	Jun 7	Jun 7	1h	1h	2d 4h	0	Index	30
1.3.3	Motor on	Jun 7	Jun 7	10min	10min	2d 1h	0	TransportMotor	3
1.3.4	Empty Work Area	Jun 7	Jun 8	20h	20h 1min	2d 1h	0	WorkPosStopper	0
1.4	Init Done	Jun 8	Jun 8	N/A	N/A	2d 1h	0		0
2	Normal operation, first time	Jun 8	Jun 10	2d 20h	2d 1h	2d 1h	0		0
2.1	Supply	Jun 8	Jun 8	11h 20min	12h 20min	3d 13h	0		0
2.1.1	Cyl work	Jun 8	Jun 8	1h 30min	1h 30min	1d 1h	0	Cyl	0
2.1.2	Cyl home	Jun 8	Jun 8	1h 30min	1h 30min	1d 1h	0	СуІ	0
2.1.3	Supply Motor on	Jun 8	Jun 8	10min	10min	3d 13h	0	SupplyMotor	0
2.1.4	Wait for Cap	Jun 8	Jun 8	8h	8h	3d 13h	0	PartPresence	0
2.1.5	Supply Motor off	Jun 8	Jun 8	10min	10min	3d 13h	0	SupplyMotor	0
2.2	Pick & Place	Jun 8	Jun 9	15h	1d 14h	2d 9h	0		0
2.2.1	Close Gripper	Jun 8	Jun 8	1h	1h	1d 1h	0	Gripper	0
2.2.2	Hor work	Jun 8	Jun 8	2h	2h	1d 1h	0	Hor Cyl	0
2.2.3	Ver work	Jun 9	Jun 9	3h	3h		0	Ver Cyl	0
2.2.4	Capture pressure profile	Jun 9	Jun 9	3h	3h	2d 15h	0	PressureSensor	0
2.2.5	Open Gripper	Jun 9	Jun 9	1h	1h		0	Gripper	0
2.2.6	Ver home	Jun 9	Jun 9	3h	3h		0	Ver Cyl	0
2.2.7	Hor home	Jun 9	Jun 9	2h	2h	1d 9h	0	Hor Cyl	0
2.3	Handle Transport	Jun 8	Jun 10	1d 18h	2d 1h	2d 1h	0		0
2.3.1	Let pass 1 palette	Jun 8	Jun 8	10h	10h		0	InletStopper	0
2.3.2	Wait for palette	Jun 8	Jun 9	20h	20h 1min		0	WorkPosStopper	0
2.3.3	Fix platte	Jun 9	Jun 9	1h	1h		0	Index	0
2.3.4	Release palette	Jun 9	Jun 9	1h	1h		0	Index	0
2.3.5	Move out palette	Jun 9	Jun 10	10h	10h 1min		0	WorkPosStopper	0
2.3.6	Work area empty	Jun 10	Jun 10	N/A	N/A		0	WorkPosStopper	0
3	Normal operation, consecutive	Jun 9	Jun 12	2d 20h	2d 9h		0		0
3.1	Supply	Jun 9	Jun 10	11h 10min	12h 9min	1d 21h	0		0
3.1.1	Cyl work Cyl home	Jun 9 Jun 9	Jun 9 Jun 10	1h 30min 1h 30min	1h 30min 1h 31min	1d 9h 1d 10h	0	Cyl	0
3.1.3	Supply Motor on	Jun 10	Jun 10	10min	10min	1d 10h	0	SupplyMotor	0
3.1.4	Wait for Cap	<u> </u>	Jun 10	8h	8h	1d 21h	0	PartPresence	0
3.2	Pick & Place	Jun 9	Jun 11	15h	1d 23h	8h 59min	0	raid reserice	0
3.2.1	Close Gripper2	Jun 9	Jun 9	1h	1h	1d 9h	0	Gripper	0
3.2.2	Hor work	-	Jun 10	2h	2h	1d 10h	0	Hor Cyl	0
3.2.3	Ver work	Jun 11		3h	3h		0	Ver Cyl	0
3.2.4	Capture pressure profile	Jun 11		3h	3h	14h 59min	0	PressureSensor	0
3.2.5	Open Gripper	Jun 11		1h	1h		0	Gripper	0
	the state of the s	-	Jun 11	3h	3h		0	Ver Cyl	0
3.2.6	Ver home	Jun 11				8h 59min	0	Hor Cyl	0
3.2.6 3.2.7	Ver home Hor home	Jun 11	Jun 11	2h	2h	0 55		,	
		-		2h 1d 18h	2d 1h	0 33	0		0
3.2.7	Hor home	Jun 11	Jun 12				0	InletStopper	0
3.2.7	Hor home Handle Transport	Jun 11 Jun 10	Jun 12 Jun 10	1d 18h	2d 1h			,	
3.2.7 3.3 3.3.1	Hor home Handle Transport Let pass 1 palette	Jun 11 Jun 10 Jun 10	Jun 12 Jun 10 Jun 11	1d 18h 10h	2d 1h 10h		0	InletStopper	0
3.2.7 3.3 3.3.1 3.3.2	Hor home Handle Transport Let pass 1 palette Wait for palette	Jun 11 Jun 10 Jun 10 Jun 10	Jun 12 Jun 10 Jun 11 Jun 11	1d 18h 10h 20h	2d 1h 10h 20h 1min		0	InletStopper WorkPosStopper	0
3.2.7 3.3 3.3.1 3.3.2 3.3.3	Hor home Handle Transport Let pass 1 palette Wait for palette Fix platte 2	Jun 11 Jun 10 Jun 10 Jun 10 Jun 10 Jun 11	Jun 12 Jun 10 Jun 11 Jun 11 Jun 11	1d 18h 10h 20h 1h	2d 1h 10h 20h 1min 1h		0 0 0	InletStopper WorkPosStopper Index	0 0 0

	1		T	_	
Name	Short name	Туре	Group	Email	Cost
Gripper		Work	P&P		0
Ver Cyl		Work	P&P		0
Hor Cyl		Work	P&P		0
InletStopper		Work	Transport		0
WorkPosStopper		Work	Transport		0
Index		Work	Transport		0
TransportMotor		Work	Transport		0
СуІ		Work	Supply		0
PartPresence		Work	Supply		0
SupplyMotor		Work	Supply		0
PressureSensor		Work	P&P		0