



Jobcard (Schedule Attention) : 006
Diesel Electric Loco Shed-Sabarmati
Western Railway

Loco/Sch : 32456 - I/IB
Arrival : 03/04/2025 21:09
Issued To : Mechanical

Tested By (E/M) : -- / --

Created By/On : SUDHIR KUMAR- 07/04/2025 10:47

Issued By/On : SUDHIR KUMAR -07/04/2025 10:56

Returned By/On : Vikash Kumar -07/04/2025 14:24

No	Description of Job	Type	Action Taken	Comp.	Attn.By
1	Gear case no 5 bottom side 02 no. bolt of size 16x20 mm, fitted with TM end cover broken inside.	D/R	Attended	Fit	CHHOTI LAL MEENA,PAWAN KUMAR
2	Wheel no. 10 compound oil leakage.	D/R	Attended	Fit	CHHOTI LAL MEENA,PAWAN KUMAR

Section Remarks:

Enter your section activity remarks here for CARDEX updation

Issued By
(SUDHIR KUMAR)

Checked By
(Mechanical Supervisor)

Verified By
(Planning Section Technician)

Verified By
(Planning Section Supervisor)



Jobcard (Schedule Attention) : 004
Diesel Electric Loco Shed-Sabarmati
Western Railway

Loco/Sch : 32456 - I/IB
Arrival : 03/04/2025 21:09
Issued To : Pneumatic

Tested By (E/M) : -- / --

Created By/On : SUDHIR KUMAR- 07/04/2025 10:45

Issued By/On : SUDHIR KUMAR -07/04/2025 10:56

Returned By/On : RAJESH KUMAR -07/04/2025 14:49

No	Description of Job	Type	Action Taken	Comp.	Attn.By
1	Bogie -2 isolate precautionary by switch no 154 to stop the jerk for safety purpose.	D/R	Book pertain to electsection	Reject	RAJESH KUMAR
2	Both side sanders are not working of cab -1 & cab -2.	D/R	Sender overhaul working normal	Fit	RAJESH KUMAR

Section Remarks:

Schedule done

Issued By
(SUDHIR KUMAR)

Checked By
(Pneumatic Supervisor)

Verified By
(Planning Section Technician)

Verified By
(Planning Section Supervisor)



Jobcard (Schedule Attention) : 002
Diesel Electric Loco Shed-Sabarmati
Western Railway

Loco/Sch : 32456 - I/IB
Arrival : 03/04/2025 21:09
Issued To : Electrical

Tested By (E/M) : -- / --

Created By/On : SUDHIR KUMAR- 07/04/2025 10:44

Issued By/On : SUDHIR KUMAR -07/04/2025 10:56

Returned By/On : Amrish Kumar -09/04/2025 19:50

No	Description of Job	Type	Action Taken	Comp.	Attn.By
1	Selica gel colour slightly pink.	D/R	attend	Fit	SITA RAM,YOGESH
2	Bogie -2 isolate pracautionary by switch no 154 to stop the jerk to stop the jerk for safety purpose.	D/R	attend	Fit	JAMSHER ALAM
3	F0305P2 fault msg for equip. temp high.	D/R	attend	Fit	RAKESH KUMAR,MUNENDRA BHARATI
4	F0304P2 faulty moton temp sensor.	D/R	TM 5 temp sensor changed	Fit	RAKESH KUMAR,MUNENDRA BHARATI
5	Cab -2 AC not working. but blower ok.	D/R	same allow	Fit	JAMSHER ALAM

Section Remarks:

Enter your section activity remarks here for CARDEX updation

Issued By
(SUDHIR KUMAR)

Checked By
(Electrical Supervisor)

Verified By
(Planning Section Technician)

Verified By
(Planning Section Supervisor)