PROPERTY CONDITION ASSESSMENT

Union Union Tower | Atlanta, GA

Property	Union Union Tower
Address	5946 Pioneer Drive, Atlanta, GA 34669
Site Visit Date	July 2, 2018
Client	Beacon Hollow Investors
Immediate Repairs	$421,000

Construction Details

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The building features a renovated lobby, structured parking at a ratio of 16 per 1,000 square feet, and a tenant lounge with fitness center. Floor plates are efficient and column-spacing supports open and private-office layouts. Weighted average lease term remaining is 10 years and in-place rents average $42 per square foot, full service gross.

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Weighted average lease term remaining is 3 years and in-place rents average $42 per square foot, full service gross. Floor plates are efficient and column-spacing supports open and private-office layouts. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $45,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 41 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $209,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 4 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months.

Building Systems

Floor plates are efficient and column-spacing supports open and private-office layouts. Weighted average lease term remaining is 8 years and in-place rents average $42 per square foot, full service gross. The roof is a 24-year membrane system with an estimated remaining useful life of 3 years. Mechanical systems include rooftop package units and central plant equipment of varying age. Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 37 stories. Common area interiors have been refreshed within the last 4 years and are in average to good condition.

Floor plates are efficient and column-spacing supports open and private-office layouts. Common area interiors have been refreshed within the last 6 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Mechanical systems include rooftop package units and central plant equipment of varying age. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $352,000. Elevators were last modernized 9 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Weighted average lease term remaining is 6 years and in-place rents average $42 per square foot, full service gross. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Common area interiors have been refreshed within the last 5 years and are in average to good condition.

The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Weighted average lease term remaining is 10 years and in-place rents average $42 per square foot, full service gross. The building features a renovated lobby, structured parking at a ratio of 17 per 1,000 square feet, and a tenant lounge with fitness center. Mechanical systems include rooftop package units and central plant equipment of varying age.

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $470,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 20 months.

Elevators were last modernized 3 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $136,000.

Building Systems

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Floor plates are efficient and column-spacing supports open and private-office layouts. The building features a renovated lobby, structured parking at a ratio of 47 per 1,000 square feet, and a tenant lounge with fitness center. Mechanical systems include rooftop package units and central plant equipment of varying age. Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 46 stories.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The building features a renovated lobby, structured parking at a ratio of 18 per 1,000 square feet, and a tenant lounge with fitness center. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. The roof is a 8-year membrane system with an estimated remaining useful life of 11 years. Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 36 stories.

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $320,000.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 23 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $135,000.

Construction Details

Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 47 stories. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Mechanical systems include rooftop package units and central plant equipment of varying age. Weighted average lease term remaining is 8 years and in-place rents average $42 per square foot, full service gross. The roof is a 33-year membrane system with an estimated remaining useful life of 6 years. Floor plates are efficient and column-spacing supports open and private-office layouts.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	24	29	5	Fair	$30,000	$56,000
Paving	8	17	9	Poor	$9,000	$206,000
HVAC	20	36	16	Poor	$18,000	$76,000
Plumbing	5	33	28	Fair	$17,000	$8,000
Electrical	8	27	19	Fair	$10,000	$198,000
Elevators	1	15	14	Good	$12,000	$145,000
Fire/Life Safety	15	33	18	Fair	$13,000	$257,000
Windows	2	14	12	Fair	$0	$202,000
Siding/Facade	12	27	15	Good	$3,000	$36,000
Flooring	15	30	15	Fair	$17,000	$265,000
Appliances	3	13	10	Fair	$32,000	$230,000
Landscaping	2	35	33	Fair	$1,000	$74,000
Pool/Amenity	2	34	32	Good	$3,000	$221,000
Signage	5	11	6	Fair	$16,000	$131,000
Fencing	2	10	8	Fair	$13,000	$78,000
Roof (2)	8	26	18	Fair	$14,000	$277,000
Paving (2)	15	17	2	Fair	$37,000	$11,000
HVAC (2)	9	16	7	Good	$38,000	$109,000
Plumbing (2)	2	11	9	Poor	$26,000	$36,000
Electrical (2)	1	19	18	Good	$4,000	$183,000
Elevators (2)	12	15	3	Good	$10,000	$85,000
Fire/Life Safety (2)	19	21	2	Poor	$8,000	$122,000
Windows (2)	15	15	0	Poor	$29,000	$20,000
Siding/Facade (2)	1	21	20	Good	$11,000	$50,000
Flooring (2)	22	33	11	Poor	$0	$99,000
Appliances (2)	16	16	0	Fair	$3,000	$70,000
Landscaping (2)	10	15	5	Poor	$7,000	$133,000
Pool/Amenity (2)	12	32	20	Good	$4,000	$22,000
Signage (2)	13	28	15	Fair	$32,000	$125,000
Fencing (2)	34	40	6	Fair	$24,000	$33,000

Report generated 07/02/2018. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Stair treads	Roof	Worn / loose	Replace treads	Reserve	$16,500
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 2-5	$27,500
Window sealant	Site	Failed	Re-caulk	Immediate	$78,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Year 1	$45,500
Water heater	Bldg B	Corrosion	Replace	Year 2-5	$72,000
Sidewalk	Roof	Trip hazards	Grind / replace	Year 2-5	$32,000
Window sealant	Roof	Failed	Re-caulk	Year 1	$85,500
Sprinkler heads	Site	Painted heads	Replace	Immediate	$36,500
HVAC unit	Site	Beyond useful life	Replace RTU	Year 2-5	$76,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 1	$15,000
Fire extinguishers	Site	Expired tags	Service	Immediate	$48,000
Sprinkler heads	Site	Painted heads	Replace	Reserve	$67,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 1	$14,000
Asphalt paving	Site	Alligator cracking	Mill and overlay	Immediate	$12,500
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 2-5	$90,000
Sidewalk	Mechanical	Trip hazards	Grind / replace	Reserve	$63,000
Window sealant	Common	Failed	Re-caulk	Reserve	$35,500
Sidewalk	Roof	Trip hazards	Grind / replace	Year 1	$2,500
Sprinkler heads	Roof	Painted heads	Replace	Year 2-5	$8,500
Handrail	Bldg B	Loose	Secure	Year 2-5	$57,000
Sprinkler heads	Site	Painted heads	Replace	Immediate	$11,500
Water heater	Mechanical	Corrosion	Replace	Year 1	$54,500
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Year 2-5	$53,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Immediate	$16,000
Window sealant	Bldg B	Failed	Re-caulk	Year 2-5	$61,000
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$55,000
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Year 2-5	$73,000
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 1	$9,000
Sidewalk	Bldg A	Trip hazards	Grind / replace	Year 1	$31,000
HVAC unit	Site	Beyond useful life	Replace RTU	Year 1	$27,500
Sidewalk	Site	Trip hazards	Grind / replace	Year 2-5	$73,000
Dumpster enclosure	Site	Damaged gate	Repair	Year 1	$87,000
Sprinkler heads	Common	Painted heads	Replace	Immediate	$73,000
Stair treads	Mechanical	Worn / loose	Replace treads	Year 2-5	$33,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Year 1	$70,000
Water heater	Common	Corrosion	Replace	Year 2-5	$16,000
Stair treads	Mechanical	Worn / loose	Replace treads	Reserve	$19,000
Stair treads	Roof	Worn / loose	Replace treads	Year 2-5	$67,500
Window sealant	Roof	Failed	Re-caulk	Year 1	$84,500
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Reserve	$15,500
Fire extinguishers	Site	Expired tags	Service	Year 1	$12,000
Dumpster enclosure	Roof	Damaged gate	Repair	Year 1	$2,500

Report generated 07/02/2018. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 38 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 6 years ago and are operating without deficiency.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $108,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 30 months. Elevators were last modernized 9 years ago and are operating without deficiency.

Elevators were last modernized 8 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $455,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Deferred Maintenance

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 40 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 10 years ago and are operating without deficiency.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 7 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $197,000.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Construction Details

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Floor plates are efficient and column-spacing supports open and private-office layouts. Weighted average lease term remaining is 6 years and in-place rents average $42 per square foot, full service gross. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 8 stories.

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The roof is a 27-year membrane system with an estimated remaining useful life of 7 years. Weighted average lease term remaining is 12 years and in-place rents average $42 per square foot, full service gross.

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $37,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 6 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $208,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months. Elevators were last modernized 11 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Improvements Description

Common area interiors have been refreshed within the last 11 years and are in average to good condition. The roof is a 5-year membrane system with an estimated remaining useful life of 12 years. Mechanical systems include rooftop package units and central plant equipment of varying age. Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 30 stories.

The roof is a 40-year membrane system with an estimated remaining useful life of 5 years. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Floor plates are efficient and column-spacing supports open and private-office layouts.

Recommendations

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 14 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $70,000. Elevators were last modernized 5 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months.

Improvements Description

Common area interiors have been refreshed within the last 12 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 22 stories. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Floor plates are efficient and column-spacing supports open and private-office layouts.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	10	29	19	Fair	$23,000	$190,000
Paving	7	17	10	Good	$24,000	$167,000
HVAC	13	24	11	Poor	$10,000	$140,000
Plumbing	13	13	0	Poor	$32,000	$122,000
Electrical	6	16	10	Poor	$21,000	$267,000
Elevators	12	35	23	Fair	$38,000	$146,000
Fire/Life Safety	3	24	21	Poor	$11,000	$120,000
Windows	25	35	10	Fair	$33,000	$198,000
Siding/Facade	7	35	28	Fair	$16,000	$239,000
Flooring	5	27	22	Poor	$26,000	$128,000
Appliances	3	22	19	Fair	$33,000	$238,000
Landscaping	34	39	5	Fair	$11,000	$108,000
Pool/Amenity	20	32	12	Fair	$12,000	$108,000
Signage	12	19	7	Fair	$37,000	$193,000
Fencing	9	10	1	Fair	$22,000	$39,000
Roof (2)	6	20	14	Fair	$14,000	$9,000
Paving (2)	3	16	13	Good	$40,000	$236,000
HVAC (2)	24	24	0	Fair	$20,000	$69,000
Plumbing (2)	31	36	5	Poor	$32,000	$136,000
Electrical (2)	28	32	4	Good	$2,000	$185,000
Elevators (2)	5	12	7	Fair	$25,000	$19,000
Fire/Life Safety (2)	16	26	10	Poor	$6,000	$17,000
Windows (2)	22	37	15	Poor	$36,000	$75,000
Siding/Facade (2)	20	26	6	Poor	$5,000	$266,000
Flooring (2)	2	12	10	Poor	$4,000	$251,000
Appliances (2)	8	10	2	Fair	$5,000	$119,000
Landscaping (2)	11	14	3	Fair	$24,000	$17,000
Pool/Amenity (2)	20	24	4	Fair	$40,000	$277,000
Signage (2)	18	19	1	Fair	$15,000	$36,000
Fencing (2)	4	17	13	Poor	$15,000	$59,000

Report generated 07/02/2018. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Water heater	Common	Corrosion	Replace	Year 1	$30,000
Window sealant	Roof	Failed	Re-caulk	Immediate	$85,000
Water heater	Roof	Corrosion	Replace	Reserve	$8,000
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Reserve	$85,500
Water heater	Bldg A	Corrosion	Replace	Reserve	$9,000
Stair treads	Mechanical	Worn / loose	Replace treads	Reserve	$24,000
Window sealant	Bldg B	Failed	Re-caulk	Immediate	$86,500
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Reserve	$55,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 2-5	$22,500
Sprinkler heads	Roof	Painted heads	Replace	Year 1	$34,500
Water heater	Common	Corrosion	Replace	Year 2-5	$25,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 2-5	$24,500
Window sealant	Bldg A	Failed	Re-caulk	Year 2-5	$56,500
Dumpster enclosure	Roof	Damaged gate	Repair	Year 1	$81,000
Window sealant	Site	Failed	Re-caulk	Reserve	$30,500
Roof membrane	Bldg B	Ponding / seams	Re-seal and repair	Year 1	$62,000
Window sealant	Site	Failed	Re-caulk	Immediate	$85,000
Sprinkler heads	Mechanical	Painted heads	Replace	Year 2-5	$29,500
Dumpster enclosure	Bldg A	Damaged gate	Repair	Year 1	$27,000
Roof membrane	Common	Ponding / seams	Re-seal and repair	Year 1	$83,500
Stair treads	Roof	Worn / loose	Replace treads	Year 1	$62,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Year 1	$34,500
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Year 2-5	$30,000
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Immediate	$67,000
Water heater	Bldg A	Corrosion	Replace	Reserve	$59,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Immediate	$63,000
Window sealant	Mechanical	Failed	Re-caulk	Immediate	$55,000
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Reserve	$15,000
Water heater	Roof	Corrosion	Replace	Immediate	$77,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Immediate	$78,500
Stair treads	Roof	Worn / loose	Replace treads	Year 2-5	$58,000
Stair treads	Mechanical	Worn / loose	Replace treads	Year 2-5	$31,500
Fire extinguishers	Mechanical	Expired tags	Service	Year 1	$6,000
HVAC unit	Site	Beyond useful life	Replace RTU	Reserve	$10,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 2-5	$85,000
Stair treads	Mechanical	Worn / loose	Replace treads	Reserve	$60,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 1	$59,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Reserve	$34,500
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Year 2-5	$89,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Immediate	$4,000
Fire extinguishers	Mechanical	Expired tags	Service	Year 1	$80,500
Asphalt paving	Site	Alligator cracking	Mill and overlay	Year 1	$9,500

Report generated 07/02/2018. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Elevators were last modernized 7 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 31 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $252,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 37 months. Elevators were last modernized 10 years ago and are operating without deficiency.

Recommendations

Elevators were last modernized 11 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Elevators were last modernized 4 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $167,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 15 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $479,000. Elevators were last modernized 10 years ago and are operating without deficiency.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 47 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $111,000.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Mechanical systems include rooftop package units and central plant equipment of varying age. Weighted average lease term remaining is 4 years and in-place rents average $42 per square foot, full service gross. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The roof is a 4-year membrane system with an estimated remaining useful life of 7 years.

Weighted average lease term remaining is 6 years and in-place rents average $42 per square foot, full service gross. Mechanical systems include rooftop package units and central plant equipment of varying age. The building features a renovated lobby, structured parking at a ratio of 10 per 1,000 square feet, and a tenant lounge with fitness center. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 43 stories.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $141,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. Elevators were last modernized 6 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $326,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 12 years ago and are operating without deficiency.

Building Systems

Weighted average lease term remaining is 12 years and in-place rents average $42 per square foot, full service gross. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Union Union Tower was originally constructed in 2013 and consists of 406,000 SF in a building of 39 stories. The building features a renovated lobby, structured parking at a ratio of 3 per 1,000 square feet, and a tenant lounge with fitness center. Common area interiors have been refreshed within the last 6 years and are in average to good condition. The roof is a 9-year membrane system with an estimated remaining useful life of 6 years.

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Weighted average lease term remaining is 8 years and in-place rents average $42 per square foot, full service gross. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 38 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $320,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $186,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months.

Building Systems

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Weighted average lease term remaining is 8 years and in-place rents average $42 per square foot, full service gross. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Floor plates are efficient and column-spacing supports open and private-office layouts. The building features a renovated lobby, structured parking at a ratio of 35 per 1,000 square feet, and a tenant lounge with fitness center.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Union Union Tower and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on June 21, 2018.

_____

Elena Nguyen, PE

Lindqvist Engineering Group

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only