PROPERTY CONDITION ASSESSMENT

Jasper Verde Secure Storage | Boston, MA

Property	Jasper Verde Secure Storage
Address	8253 Heritage Drive, Boston, MA 66047
Site Visit Date	July 11, 2021
Client	Anchorage Meadow Partners
Immediate Repairs	$420,000

Building Systems

The roof is a 25-year membrane system with an estimated remaining useful life of 11 years. Mechanical systems include rooftop package units and central plant equipment of varying age. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

The facility offers climate-controlled and drive-up units, a manager's office, keypad gate access and video surveillance. Common area interiors have been refreshed within the last 11 years and are in average to good condition. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Physical occupancy is 90.6% and the average in-place rent is $182 per unit per month. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 5-year membrane system with an estimated remaining useful life of 6 years.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 37 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 3 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 5 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 7 years ago and are operating without deficiency.

Improvements Description

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Physical occupancy is 93.3% and the average in-place rent is $182 per unit per month. Ancillary income includes tenant insurance, merchandise sales and truck rental commissions.

The roof is a 5-year membrane system with an estimated remaining useful life of 10 years. Jasper Verde Secure Storage was originally constructed in 1962 and consists of 571 storage units in a building of 20 stories. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The facility offers climate-controlled and drive-up units, a manager's office, keypad gate access and video surveillance. Physical occupancy is 92.3% and the average in-place rent is $182 per unit per month. Mechanical systems include rooftop package units and central plant equipment of varying age.

Deferred Maintenance

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

Physical occupancy is 94.4% and the average in-place rent is $182 per unit per month. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Unit sizes range from 5x5 to 10x30 and the property is managed by an on-site team with online rental capability. Ancillary income includes tenant insurance, merchandise sales and truck rental commissions. Common area interiors have been refreshed within the last 10 years and are in average to good condition.

The roof is a 29-year membrane system with an estimated remaining useful life of 4 years. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Physical occupancy is 89.4% and the average in-place rent is $182 per unit per month. Unit sizes range from 5x5 to 10x30 and the property is managed by an on-site team with online rental capability. Common area interiors have been refreshed within the last 8 years and are in average to good condition.

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $200,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 46 months.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 38 months. Elevators were last modernized 5 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Improvements Description

Common area interiors have been refreshed within the last 11 years and are in average to good condition. The roof is a 35-year membrane system with an estimated remaining useful life of 8 years. Physical occupancy is 96.4% and the average in-place rent is $182 per unit per month. Mechanical systems include rooftop package units and central plant equipment of varying age. Unit sizes range from 5x5 to 10x30 and the property is managed by an on-site team with online rental capability. Jasper Verde Secure Storage was originally constructed in 1962 and consists of 571 storage units in a building of 14 stories.

Mechanical systems include rooftop package units and central plant equipment of varying age. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Common area interiors have been refreshed within the last 7 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The roof is a 6-year membrane system with an estimated remaining useful life of 9 years.

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 10 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $217,000.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	18	38	20	Good	$1,000	$138,000
Paving	11	12	1	Fair	$20,000	$215,000
HVAC	7	33	26	Poor	$9,000	$275,000
Plumbing	10	17	7	Poor	$32,000	$99,000
Electrical	1	20	19	Poor	$5,000	$36,000
Elevators	37	39	2	Fair	$32,000	$214,000
Fire/Life Safety	10	12	2	Fair	$8,000	$121,000
Windows	3	25	22	Fair	$18,000	$186,000
Siding/Facade	3	11	8	Poor	$20,000	$149,000
Flooring	20	35	15	Poor	$27,000	$18,000
Appliances	19	19	0	Good	$3,000	$134,000
Landscaping	6	15	9	Fair	$14,000	$236,000
Pool/Amenity	22	24	2	Poor	$39,000	$103,000
Signage	25	30	5	Fair	$17,000	$276,000
Fencing	9	15	6	Poor	$35,000	$104,000
Roof (2)	1	30	29	Good	$17,000	$114,000
Paving (2)	7	37	30	Poor	$17,000	$222,000
HVAC (2)	18	28	10	Fair	$5,000	$118,000
Plumbing (2)	8	11	3	Fair	$15,000	$24,000
Electrical (2)	5	17	12	Fair	$16,000	$277,000
Elevators (2)	17	25	8	Fair	$34,000	$104,000
Fire/Life Safety (2)	11	15	4	Good	$31,000	$17,000
Windows (2)	4	17	13	Good	$22,000	$276,000
Siding/Facade (2)	20	28	8	Fair	$9,000	$41,000
Flooring (2)	19	20	1	Good	$36,000	$193,000
Appliances (2)	18	26	8	Good	$10,000	$39,000
Landscaping (2)	10	10	0	Good	$3,000	$232,000
Pool/Amenity (2)	8	32	24	Good	$35,000	$96,000
Signage (2)	13	36	23	Fair	$34,000	$130,000
Fencing (2)	28	33	5	Fair	$25,000	$95,000

Report generated 07/11/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Sidewalk	Roof	Trip hazards	Grind / replace	Year 2-5	$44,000
Roof membrane	Common	Ponding / seams	Re-seal and repair	Year 2-5	$3,000
Sprinkler heads	Site	Painted heads	Replace	Year 1	$84,500
Fire extinguishers	Bldg A	Expired tags	Service	Immediat	$62,500
Fire extinguishers	Roof	Expired tags	Service	Immediat	$11,000
Handrail	Common	Loose	Secure	Immediat	$7,500
Sidewalk	Site	Trip hazards	Grind / replace	Year 1	$18,500
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Reserve	$69,500
Roof membrane	Bldg B	Ponding / seams	Re-seal and repair	Immediat	$11,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Reserve	$34,500
Handrail	Mechanical	Loose	Secure	Year 1	$13,500
Handrail	Site	Loose	Secure	Year 2-5	$17,000
Dumpster enclosure	Bldg B	Damaged gate	Repair	Reserve	$75,500
Stair treads	Common	Worn / loose	Replace treads	Immediat	$30,500
Sidewalk	Mechanical	Trip hazards	Grind / replace	Year 2-5	$74,500
Stair treads	Bldg B	Worn / loose	Replace treads	Year 2-5	$28,000
Sidewalk	Bldg A	Trip hazards	Grind / replace	Year 1	$52,500
Sprinkler heads	Bldg B	Painted heads	Replace	Reserve	$7,000
Stair treads	Common	Worn / loose	Replace treads	Reserve	$89,000
Sprinkler heads	Bldg B	Painted heads	Replace	Reserve	$16,000
Window sealant	Common	Failed	Re-caulk	Year 2-5	$16,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 1	$88,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Immediat	$51,000
Window sealant	Bldg A	Failed	Re-caulk	Reserve	$54,000
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Year 1	$48,000
Water heater	Roof	Corrosion	Replace	Reserve	$71,000
Dumpster enclosure	Bldg B	Damaged gate	Repair	Reserve	$73,000
Sidewalk	Bldg B	Trip hazards	Grind / replace	Reserve	$5,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Reserve	$84,500
Fire extinguishers	Roof	Expired tags	Service	Reserve	$84,000
Stair treads	Roof	Worn / loose	Replace treads	Reserve	$81,000
Dumpster enclosure	Site	Damaged gate	Repair	Year 2-5	$4,000
Sprinkler heads	Common	Painted heads	Replace	Year 1	$43,500
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Year 1	$59,500
Water heater	Bldg B	Corrosion	Replace	Year 1	$77,000
Sidewalk	Common	Trip hazards	Grind / replace	Immediat	$87,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Reserve	$28,000
Dumpster enclosure	Site	Damaged gate	Repair	Reserve	$17,500
Water heater	Bldg B	Corrosion	Replace	Reserve	$49,500
Asphalt paving	Common	Alligator cracking	Mill and overlay	Year 1	$500

Report generated 07/11/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only