CAPITAL IMPROVEMENT PLAN

Nautilus Onyx Tower | Richmond, VA

Property	Nautilus Onyx Tower
Plan Date	August 16, 2021
Prepared For	Keel & Compass Properties
Total Plan Budget	$412,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Door hardware	Interior	02/10/23	Q3 2027	$106,000	$12,038	Bidding
Unit interior upgrades	Interior	06/14/23	Q2 2027	$545,000	$410,643	In progress
Water heater replacement	Life Safety	03/16/24	Q2 2026	$415,000	$131,915	Deferred
Sewer line repair	Interior	12/26/23	Q1 2025	$436,000	$255,271	Deferred
Unit interior upgrades	Site	06/16/26	Q1 2027	$69,000	$1,148	Deferred
Unit interior upgrades	Energy	06/24/25	Q1 2025	$808,000	$310,818	Complete
Fence replacement	Building	08/20/25	Q3 2026	$144,000	$7,586	Approved
Lobby renovation	Energy	02/05/26	Q1 2026	$526,000	$292,951	Approved
Exterior paint	Site	09/26/26	Q4 2027	$100,000	$84,837	Bidding
Exterior paint	Life Safety	12/31/25	Q3 2026	$714,000	$158,044	Complete
HVAC replacement	Energy	02/01/24	Q2 2025	$587,000	$433,852	In progress
Signage / monument	Energy	04/10/25	Q2 2026	$389,000	$192,921	Bidding
Water heater replacement	Building	08/14/23	Q3 2027	$426,000	$219,614	Approved
Amenity renovation	Site	10/05/26	Q3 2025	$426,000	$218,651	Bidding
Storefront glazing	Building	02/20/26	Q1 2027	$95,000	$76,872	Approved
Landscape / irrigation	Energy	11/18/25	Q1 2027	$96,000	$6,167	Bidding
Amenity renovation	Life Safety	03/07/26	Q1 2026	$830,000	$563,112	Approved
Security camera upgrade	Building	09/02/25	Q3 2025	$886,000	$271,157	Complete
Storefront glazing	Energy	08/19/24	Q4 2027	$267,000	$243,201	Bidding
Storefront glazing	Interior	11/09/25	Q4 2027	$760,000	$370,695	Deferred
Exterior paint	Life Safety	03/13/25	Q1 2025	$676,000	$678,569	Approved
Fire alarm panel upgrade	Life Safety	08/17/26	Q4 2025	$336,000	$107,547	In progress
LED lighting retrofit	Life Safety	11/11/24	Q4 2027	$470,000	$359,440	Complete

Report generated 08/16/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Storefront glazing	Site	01/25/24	Q2 2026	$68,000	$33,902	Bidding
Fire alarm panel upgrade	Site	09/22/24	Q4 2027	$266,000	$244,525	In progress
Signage / monument	Energy	10/29/24	Q4 2025	$557,000	$543,099	Approved
Unit interior upgrades	Site	10/26/26	Q2 2026	$126,000	$10,584	Approved
Security camera upgrade	Building	01/31/24	Q3 2026	$740,000	$485,148	Complete
Security camera upgrade	Building	07/12/26	Q2 2025	$248,000	$170,249	In progress
Security camera upgrade	Building	11/17/25	Q4 2026	$496,000	$325,823	Deferred
Elevator modernization	Building	08/24/23	Q2 2026	$545,000	$366,234	Deferred
Door hardware	Site	08/10/23	Q3 2027	$93,000	$56,911	Bidding
Water heater replacement	Building	10/01/26	Q4 2027	$110,000	$62,096	Approved
Parking lot resurfacing	Interior	12/30/24	Q2 2027	$529,000	$539,608	Approved
Unit interior upgrades	Life Safety	07/10/25	Q3 2026	$559,000	$389,956	Bidding
Parking lot resurfacing	Site	09/08/24	Q4 2025	$687,000	$100,230	Approved
Parking lot resurfacing	Interior	03/26/25	Q4 2026	$159,000	$76,443	Complete
HVAC replacement	Life Safety	12/31/24	Q3 2027	$161,000	$104,731	Approved
Fire alarm panel upgrade	Interior	11/06/25	Q4 2025	$648,000	$394,705	Approved
Elevator modernization	Building	08/09/25	Q3 2025	$785,000	$283,901	Bidding
LED lighting retrofit	Site	12/28/23	Q1 2027	$604,000	$202,311	Approved
Parking lot resurfacing	Interior	12/12/23	Q1 2026	$789,000	$344,830	Bidding
Exterior paint	Building	08/18/25	Q1 2027	$176,000	$171,288	Approved
Exterior paint	Energy	06/19/24	Q1 2026	$685,000	$705,303	Complete
Exterior paint	Energy	03/16/26	Q4 2027	$439,000	$115,579	Approved
Sewer line repair	Interior	05/17/23	Q2 2025	$111,000	$95,033	Complete
Unit interior upgrades	Interior	07/25/24	Q1 2026	$591,000	$52,500	Deferred
Fence replacement	Interior	12/23/23	Q4 2026	$292,000	$19,074	Complete
Water heater replacement	Interior	05/18/25	Q2 2025	$640,000	$38,432	Deferred
HVAC replacement	Building	08/06/26	Q2 2026	$643,000	$421,302	Bidding
Elevator modernization	Life Safety	08/24/23	Q1 2025	$313,000	$57,140	Complete
Amenity renovation	Energy	08/22/23	Q4 2027	$714,000	$463,587	Complete
Security camera upgrade	Energy	08/12/25	Q1 2025	$551,000	$3,059	Deferred
Unit interior upgrades	Energy	08/10/26	Q2 2027	$685,000	$13,443	In progress
Water heater replacement	Site	02/07/25	Q4 2027	$529,000	$300,831	Complete
Amenity renovation	Building	08/11/26	Q3 2026	$898,000	$12,851	Complete
Exterior paint	Interior	01/06/25	Q2 2027	$735,000	$641,465	In progress
Parking lot resurfacing	Site	08/09/25	Q3 2027	$493,000	$126,548	Approved
LED lighting retrofit	Building	12/13/26	Q1 2026	$601,000	$444,962	In progress
Storefront glazing	Life Safety	10/21/24	Q1 2025	$167,000	$55,925	In progress
Fire alarm panel upgrade	Building	10/26/25	Q4 2027	$29,000	$28,290	In progress
Lobby renovation	Interior	08/10/26	Q3 2027	$878,000	$494,705	Approved
Water heater replacement	Site	09/26/24	Q3 2027	$284,000	$203,018	Complete
ADA compliance	Interior	08/20/25	Q3 2027	$458,000	$448,680	Deferred
Exterior paint	Building	01/14/25	Q4 2027	$659,000	$503,677	In progress

Report generated 08/16/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $69,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 7 years ago and are operating without deficiency.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 8 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $458,000.

Investment Overview

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Projected levered IRR is 3.4% with an equity multiple of 1.25x over the hold period. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Floor plates are efficient and column-spacing supports open and private-office layouts.

Distributions to investors for the quarter were paid at an annualized rate of 6.9% on contributed capital. The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Weighted average lease term remaining is 4 years and in-place rents average $48 per square foot, full service gross. Projected levered IRR is 7.0% with an equity multiple of 1.20x over the hold period. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Deferred Maintenance

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 8 years ago and are operating without deficiency.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $285,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Risk Considerations

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The building features a renovated lobby, structured parking at a ratio of 12 per 1,000 square feet, and a tenant lounge with fitness center. Projected levered IRR is 12.6% with an equity multiple of 1.32x over the hold period. Floor plates are efficient and column-spacing supports open and private-office layouts. The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant.

Floor plates are efficient and column-spacing supports open and private-office layouts. Distributions to investors for the quarter were paid at an annualized rate of 3.4% on contributed capital. Weighted average lease term remaining is 11 years and in-place rents average $48 per square foot, full service gross. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Projected levered IRR is 12.5% with an equity multiple of 1.30x over the hold period.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $408,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months. Elevators were last modernized 4 years ago and are operating without deficiency.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $465,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Risk Considerations

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Lobby renovation	Site	10/14/25	Q3 2025	$134,000	$113,500	Deferred
LED lighting retrofit	Life Safety	10/30/25	Q2 2025	$629,000	$124,646	Bidding
Roof replacement - Bldg B	Energy	11/28/23	Q2 2025	$461,000	$468,651	Bidding
Fire alarm panel upgrade	Building	08/29/24	Q3 2027	$325,000	$65,032	In progress
Landscape / irrigation	Building	08/21/24	Q1 2025	$591,000	$235,174	Complete
Sewer line repair	Building	04/10/26	Q3 2026	$429,000	$444,388	Complete
Roof replacement - Bldg C	Building	07/19/26	Q1 2026	$120,000	$73,172	Deferred
Roof replacement - Bldg A	Interior	07/15/25	Q2 2025	$108,000	$49,780	Bidding
Fence replacement	Energy	01/18/25	Q4 2026	$227,000	$134,887	Approved
Exterior paint	Site	08/15/23	Q3 2026	$106,000	$15,131	Deferred
Water heater replacement	Site	11/15/26	Q2 2026	$756,000	$493,141	Complete
Amenity renovation	Site	07/02/25	Q4 2027	$664,000	$615,241	In progress
Signage / monument	Life Safety	03/27/24	Q1 2027	$839,000	$34,742	In progress
Water heater replacement	Energy	12/30/26	Q4 2025	$676,000	$677,121	Deferred
Fire alarm panel upgrade	Interior	07/10/26	Q4 2027	$493,000	$228,765	In progress
Door hardware	Building	09/12/26	Q2 2026	$463,000	$190,710	Complete
Elevator modernization	Site	05/17/24	Q3 2026	$386,000	$48,119	Complete
Storefront glazing	Energy	06/23/23	Q3 2025	$229,000	$165,495	In progress
Parking lot resurfacing	Energy	02/01/24	Q3 2026	$437,000	$339,368	In progress
ADA compliance	Energy	08/06/24	Q1 2025	$56,000	$24,842	Complete
ADA compliance	Life Safety	07/28/26	Q4 2025	$271,000	$185,097	In progress
Exterior paint	Interior	03/18/24	Q2 2027	$815,000	$413,915	Approved
Pool resurfacing	Interior	07/12/23	Q2 2025	$525,000	$402,891	Complete
Amenity renovation	Interior	03/10/24	Q2 2026	$133,000	$82,711	Approved
Storefront glazing	Interior	01/05/23	Q4 2026	$24,000	$6,882	Bidding
Sewer line repair	Life Safety	04/14/23	Q4 2027	$818,000	$570,456	Deferred
Fire alarm panel upgrade	Site	08/28/25	Q2 2026	$211,000	$17,477	Deferred
Storefront glazing	Interior	11/13/25	Q1 2027	$417,000	$408,424	Deferred
Landscape / irrigation	Life Safety	09/24/25	Q4 2027	$678,000	$264,655	Complete
Door hardware	Interior	12/17/25	Q4 2026	$844,000	$56,553	Complete
Parking lot resurfacing	Building	08/22/23	Q1 2025	$249,000	$4,770	Deferred
Lobby renovation	Life Safety	12/06/26	Q2 2025	$163,000	$147,758	Complete
LED lighting retrofit	Life Safety	03/08/24	Q4 2026	$252,000	$47,697	Deferred
Unit interior upgrades	Energy	10/26/26	Q1 2025	$887,000	$264,359	Approved
ADA compliance	Interior	09/05/25	Q3 2025	$153,000	$103,019	In progress
Pool resurfacing	Life Safety	02/11/25	Q4 2026	$572,000	$579,974	Approved
Door hardware	Interior	04/24/26	Q2 2026	$833,000	$860,729	In progress
Fence replacement	Life Safety	12/17/23	Q3 2027	$365,000	$342,517	Deferred
Roof replacement - Bldg A	Site	03/30/24	Q3 2026	$358,000	$252,396	In progress
Fire alarm panel upgrade	Energy	06/26/23	Q2 2025	$470,000	$305,058	Approved

Report generated 08/16/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Elevators were last modernized 8 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $53,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months.

Elevators were last modernized 5 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $345,000.

Risk Considerations

Projected levered IRR is 5.5% with an equity multiple of 1.8x over the hold period. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Distributions to investors for the quarter were paid at an annualized rate of 3.1% on contributed capital. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Floor plates are efficient and column-spacing supports open and private-office layouts.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $76,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 21 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Investor Distributions

Projected levered IRR is 6.1% with an equity multiple of 1.27x over the hold period. The building features a renovated lobby, structured parking at a ratio of 23 per 1,000 square feet, and a tenant lounge with fitness center. Weighted average lease term remaining is 11 years and in-place rents average $48 per square foot, full service gross. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

The building features a renovated lobby, structured parking at a ratio of 34 per 1,000 square feet, and a tenant lounge with fitness center. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Floor plates are efficient and column-spacing supports open and private-office layouts.

Deferred Maintenance

Elevators were last modernized 3 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $199,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 28 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $104,000.

Risk Considerations

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
ADA compliance	Interior	05/21/24	Q1 2026	$819,000	$25,888	Complete
Pool resurfacing	Energy	02/23/23	Q3 2025	$44,000	$6,206	In progress
Lobby renovation	Site	11/04/23	Q1 2026	$796,000	$741,134	In progress
Signage / monument	Interior	12/06/23	Q4 2027	$420,000	$247,008	In progress
Signage / monument	Building	07/05/23	Q1 2025	$394,000	$223,370	Deferred
ADA compliance	Interior	06/29/23	Q3 2027	$442,000	$144,111	Bidding
Water heater replacement	Life Safety	03/10/24	Q4 2027	$235,000	$695	In progress
Fence replacement	Site	02/20/23	Q2 2026	$826,000	$824,786	Approved
Fire alarm panel upgrade	Site	08/14/25	Q4 2025	$545,000	$164,748	In progress
Unit interior upgrades	Building	11/24/26	Q3 2026	$242,000	$111,375	Approved
Landscape / irrigation	Site	05/04/26	Q2 2027	$654,000	$442,713	In progress
Elevator modernization	Building	12/21/25	Q2 2026	$642,000	$359,131	Approved
Unit interior upgrades	Building	12/14/24	Q1 2027	$112,000	$50,616	In progress
Exterior paint	Energy	01/31/24	Q3 2025	$464,000	$79,288	Deferred
Landscape / irrigation	Building	04/19/26	Q4 2026	$338,000	$176,212	In progress
Exterior paint	Building	02/07/25	Q1 2025	$538,000	$433,760	Bidding
Door hardware	Interior	09/10/25	Q3 2027	$112,000	$82,438	Complete
Amenity renovation	Energy	03/03/25	Q2 2025	$900,000	$112,232	Bidding
Unit interior upgrades	Site	08/28/24	Q3 2026	$888,000	$541,663	Approved
Unit interior upgrades	Energy	07/22/26	Q1 2025	$50,000	$25,501	Bidding
Fire alarm panel upgrade	Interior	07/01/24	Q3 2025	$721,000	$497,652	Approved
Exterior paint	Building	10/24/25	Q2 2027	$239,000	$127,844	Bidding
Storefront glazing	Life Safety	06/02/23	Q2 2027	$251,000	$256,935	Deferred
Pool resurfacing	Building	04/04/23	Q1 2027	$151,000	$111,509	Approved
Fence replacement	Site	01/19/24	Q1 2026	$764,000	$513,534	Complete
Parking lot resurfacing	Energy	07/11/25	Q3 2027	$403,000	$145,161	Approved
Door hardware	Interior	08/02/24	Q2 2027	$893,000	$565,888	Approved
Door hardware	Energy	07/23/24	Q4 2026	$403,000	$314,044	Complete
Roof replacement - Bldg C	Energy	01/28/25	Q3 2025	$502,000	$299,003	Approved
HVAC replacement	Building	09/28/24	Q1 2027	$338,000	$128,024	Complete
Lobby renovation	Interior	02/22/25	Q3 2026	$323,000	$75,278	In progress
Unit interior upgrades	Building	02/20/24	Q3 2025	$71,000	$61,426	Deferred
Landscape / irrigation	Interior	04/11/23	Q3 2025	$589,000	$586,621	Approved
HVAC replacement	Interior	04/25/25	Q4 2027	$345,000	$312,228	Deferred
ADA compliance	Energy	04/25/26	Q2 2025	$896,000	$926,025	Complete
Parking lot resurfacing	Interior	04/12/24	Q2 2026	$543,000	$341,402	In progress
Fence replacement	Building	12/09/25	Q2 2026	$628,000	$322,395	Approved
Storefront glazing	Life Safety	09/10/25	Q1 2027	$474,000	$15,397	In progress
Roof replacement - Bldg B	Building	07/14/23	Q4 2026	$195,000	$106,251	Deferred
Parking lot resurfacing	Site	01/25/25	Q3 2027	$576,000	$13,726	In progress
ADA compliance	Building	01/25/23	Q2 2025	$496,000	$491,774	Approved

Report generated 08/16/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Summary and Notes

Valuation Discussion

Effective gross income for the trailing period was $364,000, representing a 2.5% increase over the prior year. Net operating income is projected to grow at a compound annual rate of 7.3% over the hold period. Management fees are calculated at 5.4% of collected revenue and are included in operating expenses. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Floor plates are efficient and column-spacing supports open and private-office layouts. A reserve for replacements of $250 per unit has been underwritten in the cash flow below net operating income.

Weighted average lease term remaining is 12 years and in-place rents average $48 per square foot, full service gross. The going-in capitalization rate of 5.57% reflects the in-place income and the stabilized occupancy assumption. Debt service coverage ratio was 7.75x on a trailing basis against a covenant minimum of 1.20x. A reserve for replacements of $250 per unit has been underwritten in the cash flow below net operating income.

Management Commentary

Marketing efforts include digital listings, signage, broker outreach and a resident referral program. Collections for the period were 96.2% of billed charges, with bad debt of 4.2% of gross potential income. Preventive maintenance schedules for HVAC, elevators and life-safety systems were completed on time during the period. On-site staffing consists of a property manager, assistant manager, maintenance supervisor and 45 additional team members. Weighted average lease term remaining is 4 years and in-place rents average $48 per square foot, full service gross. Service requests are tracked through a work-order system with an average completion time of 29 hours.

The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. The manager completes a monthly walk of the property and submits a variance report to the owner by the 18th business day. Weighted average lease term remaining is 5 years and in-place rents average $48 per square foot, full service gross. The building features a renovated lobby, structured parking at a ratio of 25 per 1,000 square feet, and a tenant lounge with fitness center. Floor plates are efficient and column-spacing supports open and private-office layouts. On-site staffing consists of a property manager, assistant manager, maintenance supervisor and 41 additional team members.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only