PHASE I ENVIRONMENTAL SITE ASSESSMENT

Sterling Student Living | Omaha, NE

Site	Sterling Student Living
Address	305 Airport Parkway, Omaha, NE 36356
Prepared For	Beacon Hollow Investors
Report Date	March 4, 2020
Standard	ASTM E1527-21

Access and Utilities

The site contains approximately 36.36 acres and is generally level with frontage along Airport Parkway. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

The site contains approximately 5.5 acres and is generally level with frontage along Airport Parkway. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 43 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Records Review

Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. A former dry cleaner located 8 blocks to the north is listed as a closed case and is not expected to impact the site.

Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No recognized environmental conditions (RECs) were identified in connection with the subject property. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site.

Topography and Flood Zone

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 4 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Access to the site is provided by 29 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 41.41 acres and is generally level with frontage along Airport Parkway. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Historical Use

A former dry cleaner located 6 blocks to the north is listed as a closed case and is not expected to impact the site. No recognized environmental conditions (RECs) were identified in connection with the subject property. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. A former dry cleaner located 3 blocks to the north is listed as a closed case and is not expected to impact the site. Vapor encroachment screening did not identify a condition requiring further evaluation. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Access and Utilities

The site contains approximately 35.35 acres and is generally level with frontage along Airport Parkway. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 25 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 21.21 acres and is generally level with frontage along Airport Parkway. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 21 curb cuts and the property is served by municipal water and sanitary sewer.

Historical Use

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. A former dry cleaner located 6 blocks to the north is listed as a closed case and is not expected to impact the site. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Vapor encroachment screening did not identify a condition requiring further evaluation.

Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 9 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

Topography and Flood Zone

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 41 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 45.45 acres and is generally level with frontage along Airport Parkway.

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 46 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 13.13 acres and is generally level with frontage along Airport Parkway. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Site Reconnaissance

Historical sources indicate the site was previously used for agricultural and light commercial purposes. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property. Vapor encroachment screening did not identify a condition requiring further evaluation. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No recognized environmental conditions (RECs) were identified in connection with the subject property.

Access and Utilities

Access to the site is provided by 48 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 26.26 acres and is generally level with frontage along Airport Parkway. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Regulatory Database Search Results

Database	Search Radius (mi)	Sites Within Radius	Subject Property?	Further Evaluation
NPL (Superfund)	0.25	0	No	None
CERCLIS / SEMS	0.5	4	No	Reviewed - no action
RCRA - Generators	0.25	0	No	None
RCRA - TSD	0.5	2	No	None
LUST	1.0	7	No	None
UST	0.25	2	No	None
State Hazardous Waste Sites	1.0	1	No	Reviewed - no action
Brownfields	0.25	0	No	None
Engineering Controls	0.5	0	No	None
Institutional Controls	0.5	0	No	Reviewed - no action
ERNS	0.25	7	No	None
Drycleaner Facilities	0.25	1	No	None
Solid Waste Landfills	1.0	7	No	None
Voluntary Cleanup	0.25	0	No	None
Historical Auto Stations	0.5	0	No	None
NPL (Superfund)	0.25	2	No	None
CERCLIS / SEMS	0.5	0	No	Reviewed - no action
RCRA - Generators	0.25	0	No	None
RCRA - TSD	1.0	0	No	Reviewed - no action
LUST	0.5	1	No	Reviewed - no action
UST	0.25	2	No	Reviewed - no action
State Hazardous Waste Sites	0.25	4	No	None
Brownfields	0.5	7	No	None
Engineering Controls	0.5	0	No	None
Institutional Controls	0.5	2	No	None
ERNS	1.0	7	No	None
Drycleaner Facilities	0.5	0	No	Reviewed - no action
Solid Waste Landfills	0.25	4	No	Reviewed - no action
Voluntary Cleanup	0.5	7	No	Reviewed - no action
Historical Auto Stations	0.25	2	No	None

Report generated 03/04/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Site Reconnaissance

Vapor encroachment screening did not identify a condition requiring further evaluation. No recognized environmental conditions (RECs) were identified in connection with the subject property. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

Historical Use

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site. Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Historical Use

A former dry cleaner located 5 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No recognized environmental conditions (RECs) were identified in connection with the subject property. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

A former dry cleaner located 9 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Site Description

Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 41 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 12 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 12.12 acres and is generally level with frontage along Airport Parkway. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Records Review

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A former dry cleaner located 3 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

Topography and Flood Zone

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 40 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 48.48 acres and is generally level with frontage along Airport Parkway.

Access to the site is provided by 23 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 14.14 acres and is generally level with frontage along Airport Parkway. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Findings and Opinions

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No recognized environmental conditions (RECs) were identified in connection with the subject property. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site.

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation. No recognized environmental conditions (RECs) were identified in connection with the subject property.

Topography and Flood Zone

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 27.27 acres and is generally level with frontage along Airport Parkway. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Access to the site is provided by 26 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 23 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Regulatory Database Search Results

Database	Search Radius (mi)	Sites Within Radius	Subject Property?	Further Evaluation
NPL (Superfund)	0.5	0	No	None
CERCLIS / SEMS	1.0	7	No	None
RCRA - Generators	0.5	1	No	None
RCRA - TSD	0.25	2	No	Reviewed - no action
LUST	1.0	7	No	Reviewed - no action
UST	1.0	0	No	None
State Hazardous Waste Sites	0.5	1	No	None
Brownfields	0.25	0	No	Reviewed - no action
Engineering Controls	0.25	0	No	None
Institutional Controls	0.25	0	No	None
ERNS	0.5	1	No	None
Drycleaner Facilities	1.0	1	No	None
Solid Waste Landfills	1.0	1	No	None
Voluntary Cleanup	0.5	0	No	None
Historical Auto Stations	0.5	7	No	Reviewed - no action
NPL (Superfund)	0.25	2	No	None
CERCLIS / SEMS	0.25	0	No	None
RCRA - Generators	1.0	1	No	None
RCRA - TSD	0.5	4	No	Reviewed - no action
LUST	0.5	7	No	None
UST	1.0	2	No	Reviewed - no action
State Hazardous Waste Sites	0.25	1	No	None
Brownfields	0.25	7	No	None
Engineering Controls	0.25	0	No	None
Institutional Controls	1.0	0	No	None
ERNS	0.25	4	No	None
Drycleaner Facilities	1.0	2	No	None
Solid Waste Landfills	1.0	4	No	Reviewed - no action
Voluntary Cleanup	1.0	0	No	None
Historical Auto Stations	0.25	1	No	None

Report generated 03/04/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions

Historical sources indicate the site was previously used for agricultural and light commercial purposes. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property. Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site.

Findings and Opinions

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

A former dry cleaner located 1 blocks to the north is listed as a closed case and is not expected to impact the site. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

Records Review

No recognized environmental conditions (RECs) were identified in connection with the subject property. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site.

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. A former dry cleaner located 6 blocks to the north is listed as a closed case and is not expected to impact the site. No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Topography and Flood Zone

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 46.46 acres and is generally level with frontage along Airport Parkway. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 4 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 32.32 acres and is generally level with frontage along Airport Parkway. Access to the site is provided by 36 curb cuts and the property is served by municipal water and sanitary sewer.

Records Review

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation.

Access and Utilities

Access to the site is provided by 36 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 22.22 acres and is generally level with frontage along Airport Parkway.

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 35 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 32.32 acres and is generally level with frontage along Airport Parkway.

Site Reconnaissance

No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 9 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation.

A former dry cleaner located 8 blocks to the north is listed as a closed case and is not expected to impact the site. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

Topography and Flood Zone

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 42.42 acres and is generally level with frontage along Airport Parkway. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 41 curb cuts and the property is served by municipal water and sanitary sewer.

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 48 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Findings and Opinions

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Regulatory Database Search Results

Database	Search Radius (mi)	Sites Within Radius	Subject Property?	Further Evaluation
NPL (Superfund)	0.25	0	No	None
CERCLIS / SEMS	1.0	1	No	None
RCRA - Generators	1.0	1	No	None
RCRA - TSD	0.5	7	No	Reviewed - no action
LUST	0.25	0	No	None
UST	1.0	1	No	None
State Hazardous Waste Sites	0.25	0	No	Reviewed - no action
Brownfields	1.0	2	No	None
Engineering Controls	0.25	4	No	None
Institutional Controls	0.25	0	No	None
ERNS	0.5	2	No	None
Drycleaner Facilities	0.5	2	No	None
Solid Waste Landfills	0.5	1	No	None
Voluntary Cleanup	0.25	0	No	None
Historical Auto Stations	0.25	0	No	None
NPL (Superfund)	0.25	0	No	None
CERCLIS / SEMS	1.0	0	No	Reviewed - no action
RCRA - Generators	1.0	2	No	None
RCRA - TSD	0.25	0	No	None
LUST	0.25	4	No	None
UST	0.5	0	No	Reviewed - no action
State Hazardous Waste Sites	0.25	0	No	None
Brownfields	0.5	7	No	None
Engineering Controls	0.5	7	No	None
Institutional Controls	0.5	2	No	Reviewed - no action
ERNS	0.25	2	No	None
Drycleaner Facilities	1.0	2	No	None
Solid Waste Landfills	0.5	4	No	Reviewed - no action
Voluntary Cleanup	1.0	4	No	None
Historical Auto Stations	1.0	2	No	None

Report generated 03/04/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only