PROPERTY CONDITION ASSESSMENT

Alder Office Park | Madison, WI

Property	Alder Office Park
Address	1218 Railroad Boulevard, Madison, WI 47169
Site Visit Date	June 11, 2019
Client	Beacon Hollow Investors
Immediate Repairs	$376,000

Construction Details

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Weighted average lease term remaining is 10 years and in-place rents average $31 per square foot, full service gross.

Common area interiors have been refreshed within the last 8 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Floor plates are efficient and column-spacing supports open and private-office layouts. The building features a renovated lobby, structured parking at a ratio of 39 per 1,000 square feet, and a tenant lounge with fitness center.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $142,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 7 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $474,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Building Systems

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Weighted average lease term remaining is 5 years and in-place rents average $31 per square foot, full service gross. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant.

Weighted average lease term remaining is 7 years and in-place rents average $31 per square foot, full service gross. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Floor plates are efficient and column-spacing supports open and private-office layouts. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant.

Observed Conditions

Elevators were last modernized 9 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 48 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $143,000.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

Common area interiors have been refreshed within the last 4 years and are in average to good condition. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Floor plates are efficient and column-spacing supports open and private-office layouts. Alder Office Park was originally constructed in 1986 and consists of 57,000 SF in a building of 38 stories. Weighted average lease term remaining is 4 years and in-place rents average $31 per square foot, full service gross.

Weighted average lease term remaining is 12 years and in-place rents average $31 per square foot, full service gross. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 8-year membrane system with an estimated remaining useful life of 4 years. The building features a renovated lobby, structured parking at a ratio of 25 per 1,000 square feet, and a tenant lounge with fitness center. Alder Office Park was originally constructed in 1986 and consists of 57,000 SF in a building of 11 stories.

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $441,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 47 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $339,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Improvements Description

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Alder Office Park was originally constructed in 1986 and consists of 57,000 SF in a building of 10 stories. Floor plates are efficient and column-spacing supports open and private-office layouts. The building features a renovated lobby, structured parking at a ratio of 32 per 1,000 square feet, and a tenant lounge with fitness center. Common area interiors have been refreshed within the last 4 years and are in average to good condition.

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Mechanical systems include rooftop package units and central plant equipment of varying age.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $434,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 11 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 39 months.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 11 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Building Systems

Mechanical systems include rooftop package units and central plant equipment of varying age. Alder Office Park was originally constructed in 1986 and consists of 57,000 SF in a building of 33 stories. Weighted average lease term remaining is 11 years and in-place rents average $31 per square foot, full service gross. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 10-year membrane system with an estimated remaining useful life of 6 years.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	2	10	8	Good	$35,000	$74,000
Paving	14	30	16	Good	$37,000	$209,000
HVAC	10	11	1	Poor	$22,000	$96,000
Plumbing	25	29	4	Fair	$15,000	$92,000
Electrical	3	21	18	Fair	$25,000	$44,000
Elevators	14	15	1	Poor	$34,000	$86,000
Fire/Life Safety	15	23	8	Fair	$5,000	$93,000
Windows	26	36	10	Good	$21,000	$116,000
Siding/Facade	7	34	27	Poor	$40,000	$41,000
Flooring	16	18	2	Fair	$9,000	$98,000
Appliances	8	26	18	Fair	$29,000	$247,000
Landscaping	18	25	7	Good	$17,000	$262,000
Pool/Amenity	4	16	12	Fair	$0	$265,000
Signage	6	27	21	Good	$24,000	$158,000
Fencing	7	34	27	Fair	$33,000	$102,000
Roof (2)	20	40	20	Good	$27,000	$33,000
Paving (2)	14	27	13	Fair	$25,000	$24,000
HVAC (2)	11	11	0	Fair	$38,000	$189,000
Plumbing (2)	7	20	13	Good	$16,000	$170,000
Electrical (2)	11	26	15	Fair	$29,000	$86,000
Elevators (2)	6	13	7	Poor	$21,000	$129,000
Fire/Life Safety (2)	12	28	16	Fair	$36,000	$201,000
Windows (2)	27	36	9	Fair	$18,000	$243,000
Siding/Facade (2)	33	40	7	Fair	$33,000	$57,000
Flooring (2)	9	33	24	Fair	$38,000	$157,000
Appliances (2)	27	29	2	Fair	$3,000	$246,000
Landscaping (2)	11	19	8	Good	$27,000	$23,000
Pool/Amenity (2)	4	20	16	Fair	$25,000	$28,000
Signage (2)	14	39	25	Fair	$12,000	$277,000
Fencing (2)	13	20	7	Fair	$4,000	$4,000

Report generated 06/11/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Stair treads	Common	Worn / loose	Replace treads	Immediate	$31,000
Fire extinguishers	Common	Expired tags	Service	Immediate	$5,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 1	$18,500
Sidewalk	Bldg A	Trip hazards	Grind / replace	Year 2-5	$12,500
Handrail	Bldg A	Loose	Secure	Year 2-5	$7,000
Fire extinguishers	Roof	Expired tags	Service	Year 1	$86,000
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 2-5	$30,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 1	$20,500
Sidewalk	Roof	Trip hazards	Grind / replace	Immediate	$85,500
Handrail	Roof	Loose	Secure	Reserve	$70,500
Sprinkler heads	Mechanical	Painted heads	Replace	Reserve	$86,500
Sprinkler heads	Bldg A	Painted heads	Replace	Year 2-5	$11,500
Fire extinguishers	Bldg B	Expired tags	Service	Reserve	$50,500
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Year 2-5	$21,000
Sprinkler heads	Bldg B	Painted heads	Replace	Reserve	$67,000
Water heater	Mechanical	Corrosion	Replace	Immediate	$26,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 1	$63,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Immediate	$3,500
Sidewalk	Bldg A	Trip hazards	Grind / replace	Year 2-5	$74,500
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Year 1	$63,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 1	$71,000
Sprinkler heads	Common	Painted heads	Replace	Immediate	$42,000
Water heater	Site	Corrosion	Replace	Immediate	$75,000
Roof membrane	Bldg B	Ponding / seams	Re-seal and repair	Immediate	$77,000
Stair treads	Site	Worn / loose	Replace treads	Reserve	$63,500
Water heater	Roof	Corrosion	Replace	Immediate	$11,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Immediate	$36,000
Window sealant	Common	Failed	Re-caulk	Immediate	$33,500
Handrail	Site	Loose	Secure	Reserve	$73,500
HVAC unit	Site	Beyond useful life	Replace RTU	Year 1	$85,000
Roof membrane	Common	Ponding / seams	Re-seal and repair	Reserve	$39,000
Fire extinguishers	Site	Expired tags	Service	Reserve	$56,000
Handrail	Common	Loose	Secure	Year 2-5	$69,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Year 1	$24,000
Handrail	Roof	Loose	Secure	Reserve	$23,500
Stair treads	Bldg B	Worn / loose	Replace treads	Immediate	$26,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 1	$4,000
Water heater	Mechanical	Corrosion	Replace	Reserve	$28,000
Fire extinguishers	Roof	Expired tags	Service	Immediate	$55,500
Window sealant	Bldg B	Failed	Re-caulk	Reserve	$68,500
Asphalt paving	Common	Alligator cracking	Mill and overlay	Year 2-5	$37,500
Fire extinguishers	Bldg B	Expired tags	Service	Year 2-5	$89,000

Report generated 06/11/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 7 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $257,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 30 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $156,000.

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $192,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 30 months.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $248,000. Elevators were last modernized 6 years ago and are operating without deficiency.

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 6 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $171,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 11 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $390,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

The building features a renovated lobby, structured parking at a ratio of 10 per 1,000 square feet, and a tenant lounge with fitness center. Floor plates are efficient and column-spacing supports open and private-office layouts. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 30-year membrane system with an estimated remaining useful life of 12 years.

Floor plates are efficient and column-spacing supports open and private-office layouts. Common area interiors have been refreshed within the last 5 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Mechanical systems include rooftop package units and central plant equipment of varying age.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $457,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 40 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Improvements Description

The roof is a 6-year membrane system with an estimated remaining useful life of 4 years. Weighted average lease term remaining is 9 years and in-place rents average $31 per square foot, full service gross. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Mechanical systems include rooftop package units and central plant equipment of varying age. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 19-year membrane system with an estimated remaining useful life of 5 years. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 20 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $404,000. Elevators were last modernized 4 years ago and are operating without deficiency.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $157,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 34 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Building Systems

Common area interiors have been refreshed within the last 6 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. The building features a renovated lobby, structured parking at a ratio of 3 per 1,000 square feet, and a tenant lounge with fitness center. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 14-year membrane system with an estimated remaining useful life of 6 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The building features a renovated lobby, structured parking at a ratio of 35 per 1,000 square feet, and a tenant lounge with fitness center.

Deferred Maintenance

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	6	37	31	Poor	$0	$226,000
Paving	14	15	1	Poor	$21,000	$83,000
HVAC	14	21	7	Poor	$35,000	$111,000
Plumbing	6	22	16	Poor	$31,000	$212,000
Electrical	5	15	10	Poor	$27,000	$258,000
Elevators	5	12	7	Poor	$22,000	$43,000
Fire/Life Safety	19	40	21	Fair	$8,000	$185,000
Windows	9	20	11	Poor	$7,000	$68,000
Siding/Facade	1	10	9	Fair	$4,000	$96,000
Flooring	16	19	3	Fair	$4,000	$115,000
Appliances	32	40	8	Fair	$38,000	$130,000
Landscaping	10	19	9	Fair	$10,000	$30,000
Pool/Amenity	19	22	3	Fair	$27,000	$163,000
Signage	25	29	4	Fair	$33,000	$57,000
Fencing	19	22	3	Fair	$32,000	$43,000
Roof (2)	11	39	28	Good	$26,000	$180,000
Paving (2)	2	35	33	Fair	$17,000	$123,000
HVAC (2)	22	38	16	Poor	$1,000	$264,000
Plumbing (2)	3	10	7	Poor	$39,000	$103,000
Electrical (2)	11	23	12	Good	$2,000	$166,000
Elevators (2)	6	23	17	Fair	$26,000	$7,000
Fire/Life Safety (2)	3	30	27	Poor	$12,000	$166,000
Windows (2)	28	33	5	Poor	$39,000	$157,000
Siding/Facade (2)	6	17	11	Good	$20,000	$42,000
Flooring (2)	1	10	9	Fair	$37,000	$21,000
Appliances (2)	28	30	2	Poor	$34,000	$180,000
Landscaping (2)	3	19	16	Fair	$29,000	$40,000
Pool/Amenity (2)	35	37	2	Good	$23,000	$226,000
Signage (2)	7	16	9	Fair	$32,000	$189,000
Fencing (2)	23	39	16	Fair	$8,000	$143,000

Report generated 06/11/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Year 1	$80,500
Sprinkler heads	Site	Painted heads	Replace	Immediate	$62,500
Stair treads	Bldg A	Worn / loose	Replace treads	Year 1	$37,000
Sidewalk	Roof	Trip hazards	Grind / replace	Year 2-5	$8,500
Water heater	Roof	Corrosion	Replace	Reserve	$25,000
Stair treads	Bldg B	Worn / loose	Replace treads	Year 1	$86,000
HVAC unit	Common	Beyond useful life	Replace RTU	Year 1	$77,000
Stair treads	Bldg A	Worn / loose	Replace treads	Year 1	$61,000
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Immediate	$86,500
Dumpster enclosure	Common	Damaged gate	Repair	Reserve	$14,500
Sidewalk	Site	Trip hazards	Grind / replace	Year 2-5	$45,500
Fire extinguishers	Roof	Expired tags	Service	Reserve	$52,500
Roof membrane	Common	Ponding / seams	Re-seal and repair	Year 2-5	$40,500
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$34,500
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Reserve	$30,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 2-5	$81,500
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 1	$67,000
HVAC unit	Common	Beyond useful life	Replace RTU	Reserve	$39,000
Water heater	Common	Corrosion	Replace	Year 2-5	$8,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Reserve	$29,000
Window sealant	Roof	Failed	Re-caulk	Year 1	$48,000
Sprinkler heads	Bldg A	Painted heads	Replace	Year 1	$7,000
Sidewalk	Site	Trip hazards	Grind / replace	Year 1	$15,000
Sprinkler heads	Common	Painted heads	Replace	Year 1	$12,000
Fire extinguishers	Site	Expired tags	Service	Year 2-5	$48,500
Fire extinguishers	Roof	Expired tags	Service	Year 2-5	$13,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Immediate	$6,000
Dumpster enclosure	Bldg A	Damaged gate	Repair	Immediate	$65,000
Roof membrane	Common	Ponding / seams	Re-seal and repair	Immediate	$38,500
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Immediate	$89,500
HVAC unit	Common	Beyond useful life	Replace RTU	Year 2-5	$89,500
Sidewalk	Mechanical	Trip hazards	Grind / replace	Year 2-5	$61,000
Dumpster enclosure	Mechanical	Damaged gate	Repair	Reserve	$53,000
Fire extinguishers	Roof	Expired tags	Service	Reserve	$73,000
Window sealant	Bldg B	Failed	Re-caulk	Year 1	$75,500
Fire extinguishers	Bldg A	Expired tags	Service	Reserve	$21,000
Water heater	Site	Corrosion	Replace	Year 1	$26,500
HVAC unit	Common	Beyond useful life	Replace RTU	Reserve	$59,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Immediate	$71,000
Sidewalk	Mechanical	Trip hazards	Grind / replace	Year 2-5	$82,500

Report generated 06/11/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. Elevators were last modernized 6 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $414,000.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $60,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 11 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 41 months.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 3 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $350,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 9 months.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $179,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months. Elevators were last modernized 5 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $477,000. Elevators were last modernized 4 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

The building features a renovated lobby, structured parking at a ratio of 35 per 1,000 square feet, and a tenant lounge with fitness center. The roof is a 35-year membrane system with an estimated remaining useful life of 9 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Alder Office Park was originally constructed in 1986 and consists of 57,000 SF in a building of 25 stories.

The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 20-year membrane system with an estimated remaining useful life of 9 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Floor plates are efficient and column-spacing supports open and private-office layouts.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 23 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 12 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $382,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 6 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 38 months.

Improvements Description

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Floor plates are efficient and column-spacing supports open and private-office layouts. Mechanical systems include rooftop package units and central plant equipment of varying age.

Weighted average lease term remaining is 11 years and in-place rents average $31 per square foot, full service gross. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Alder Office Park was originally constructed in 1986 and consists of 57,000 SF in a building of 22 stories.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $73,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 23 months.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 46 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 6 years ago and are operating without deficiency.

Building Systems

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 44-year membrane system with an estimated remaining useful life of 6 years. The building is served by redundant elevators, a backup generator and a high-efficiency chiller plant. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Mechanical systems include rooftop package units and central plant equipment of varying age.

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The building features a renovated lobby, structured parking at a ratio of 22 per 1,000 square feet, and a tenant lounge with fitness center. Alder Office Park was originally constructed in 1986 and consists of 57,000 SF in a building of 38 stories. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Deferred Maintenance

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Alder Office Park and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on June 6, 2019.

_____

Julia Dixon, PE

Keystone Building Consultants

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only