PROPERTY CONDITION ASSESSMENT

Elmhurst Senior Living | Naperville, IL

Property	Elmhurst Senior Living
Address	6306 Quarry Parkway, Naperville, IL 13180
Site Visit Date	October 21, 2021
Client	Keel & Compass Properties
Immediate Repairs	$299,000

Building Systems

Dining, housekeeping, transportation and activities programming are included in the base fee. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Common area interiors have been refreshed within the last 7 years and are in average to good condition.

Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Dining, housekeeping, transportation and activities programming are included in the base fee. Common area interiors have been refreshed within the last 12 years and are in average to good condition. The roof is a 44-year membrane system with an estimated remaining useful life of 11 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $267,000.

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 6 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months.

Improvements Description

The roof is a 48-year membrane system with an estimated remaining useful life of 3 years. Occupancy stands at 90.0% with an average resident length of stay of 6 years. Mechanical systems include rooftop package units and central plant equipment of varying age. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 23 stories.

Mechanical systems include rooftop package units and central plant equipment of varying age. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 5-year membrane system with an estimated remaining useful life of 3 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Common area interiors have been refreshed within the last 10 years and are in average to good condition. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 9 stories.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $114,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The roof is a 29-year membrane system with an estimated remaining useful life of 8 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Mechanical systems include rooftop package units and central plant equipment of varying age.

Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 11 stories. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Common area interiors have been refreshed within the last 11 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age.

Recommendations

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $33,000. Elevators were last modernized 10 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 11 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $391,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 8 years ago and are operating without deficiency.

Improvements Description

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The community provides assisted living and memory care services under a state-issued license with 4 full-time caregivers per shift. The roof is a 30-year membrane system with an estimated remaining useful life of 4 years. Common area interiors have been refreshed within the last 12 years and are in average to good condition. Dining, housekeeping, transportation and activities programming are included in the base fee. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

Dining, housekeeping, transportation and activities programming are included in the base fee. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care.

Recommendations

Elevators were last modernized 9 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $212,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $47,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Building Systems

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Common area interiors have been refreshed within the last 4 years and are in average to good condition. The roof is a 20-year membrane system with an estimated remaining useful life of 9 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	3	38	35	Fair	$29,000	$178,000
Paving	6	24	18	Poor	$5,000	$57,000
HVAC	22	34	12	Fair	$24,000	$47,000
Plumbing	3	13	10	Poor	$14,000	$270,000
Electrical	17	22	5	Fair	$1,000	$201,000
Elevators	8	17	9	Fair	$15,000	$128,000
Fire/Life Safety	4	27	23	Fair	$39,000	$223,000
Windows	4	28	24	Poor	$23,000	$211,000
Siding/Facade	1	17	16	Fair	$1,000	$23,000
Flooring	12	40	28	Fair	$20,000	$188,000
Appliances	15	25	10	Good	$12,000	$234,000
Landscaping	18	25	7	Fair	$12,000	$180,000
Pool/Amenity	28	40	12	Fair	$2,000	$45,000
Signage	7	16	9	Fair	$31,000	$213,000
Fencing	11	16	5	Good	$35,000	$196,000
Roof (2)	5	16	11	Fair	$17,000	$56,000
Paving (2)	16	35	19	Poor	$29,000	$187,000
HVAC (2)	14	33	19	Good	$38,000	$227,000
Plumbing (2)	15	22	7	Fair	$26,000	$59,000
Electrical (2)	25	26	1	Fair	$14,000	$229,000
Elevators (2)	12	23	11	Fair	$20,000	$149,000
Fire/Life Safety (2)	7	22	15	Poor	$34,000	$179,000
Windows (2)	13	35	22	Good	$15,000	$202,000
Siding/Facade (2)	27	29	2	Poor	$11,000	$259,000
Flooring (2)	17	20	3	Fair	$8,000	$9,000
Appliances (2)	34	34	0	Fair	$9,000	$278,000
Landscaping (2)	3	24	21	Fair	$29,000	$157,000
Pool/Amenity (2)	23	36	13	Poor	$37,000	$167,000
Signage (2)	1	35	34	Poor	$36,000	$157,000
Fencing (2)	4	13	9	Poor	$19,000	$85,000

Report generated 10/21/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Water heater	Mechanical	Corrosion	Replace	Year 1	$8,500
Water heater	Roof	Corrosion	Replace	Year 1	$24,000
Fire extinguishers	Common	Expired tags	Service	Year 1	$32,000
Sprinkler heads	Site	Painted heads	Replace	Year 1	$60,000
HVAC unit	Roof	Beyond useful life	Replace RTU	Year 1	$84,000
Window sealant	Bldg B	Failed	Re-caulk	Year 1	$61,000
Sprinkler heads	Bldg A	Painted heads	Replace	Reserve	$66,000
Dumpster enclosure	Common	Damaged gate	Repair	Year 1	$43,000
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Reserve	$83,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 1	$36,000
Fire extinguishers	Bldg B	Expired tags	Service	Reserve	$64,000
HVAC unit	Roof	Beyond useful life	Replace RTU	Reserve	$72,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Reserve	$25,500
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$45,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Immediate	$83,000
Sidewalk	Common	Trip hazards	Grind / replace	Immediate	$75,000
Water heater	Bldg B	Corrosion	Replace	Year 1	$55,000
Fire extinguishers	Mechanical	Expired tags	Service	Year 1	$25,500
Stair treads	Bldg B	Worn / loose	Replace treads	Immediate	$78,500
Sidewalk	Common	Trip hazards	Grind / replace	Year 1	$44,500
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$57,500
Water heater	Mechanical	Corrosion	Replace	Year 1	$22,000
Stair treads	Bldg A	Worn / loose	Replace treads	Reserve	$36,500
Sprinkler heads	Roof	Painted heads	Replace	Immediate	$29,000
Water heater	Mechanical	Corrosion	Replace	Year 1	$50,000
Water heater	Site	Corrosion	Replace	Year 1	$66,500
Dumpster enclosure	Common	Damaged gate	Repair	Year 2-5	$44,500
Handrail	Roof	Loose	Secure	Immediate	$36,500
Fire extinguishers	Bldg B	Expired tags	Service	Immediate	$85,000
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 1	$13,500
Water heater	Bldg B	Corrosion	Replace	Year 2-5	$72,500
Roof membrane	Common	Ponding / seams	Re-seal and repair	Reserve	$28,500
Sidewalk	Mechanical	Trip hazards	Grind / replace	Reserve	$20,000
Sprinkler heads	Mechanical	Painted heads	Replace	Year 1	$74,500
Dumpster enclosure	Roof	Damaged gate	Repair	Immediate	$67,000
Dumpster enclosure	Bldg A	Damaged gate	Repair	Reserve	$39,500
Sprinkler heads	Mechanical	Painted heads	Replace	Reserve	$76,000
Handrail	Bldg A	Loose	Secure	Reserve	$500
Water heater	Mechanical	Corrosion	Replace	Reserve	$5,500
Sprinkler heads	Bldg A	Painted heads	Replace	Immediate	$24,000

Report generated 10/21/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 6 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $426,000.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 23 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $63,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Deferred Maintenance

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 10 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $128,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 46 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 5 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 10 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $208,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

Common area interiors have been refreshed within the last 12 years and are in average to good condition. The community provides assisted living and memory care services under a state-issued license with 21 full-time caregivers per shift. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 20 stories. Mechanical systems include rooftop package units and central plant equipment of varying age.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Occupancy stands at 90.0% with an average resident length of stay of 5 years. Mechanical systems include rooftop package units and central plant equipment of varying age. The roof is a 43-year membrane system with an estimated remaining useful life of 4 years.

Recommendations

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $264,000.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $239,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency.

Building Systems

The community provides assisted living and memory care services under a state-issued license with 27 full-time caregivers per shift. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 30 stories. Common area interiors have been refreshed within the last 9 years and are in average to good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Dining, housekeeping, transportation and activities programming are included in the base fee. Occupancy stands at 94.5% with an average resident length of stay of 7 years. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 14 stories. The community provides assisted living and memory care services under a state-issued license with 5 full-time caregivers per shift. The roof is a 23-year membrane system with an estimated remaining useful life of 3 years.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $408,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 10 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Elevators were last modernized 11 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 9 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $200,000.

Building Systems

Dining, housekeeping, transportation and activities programming are included in the base fee. Mechanical systems include rooftop package units and central plant equipment of varying age. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 24 stories. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	11	13	2	Good	$0	$105,000
Paving	7	17	10	Good	$29,000	$268,000
HVAC	16	24	8	Good	$13,000	$263,000
Plumbing	1	34	33	Good	$4,000	$78,000
Electrical	7	17	10	Poor	$3,000	$145,000
Elevators	14	27	13	Good	$0	$195,000
Fire/Life Safety	13	13	0	Fair	$26,000	$26,000
Windows	13	14	1	Fair	$30,000	$151,000
Siding/Facade	18	22	4	Fair	$7,000	$127,000
Flooring	20	40	20	Fair	$18,000	$130,000
Appliances	32	35	3	Good	$1,000	$148,000
Landscaping	29	32	3	Fair	$36,000	$136,000
Pool/Amenity	10	13	3	Poor	$21,000	$101,000
Signage	10	22	12	Fair	$10,000	$81,000
Fencing	7	24	17	Fair	$7,000	$29,000
Roof (2)	9	13	4	Fair	$23,000	$126,000
Paving (2)	16	20	4	Fair	$32,000	$162,000
HVAC (2)	4	11	7	Fair	$13,000	$107,000
Plumbing (2)	5	27	22	Fair	$33,000	$71,000
Electrical (2)	18	18	0	Fair	$39,000	$40,000
Elevators (2)	10	13	3	Fair	$16,000	$71,000
Fire/Life Safety (2)	28	36	8	Fair	$18,000	$72,000
Windows (2)	24	35	11	Fair	$29,000	$64,000
Siding/Facade (2)	25	36	11	Poor	$30,000	$258,000
Flooring (2)	37	40	3	Fair	$10,000	$73,000
Appliances (2)	2	12	10	Good	$32,000	$236,000
Landscaping (2)	3	29	26	Fair	$27,000	$11,000
Pool/Amenity (2)	23	32	9	Fair	$16,000	$154,000
Signage (2)	8	37	29	Fair	$18,000	$75,000
Fencing (2)	3	15	12	Fair	$8,000	$202,000

Report generated 10/21/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Sprinkler heads	Roof	Painted heads	Replace	Immediate	$85,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 1	$69,500
Stair treads	Bldg A	Worn / loose	Replace treads	Immediate	$16,000
Asphalt paving	Site	Alligator cracking	Mill and overlay	Year 2-5	$88,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Immediate	$69,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Reserve	$48,500
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 1	$84,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Year 2-5	$44,000
Sprinkler heads	Bldg A	Painted heads	Replace	Year 2-5	$5,000
Handrail	Bldg B	Loose	Secure	Year 2-5	$90,000
Window sealant	Bldg B	Failed	Re-caulk	Reserve	$86,500
Water heater	Bldg A	Corrosion	Replace	Year 2-5	$82,500
Dumpster enclosure	Roof	Damaged gate	Repair	Year 1	$35,500
Sprinkler heads	Bldg B	Painted heads	Replace	Year 2-5	$1,500
Fire extinguishers	Mechanical	Expired tags	Service	Year 1	$20,500
Handrail	Mechanical	Loose	Secure	Immediate	$28,500
Sidewalk	Site	Trip hazards	Grind / replace	Year 1	$38,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 2-5	$85,000
Fire extinguishers	Bldg A	Expired tags	Service	Year 2-5	$41,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Reserve	$72,000
Sprinkler heads	Bldg A	Painted heads	Replace	Immediate	$77,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 1	$72,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Immediate	$8,000
Fire extinguishers	Bldg A	Expired tags	Service	Immediate	$70,000
Window sealant	Site	Failed	Re-caulk	Year 1	$63,000
Dumpster enclosure	Site	Damaged gate	Repair	Year 2-5	$7,000
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Immediate	$46,500
Sprinkler heads	Mechanical	Painted heads	Replace	Year 1	$58,500
Water heater	Common	Corrosion	Replace	Year 2-5	$54,000
Stair treads	Site	Worn / loose	Replace treads	Reserve	$13,500
Asphalt paving	Site	Alligator cracking	Mill and overlay	Immediate	$87,500
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Immediate	$44,500
Fire extinguishers	Mechanical	Expired tags	Service	Year 1	$50,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Reserve	$71,500
Handrail	Site	Loose	Secure	Reserve	$27,000
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Immediate	$8,000
HVAC unit	Roof	Beyond useful life	Replace RTU	Year 1	$65,500
HVAC unit	Site	Beyond useful life	Replace RTU	Year 2-5	$500
Window sealant	Roof	Failed	Re-caulk	Year 1	$38,000
Stair treads	Roof	Worn / loose	Replace treads	Year 2-5	$66,000
Sprinkler heads	Roof	Painted heads	Replace	Immediate	$59,000
Dumpster enclosure	Bldg A	Damaged gate	Repair	Immediate	$39,500
Stair treads	Bldg B	Worn / loose	Replace treads	Year 2-5	$57,000

Report generated 10/21/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $220,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 47 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 35 months. Elevators were last modernized 3 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $346,000. Elevators were last modernized 5 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $340,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Deferred Maintenance

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 6 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $389,000.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 26 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 11 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Occupancy stands at 95.8% with an average resident length of stay of 5 years. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Common area interiors have been refreshed within the last 11 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age.

Common area interiors have been refreshed within the last 6 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 29 stories. The roof is a 39-year membrane system with an estimated remaining useful life of 5 years. Dining, housekeeping, transportation and activities programming are included in the base fee.

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 28 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $434,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Improvements Description

Common area interiors have been refreshed within the last 10 years and are in average to good condition. Dining, housekeeping, transportation and activities programming are included in the base fee. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Mechanical systems include rooftop package units and central plant equipment of varying age.

Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 3 stories. Mechanical systems include rooftop package units and central plant equipment of varying age. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Common area interiors have been refreshed within the last 4 years and are in average to good condition. The roof is a 6-year membrane system with an estimated remaining useful life of 8 years.

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $452,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 7 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 8 years ago and are operating without deficiency.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $234,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 12 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 20 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Construction Details

Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 15 stories. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	11	16	5	Fair	$37,000	$131,000
Paving	8	10	2	Good	$30,000	$215,000
HVAC	3	20	17	Poor	$20,000	$211,000
Plumbing	25	29	4	Fair	$11,000	$247,000
Electrical	2	18	16	Fair	$4,000	$121,000
Elevators	6	23	17	Good	$6,000	$4,000
Fire/Life Safety	13	13	0	Good	$37,000	$91,000
Windows	14	27	13	Fair	$16,000	$163,000
Siding/Facade	6	15	9	Fair	$22,000	$141,000
Flooring	6	12	6	Fair	$16,000	$77,000
Appliances	12	30	18	Fair	$23,000	$233,000
Landscaping	21	32	11	Poor	$10,000	$91,000
Pool/Amenity	10	36	26	Poor	$24,000	$80,000
Signage	37	40	3	Fair	$24,000	$188,000
Fencing	4	10	6	Fair	$15,000	$196,000
Roof (2)	17	30	13	Fair	$5,000	$18,000
Paving (2)	20	20	0	Poor	$32,000	$121,000
HVAC (2)	25	25	0	Fair	$3,000	$150,000
Plumbing (2)	18	36	18	Fair	$7,000	$143,000
Electrical (2)	28	34	6	Poor	$4,000	$252,000
Elevators (2)	2	14	12	Poor	$5,000	$226,000
Fire/Life Safety (2)	33	34	1	Poor	$37,000	$189,000
Windows (2)	16	18	2	Fair	$31,000	$272,000
Siding/Facade (2)	15	35	20	Fair	$33,000	$52,000
Flooring (2)	12	36	24	Poor	$40,000	$60,000
Appliances (2)	7	15	8	Good	$37,000	$260,000
Landscaping (2)	6	13	7	Fair	$34,000	$41,000
Pool/Amenity (2)	17	18	1	Poor	$5,000	$59,000
Signage (2)	28	35	7	Good	$12,000	$279,000
Fencing (2)	2	13	11	Fair	$38,000	$272,000

Report generated 10/21/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 1	$12,500
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Immediate	$68,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Reserve	$85,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Reserve	$34,000
Handrail	Bldg A	Loose	Secure	Year 2-5	$24,500
Sprinkler heads	Bldg A	Painted heads	Replace	Year 1	$32,000
Dumpster enclosure	Site	Damaged gate	Repair	Year 1	$60,500
Window sealant	Bldg B	Failed	Re-caulk	Year 1	$84,500
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Year 1	$20,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 2-5	$58,000
Fire extinguishers	Common	Expired tags	Service	Year 2-5	$28,500
Handrail	Bldg B	Loose	Secure	Year 1	$85,000
Handrail	Mechanical	Loose	Secure	Year 2-5	$40,500
Fire extinguishers	Roof	Expired tags	Service	Reserve	$37,000
Fire extinguishers	Bldg B	Expired tags	Service	Immediate	$42,500
Sprinkler heads	Roof	Painted heads	Replace	Year 1	$82,000
Fire extinguishers	Roof	Expired tags	Service	Year 2-5	$41,000
Handrail	Site	Loose	Secure	Year 1	$85,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Reserve	$87,500
Sprinkler heads	Bldg A	Painted heads	Replace	Reserve	$35,000
Sprinkler heads	Bldg A	Painted heads	Replace	Year 1	$28,000
Sprinkler heads	Common	Painted heads	Replace	Reserve	$53,500
Fire extinguishers	Mechanical	Expired tags	Service	Year 2-5	$25,500
Roof membrane	Common	Ponding / seams	Re-seal and repair	Reserve	$87,500
Sidewalk	Common	Trip hazards	Grind / replace	Immediate	$13,500
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Year 1	$25,500
Window sealant	Mechanical	Failed	Re-caulk	Reserve	$16,500
Window sealant	Bldg A	Failed	Re-caulk	Year 1	$78,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Immediate	$33,000
Asphalt paving	Site	Alligator cracking	Mill and overlay	Year 1	$16,500
HVAC unit	Site	Beyond useful life	Replace RTU	Year 1	$27,500
Dumpster enclosure	Bldg A	Damaged gate	Repair	Year 2-5	$68,000
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Year 1	$47,500
Fire extinguishers	Bldg B	Expired tags	Service	Year 2-5	$59,500
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 2-5	$43,500
HVAC unit	Common	Beyond useful life	Replace RTU	Reserve	$24,000
Window sealant	Mechanical	Failed	Re-caulk	Year 1	$14,000
Water heater	Bldg A	Corrosion	Replace	Immediate	$54,000
Handrail	Common	Loose	Secure	Reserve	$90,000
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$33,000
Sidewalk	Bldg B	Trip hazards	Grind / replace	Immediate	$67,000

Report generated 10/21/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $37,000. Elevators were last modernized 8 years ago and are operating without deficiency.

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 37 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $121,000. Elevators were last modernized 11 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Recommendations

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $91,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 30 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 3 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $406,000. Elevators were last modernized 8 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 47 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Recommendations

Elevators were last modernized 6 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $464,000.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 11 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $166,000.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

Dining, housekeeping, transportation and activities programming are included in the base fee. Mechanical systems include rooftop package units and central plant equipment of varying age. The roof is a 5-year membrane system with an estimated remaining useful life of 4 years. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 22 stories. Occupancy stands at 88.3% with an average resident length of stay of 5 years. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Common area interiors have been refreshed within the last 5 years and are in average to good condition. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 13 stories. Occupancy stands at 94.1% with an average resident length of stay of 4 years. The roof is a 9-year membrane system with an estimated remaining useful life of 10 years.

Deferred Maintenance

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 11 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $363,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 4 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 23 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 3 years ago and are operating without deficiency.

Building Systems

Occupancy stands at 94.0% with an average resident length of stay of 8 years. Common area interiors have been refreshed within the last 5 years and are in average to good condition. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 48 stories. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Mechanical systems include rooftop package units and central plant equipment of varying age.

The roof is a 46-year membrane system with an estimated remaining useful life of 7 years. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Occupancy stands at 90.2% with an average resident length of stay of 7 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 3 stories.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $283,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 19 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 5 years ago and are operating without deficiency.

Improvements Description

The community provides assisted living and memory care services under a state-issued license with 38 full-time caregivers per shift. Occupancy stands at 90.9% with an average resident length of stay of 8 years. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. The roof is a 42-year membrane system with an estimated remaining useful life of 5 years. Dining, housekeeping, transportation and activities programming are included in the base fee. Common area interiors have been refreshed within the last 3 years and are in average to good condition.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	6	15	9	Fair	$36,000	$45,000
Paving	5	25	20	Poor	$31,000	$222,000
HVAC	8	33	25	Good	$25,000	$100,000
Plumbing	16	22	6	Good	$36,000	$260,000
Electrical	6	11	5	Fair	$12,000	$10,000
Elevators	30	33	3	Fair	$8,000	$21,000
Fire/Life Safety	8	11	3	Poor	$33,000	$2,000
Windows	39	39	0	Fair	$0	$111,000
Siding/Facade	7	15	8	Fair	$34,000	$254,000
Flooring	17	18	1	Fair	$7,000	$33,000
Appliances	20	21	1	Fair	$15,000	$128,000
Landscaping	14	29	15	Fair	$20,000	$197,000
Pool/Amenity	9	29	20	Good	$34,000	$184,000
Signage	7	14	7	Good	$37,000	$218,000
Fencing	25	35	10	Fair	$23,000	$19,000
Roof (2)	36	38	2	Fair	$14,000	$279,000
Paving (2)	20	23	3	Good	$6,000	$39,000
HVAC (2)	17	19	2	Poor	$4,000	$93,000
Plumbing (2)	20	34	14	Good	$35,000	$138,000
Electrical (2)	11	37	26	Fair	$39,000	$141,000
Elevators (2)	24	24	0	Poor	$32,000	$40,000
Fire/Life Safety (2)	5	14	9	Fair	$20,000	$30,000
Windows (2)	12	23	11	Fair	$4,000	$277,000
Siding/Facade (2)	15	32	17	Fair	$2,000	$209,000
Flooring (2)	8	33	25	Fair	$1,000	$142,000
Appliances (2)	19	26	7	Fair	$33,000	$193,000
Landscaping (2)	16	34	18	Fair	$7,000	$96,000
Pool/Amenity (2)	16	21	5	Good	$33,000	$234,000
Signage (2)	18	18	0	Good	$27,000	$147,000
Fencing (2)	6	14	8	Fair	$26,000	$238,000

Report generated 10/21/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only