CAPITAL IMPROVEMENT PLAN

Brookside Kingsley Market Lofts | Des Moines, IA

Property	Brookside Kingsley Market Lofts
Plan Date	May 12, 2025
Prepared For	Granite Lane Realty
Total Plan Budget	$300,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Unit interior upgrades	Energy	01/31/24	Q3 2027	$453,000	$10,215	Deferred
Lobby renovation	Building	07/30/23	Q4 2027	$895,000	$549,663	In progress
Door hardware	Interior	04/12/26	Q3 2025	$532,000	$378,720	Complete
Landscape / irrigation	Energy	03/24/23	Q2 2026	$461,000	$235,487	Bidding
Storefront glazing	Interior	09/29/26	Q1 2027	$314,000	$169,140	Complete
Storefront glazing	Site	08/06/23	Q2 2026	$218,000	$14,923	Approved
HVAC replacement	Interior	07/05/24	Q3 2026	$595,000	$57,440	In progress
Unit interior upgrades	Interior	01/31/25	Q2 2027	$140,000	$37,177	Bidding
Pool resurfacing	Energy	04/07/23	Q1 2025	$766,000	$415,442	Approved
Door hardware	Site	05/31/25	Q2 2025	$151,000	$70,924	Complete
Storefront glazing	Life Safety	07/07/24	Q4 2026	$544,000	$204,249	Bidding
Water heater replacement	Energy	01/08/26	Q2 2025	$224,000	$65,866	Complete
Signage / monument	Energy	02/25/24	Q1 2027	$656,000	$612,924	Complete
Pool resurfacing	Interior	04/04/25	Q1 2025	$736,000	$614,655	Complete
Fire alarm panel upgrade	Energy	11/18/24	Q1 2026	$539,000	$559,833	Complete
Storefront glazing	Energy	05/03/25	Q3 2025	$711,000	$250,274	Bidding
Exterior paint	Energy	06/12/23	Q3 2027	$123,000	$26,896	In progress
Fence replacement	Life Safety	11/05/25	Q4 2027	$810,000	$70,242	Complete
Pool resurfacing	Site	10/26/26	Q3 2027	$247,000	$9,483	Bidding
HVAC replacement	Interior	07/29/26	Q4 2027	$296,000	$120,990	Deferred
Signage / monument	Building	02/02/25	Q1 2027	$620,000	$530,029	In progress
Storefront glazing	Life Safety	06/24/25	Q3 2026	$727,000	$1,455	Deferred

Report generated 05/12/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Security camera upgrade	Life Safety	07/31/23	Q2 2027	$125,000	$116,081	Complete
Lobby renovation	Site	07/20/25	Q1 2025	$65,000	$1,802	Complete
Fence replacement	Site	05/10/24	Q4 2027	$69,000	$32,798	Complete
Security camera upgrade	Energy	10/20/25	Q3 2025	$724,000	$140,612	In progress
Security camera upgrade	Interior	10/31/25	Q4 2027	$49,000	$13,611	In progress
Lobby renovation	Energy	07/21/23	Q4 2025	$184,000	$53,793	In progress
ADA compliance	Site	03/16/26	Q3 2026	$247,000	$108,886	Approved
ADA compliance	Interior	12/22/26	Q2 2025	$121,000	$24,051	Complete
Storefront glazing	Building	06/22/26	Q4 2027	$546,000	$165,904	Complete
ADA compliance	Site	04/09/24	Q4 2027	$277,000	$120,117	Approved
Roof replacement - Bldg C	Site	11/05/26	Q2 2026	$715,000	$31,963	Deferred
Exterior paint	Life Safety	08/05/24	Q4 2027	$813,000	$476,387	Complete
HVAC replacement	Energy	06/13/25	Q3 2026	$223,000	$166,316	Approved
Unit interior upgrades	Site	03/21/26	Q2 2025	$565,000	$145,999	Bidding
Parking lot resurfacing	Energy	09/12/25	Q1 2026	$625,000	$612,805	In progress
Door hardware	Site	01/26/23	Q4 2026	$9,000	$6,374	Complete
Parking lot resurfacing	Energy	06/03/24	Q2 2027	$353,000	$140,212	Approved
Roof replacement - Bldg C	Interior	07/14/25	Q4 2027	$753,000	$332,355	In progress
Water heater replacement	Building	04/22/23	Q4 2025	$533,000	$128,376	Deferred
Parking lot resurfacing	Site	10/21/26	Q1 2025	$290,000	$18,021	Approved
Fire alarm panel upgrade	Life Safety	06/12/23	Q1 2025	$721,000	$150,623	Deferred
Fence replacement	Interior	02/22/23	Q4 2025	$253,000	$202,911	Bidding
Lobby renovation	Life Safety	01/04/24	Q1 2027	$79,000	$32,627	Deferred
Storefront glazing	Energy	08/04/24	Q3 2027	$503,000	$276,842	Bidding
Exterior paint	Building	08/03/23	Q3 2027	$825,000	$200,084	Approved
LED lighting retrofit	Building	09/08/23	Q4 2027	$773,000	$305,003	Approved
Door hardware	Interior	11/12/23	Q1 2025	$61,000	$917	Approved
LED lighting retrofit	Life Safety	10/26/26	Q1 2026	$171,000	$798	Deferred
Security camera upgrade	Interior	06/17/23	Q3 2026	$538,000	$86,643	Approved
Landscape / irrigation	Energy	05/08/26	Q4 2027	$560,000	$280,279	Deferred
Lobby renovation	Life Safety	02/12/26	Q1 2025	$517,000	$218,558	Complete
Amenity renovation	Life Safety	05/24/26	Q4 2025	$685,000	$140,278	Deferred
LED lighting retrofit	Life Safety	04/23/23	Q3 2025	$278,000	$59,738	Complete
Parking lot resurfacing	Interior	09/01/25	Q2 2026	$127,000	$29,113	In progress
Parking lot resurfacing	Building	12/03/23	Q2 2026	$445,000	$25,539	In progress
ADA compliance	Energy	03/29/26	Q2 2027	$639,000	$37,019	In progress
Parking lot resurfacing	Interior	08/05/23	Q4 2025	$12,000	$12,029	In progress
Security camera upgrade	Energy	09/24/25	Q4 2025	$298,000	$17,228	Bidding
Security camera upgrade	Life Safety	05/21/25	Q2 2027	$845,000	$374,229	Complete
Fire alarm panel upgrade	Energy	07/09/24	Q2 2026	$380,000	$298,434	In progress

Report generated 05/12/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 3 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 38 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 11 years ago and are operating without deficiency.

Investment Overview

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The property is walkable to transit, with 34 structured parking spaces shared between uses. The project combines ground-floor retail and restaurant space with upper-level residential and office components. Distributions to investors for the quarter were paid at an annualized rate of 4.3% on contributed capital. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The project combines ground-floor retail and restaurant space with upper-level residential and office components. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $268,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. Elevators were last modernized 3 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $88,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 10 years ago and are operating without deficiency.

Investor Distributions

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Projected levered IRR is 7.9% with an equity multiple of 1.15x over the hold period. The property is walkable to transit, with 29 structured parking spaces shared between uses. Distributions to investors for the quarter were paid at an annualized rate of 3.9% on contributed capital. Percentage rent and CAM reimbursements are tracked separately for the commercial component.

The business plan contemplates a hold period of 8 years with disposition upon achievement of target returns. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Projected levered IRR is 11.8% with an equity multiple of 1.11x over the hold period. Percentage rent and CAM reimbursements are tracked separately for the commercial component. The property is walkable to transit, with 14 structured parking spaces shared between uses. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $28,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Elevator modernization	Energy	02/01/23	Q1 2027	$291,000	$285,848	In progress
HVAC replacement	Energy	05/31/23	Q4 2027	$631,000	$652,925	Deferred
LED lighting retrofit	Energy	07/27/23	Q1 2025	$29,000	$29,597	Deferred
Pool resurfacing	Interior	11/05/24	Q3 2026	$664,000	$613,180	Approved
Pool resurfacing	Energy	01/10/25	Q2 2026	$222,000	$195,769	Complete
Fence replacement	Energy	10/11/26	Q2 2026	$285,000	$113,661	Deferred
Exterior paint	Building	10/23/23	Q2 2026	$192,000	$27,782	Complete
Lobby renovation	Building	01/14/23	Q2 2025	$573,000	$34,586	Bidding
Storefront glazing	Building	06/24/23	Q1 2025	$594,000	$293,251	Complete
Exterior paint	Interior	06/07/26	Q1 2027	$821,000	$284,086	Complete
Landscape / irrigation	Site	02/16/24	Q2 2026	$724,000	$187,482	Bidding
Door hardware	Site	05/24/23	Q2 2026	$793,000	$530,211	Complete
LED lighting retrofit	Energy	08/07/25	Q3 2026	$565,000	$569,715	In progress
Lobby renovation	Interior	01/01/24	Q3 2025	$145,000	$90,859	In progress
Fence replacement	Life Safety	10/24/26	Q3 2025	$35,000	$26,395	Bidding
Fence replacement	Building	10/21/24	Q3 2027	$42,000	$33,842	Deferred
Water heater replacement	Building	07/16/25	Q3 2025	$173,000	$76,027	Deferred
Pool resurfacing	Interior	04/13/23	Q2 2025	$135,000	$793	Deferred
Storefront glazing	Interior	10/02/23	Q2 2026	$591,000	$603,342	Bidding
Fire alarm panel upgrade	Life Safety	04/11/25	Q1 2027	$210,000	$11,057	In progress
Signage / monument	Life Safety	06/11/25	Q1 2025	$564,000	$159,899	Deferred
Storefront glazing	Building	07/05/26	Q4 2027	$720,000	$405,510	Complete
LED lighting retrofit	Life Safety	05/12/24	Q2 2027	$142,000	$120,024	Approved
Fence replacement	Site	03/14/23	Q1 2025	$284,000	$209,589	Deferred
Water heater replacement	Building	04/09/23	Q2 2026	$879,000	$571,795	Deferred
Elevator modernization	Interior	02/07/25	Q1 2026	$221,000	$88,636	Approved
ADA compliance	Life Safety	06/27/25	Q3 2027	$468,000	$57,144	Complete
ADA compliance	Life Safety	01/03/26	Q2 2027	$145,000	$74,691	In progress
Door hardware	Interior	10/04/25	Q4 2027	$240,000	$42,849	Complete
ADA compliance	Life Safety	01/06/24	Q4 2027	$861,000	$691,539	Approved
Landscape / irrigation	Life Safety	05/04/23	Q4 2026	$789,000	$542,322	Bidding
Water heater replacement	Life Safety	02/24/26	Q4 2027	$134,000	$35,891	Approved
Unit interior upgrades	Energy	11/14/24	Q4 2025	$602,000	$621,880	In progress
LED lighting retrofit	Life Safety	03/22/26	Q2 2027	$621,000	$260,175	Bidding
Lobby renovation	Building	08/08/25	Q2 2025	$323,000	$182,142	Complete
Signage / monument	Life Safety	10/21/24	Q2 2026	$204,000	$159,362	Deferred
Elevator modernization	Energy	04/11/25	Q3 2025	$625,000	$543,061	In progress
Lobby renovation	Life Safety	06/08/25	Q4 2026	$470,000	$376,127	Deferred
Elevator modernization	Site	12/21/25	Q1 2026	$598,000	$90,595	Deferred
Parking lot resurfacing	Interior	07/27/26	Q1 2025	$467,000	$290,545	Bidding
ADA compliance	Life Safety	08/09/25	Q4 2027	$69,000	$3,613	Bidding
Roof replacement - Bldg B	Interior	03/09/25	Q4 2027	$801,000	$459,928	Approved

Report generated 05/12/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Elevators were last modernized 5 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $71,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 11 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 41 months. Elevators were last modernized 6 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Risk Considerations

Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Distributions to investors for the quarter were paid at an annualized rate of 4.9% on contributed capital. The business plan contemplates a hold period of 8 years with disposition upon achievement of target returns. Percentage rent and CAM reimbursements are tracked separately for the commercial component.

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Projected levered IRR is 9.2% with an equity multiple of 1.22x over the hold period. Percentage rent and CAM reimbursements are tracked separately for the commercial component. The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns.

Deferred Maintenance

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 15 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 4 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $448,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 47 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 12 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $20,000.

Business Plan Progress

Distributions to investors for the quarter were paid at an annualized rate of 5.2% on contributed capital. The business plan contemplates a hold period of 12 years with disposition upon achievement of target returns. Projected levered IRR is 11.6% with an equity multiple of 1.16x over the hold period. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. Percentage rent and CAM reimbursements are tracked separately for the commercial component. Projected levered IRR is 2.9% with an equity multiple of 1.47x over the hold period. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The property is walkable to transit, with 3 structured parking spaces shared between uses.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 11 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 2 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Lobby renovation	Site	04/30/25	Q2 2027	$530,000	$424,940	Complete
Pool resurfacing	Life Safety	12/29/26	Q1 2026	$649,000	$663,844	Approved
Roof replacement - Bldg A	Site	11/02/24	Q1 2026	$859,000	$584,221	Complete
Parking lot resurfacing	Energy	04/23/23	Q3 2025	$518,000	$493,298	Approved
Parking lot resurfacing	Building	07/03/26	Q3 2027	$694,000	$74,521	Deferred
Water heater replacement	Site	01/11/24	Q1 2027	$626,000	$526,176	Complete
Signage / monument	Site	01/07/25	Q3 2026	$65,000	$11,218	Bidding
Unit interior upgrades	Building	02/04/26	Q4 2025	$618,000	$578,567	Complete
Lobby renovation	Life Safety	11/24/26	Q4 2026	$511,000	$350,804	Approved
Unit interior upgrades	Life Safety	02/15/26	Q3 2027	$291,000	$219,483	Bidding
Landscape / irrigation	Building	05/28/24	Q1 2025	$515,000	$254,811	Bidding
Security camera upgrade	Interior	05/14/25	Q2 2027	$79,000	$41,949	Complete
Fence replacement	Interior	04/08/23	Q4 2027	$711,000	$264,211	Bidding
Door hardware	Site	02/03/25	Q1 2027	$850,000	$423,465	In progress
Landscape / irrigation	Interior	12/23/24	Q4 2027	$828,000	$668,677	Complete
ADA compliance	Site	05/28/23	Q1 2025	$58,000	$12,101	Complete
Fence replacement	Energy	06/12/26	Q2 2025	$682,000	$212,526	Bidding
Lobby renovation	Life Safety	06/11/24	Q4 2026	$722,000	$504,037	Approved
Sewer line repair	Life Safety	12/03/23	Q4 2025	$391,000	$50,917	Deferred
Storefront glazing	Building	08/12/23	Q4 2025	$213,000	$79,322	Complete
Water heater replacement	Site	08/27/24	Q4 2025	$145,000	$137,133	Deferred
ADA compliance	Building	08/24/26	Q1 2025	$144,000	$133,950	In progress
Landscape / irrigation	Site	09/19/26	Q2 2025	$478,000	$140,509	In progress
Exterior paint	Life Safety	02/23/23	Q1 2025	$504,000	$238,897	Deferred
Pool resurfacing	Interior	03/29/26	Q2 2025	$393,000	$80,196	Bidding
Fire alarm panel upgrade	Energy	03/05/23	Q2 2025	$498,000	$270,807	Complete
Door hardware	Interior	08/06/25	Q2 2025	$537,000	$519,305	Approved
Landscape / irrigation	Energy	08/02/24	Q2 2026	$665,000	$262,013	Bidding
Security camera upgrade	Site	01/01/24	Q3 2026	$429,000	$252,500	Approved
LED lighting retrofit	Interior	04/04/24	Q2 2025	$579,000	$47,586	Complete
Fire alarm panel upgrade	Energy	12/12/26	Q4 2027	$733,000	$703,293	Bidding
Water heater replacement	Interior	02/25/25	Q3 2027	$313,000	$260,149	Approved
HVAC replacement	Life Safety	08/05/26	Q4 2026	$650,000	$557,019	Bidding
Amenity renovation	Building	03/30/23	Q1 2025	$707,000	$647,814	Deferred
Sewer line repair	Energy	02/20/23	Q4 2027	$30,000	$28,478	Complete
Unit interior upgrades	Building	12/08/26	Q1 2025	$509,000	$233,408	Bidding
HVAC replacement	Energy	01/09/23	Q3 2026	$534,000	$92,221	Approved
HVAC replacement	Site	03/07/26	Q2 2025	$647,000	$117,357	Approved
Elevator modernization	Interior	05/24/25	Q4 2025	$796,000	$451,946	Bidding
Exterior paint	Life Safety	07/26/24	Q4 2027	$514,000	$212,042	Approved
Fire alarm panel upgrade	Interior	12/26/24	Q4 2025	$182,000	$94,192	Deferred

Report generated 05/12/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. Elevators were last modernized 11 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $34,000.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $194,000. Elevators were last modernized 7 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months.

Investor Distributions

The project combines ground-floor retail and restaurant space with upper-level residential and office components. The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The property is walkable to transit, with 10 structured parking spaces shared between uses.

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Percentage rent and CAM reimbursements are tracked separately for the commercial component. The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. Distributions to investors for the quarter were paid at an annualized rate of 7.0% on contributed capital.

Observed Conditions

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 5 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $130,000.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $180,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Investment Overview

The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Distributions to investors for the quarter were paid at an annualized rate of 6.3% on contributed capital. Percentage rent and CAM reimbursements are tracked separately for the commercial component.

The property is walkable to transit, with 34 structured parking spaces shared between uses. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Distributions to investors for the quarter were paid at an annualized rate of 6.0% on contributed capital. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 7 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $15,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 23 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
HVAC replacement	Interior	03/15/25	Q1 2026	$533,000	$535,617	Complete
Exterior paint	Energy	11/16/26	Q1 2026	$345,000	$24,548	Complete
Water heater replacement	Energy	03/14/24	Q4 2027	$248,000	$106,695	Complete
Fire alarm panel upgrade	Life Safety	08/09/24	Q2 2026	$731,000	$508,962	Deferred
Storefront glazing	Life Safety	04/14/26	Q1 2027	$181,000	$17,062	Approved
Pool resurfacing	Building	03/26/24	Q3 2025	$544,000	$473,630	Deferred
Fence replacement	Interior	08/22/23	Q1 2027	$717,000	$721,207	Deferred
Elevator modernization	Energy	02/24/23	Q3 2025	$496,000	$57,599	Deferred
HVAC replacement	Site	01/24/23	Q2 2027	$76,000	$9,052	Bidding
Door hardware	Interior	06/21/24	Q1 2026	$868,000	$497,167	Deferred
HVAC replacement	Interior	04/13/26	Q1 2027	$520,000	$108,548	Approved
Pool resurfacing	Site	08/19/25	Q3 2026	$349,000	$350,498	Approved
Security camera upgrade	Site	05/30/26	Q3 2025	$186,000	$165,454	Approved
ADA compliance	Interior	04/27/23	Q1 2025	$373,000	$301,934	Bidding
Elevator modernization	Life Safety	07/10/24	Q4 2026	$684,000	$659,650	In progress
LED lighting retrofit	Life Safety	01/02/23	Q3 2026	$844,000	$493,552	Complete
Storefront glazing	Life Safety	02/07/25	Q1 2027	$99,000	$39,809	In progress
Door hardware	Building	10/08/23	Q1 2026	$363,000	$349,146	Bidding
Exterior paint	Building	05/31/26	Q1 2025	$685,000	$438,166	Deferred
Signage / monument	Building	04/07/26	Q4 2027	$260,000	$148,972	Deferred
Amenity renovation	Site	03/18/25	Q3 2025	$238,000	$16,994	Deferred
Parking lot resurfacing	Interior	11/21/23	Q4 2026	$242,000	$103,908	Bidding
Lobby renovation	Site	03/27/25	Q1 2026	$810,000	$218,699	In progress
ADA compliance	Site	03/28/23	Q1 2026	$527,000	$140,127	Complete
Fire alarm panel upgrade	Energy	01/16/25	Q3 2026	$455,000	$420,031	Approved
Sewer line repair	Life Safety	09/16/24	Q2 2027	$96,000	$79,134	Approved
Landscape / irrigation	Energy	01/02/25	Q2 2027	$372,000	$162,430	Bidding
Signage / monument	Site	04/29/23	Q2 2025	$643,000	$375,497	Deferred
Signage / monument	Building	02/12/26	Q1 2025	$682,000	$96,522	Deferred
Security camera upgrade	Energy	06/05/24	Q3 2025	$464,000	$6,106	Complete
Storefront glazing	Energy	12/06/24	Q4 2026	$389,000	$79,820	Deferred
Elevator modernization	Interior	05/13/24	Q1 2025	$583,000	$59,770	Approved
Door hardware	Life Safety	06/27/26	Q1 2027	$890,000	$150,131	Deferred
Sewer line repair	Energy	03/06/25	Q2 2025	$163,000	$27,766	Complete
ADA compliance	Energy	07/21/24	Q1 2025	$112,000	$56,364	Deferred
Landscape / irrigation	Life Safety	07/16/23	Q3 2025	$873,000	$439,476	In progress
Unit interior upgrades	Energy	08/13/23	Q2 2025	$284,000	$240,882	Approved
Door hardware	Life Safety	06/06/26	Q2 2027	$489,000	$378,403	Bidding
Fire alarm panel upgrade	Site	03/08/25	Q3 2027	$23,000	$14,904	Complete
Water heater replacement	Energy	03/08/24	Q3 2026	$50,000	$9,685	Bidding
Pool resurfacing	Energy	06/01/24	Q4 2027	$897,000	$657,702	Bidding
ADA compliance	Site	08/27/24	Q1 2025	$158,000	$63,344	Deferred

Report generated 05/12/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 38 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $24,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 2 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Business Plan Progress

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Projected levered IRR is 6.6% with an equity multiple of 1.18x over the hold period. The project combines ground-floor retail and restaurant space with upper-level residential and office components. Distributions to investors for the quarter were paid at an annualized rate of 8.0% on contributed capital. The property is walkable to transit, with 17 structured parking spaces shared between uses.

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Distributions to investors for the quarter were paid at an annualized rate of 7.1% on contributed capital. The property is walkable to transit, with 38 structured parking spaces shared between uses. Projected levered IRR is 5.0% with an equity multiple of 1.21x over the hold period.

Observed Conditions

Elevators were last modernized 7 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $129,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 47 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 3 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Investor Distributions

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. The property is walkable to transit, with 24 structured parking spaces shared between uses. Distributions to investors for the quarter were paid at an annualized rate of 4.8% on contributed capital. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Projected levered IRR is 5.9% with an equity multiple of 1.25x over the hold period.

Projected levered IRR is 2.4% with an equity multiple of 1.44x over the hold period. The project combines ground-floor retail and restaurant space with upper-level residential and office components. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Percentage rent and CAM reimbursements are tracked separately for the commercial component. The property is walkable to transit, with 42 structured parking spaces shared between uses.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $468,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 37 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Storefront glazing	Life Safety	09/28/24	Q4 2025	$510,000	$459,103	In progress
Landscape / irrigation	Interior	04/05/24	Q1 2027	$178,000	$54,141	Approved
Exterior paint	Energy	11/23/26	Q2 2027	$271,000	$269,545	Complete
Parking lot resurfacing	Interior	08/21/25	Q1 2025	$586,000	$63,883	In progress
Roof replacement - Bldg A	Building	06/07/23	Q3 2027	$405,000	$335,353	Bidding
Storefront glazing	Interior	08/19/25	Q3 2026	$126,000	$15,365	Complete
Fence replacement	Site	08/06/25	Q3 2026	$26,000	$12,081	Deferred
Roof replacement - Bldg C	Interior	03/28/24	Q1 2026	$563,000	$19,547	Approved
Storefront glazing	Energy	12/27/23	Q4 2025	$766,000	$446,528	In progress
Exterior paint	Building	05/27/24	Q1 2026	$275,000	$126,217	Bidding
HVAC replacement	Building	09/22/24	Q3 2025	$470,000	$274,348	Approved
HVAC replacement	Site	09/06/23	Q4 2027	$824,000	$782,561	Approved
LED lighting retrofit	Energy	09/24/24	Q2 2026	$39,000	$35,986	Complete
Unit interior upgrades	Interior	06/29/23	Q3 2025	$587,000	$184,864	Complete
Storefront glazing	Site	10/27/25	Q1 2027	$486,000	$148,688	Bidding
Signage / monument	Site	04/25/23	Q1 2025	$602,000	$475,971	Deferred
Parking lot resurfacing	Interior	09/16/26	Q1 2027	$506,000	$53,894	Bidding
Door hardware	Building	01/13/26	Q4 2025	$532,000	$527,938	Bidding
Exterior paint	Interior	11/07/23	Q2 2025	$509,000	$87,998	In progress
Storefront glazing	Energy	03/10/26	Q1 2027	$71,000	$28,033	Bidding
Pool resurfacing	Site	02/27/24	Q4 2026	$716,000	$134,462	Deferred
Fire alarm panel upgrade	Site	01/22/23	Q1 2025	$514,000	$153,189	Approved
Unit interior upgrades	Life Safety	08/28/26	Q4 2025	$564,000	$125,779	Bidding
Pool resurfacing	Site	06/04/24	Q4 2027	$20,000	$5,848	In progress
Pool resurfacing	Energy	06/11/24	Q2 2026	$720,000	$280,038	In progress
Door hardware	Interior	06/01/23	Q2 2025	$345,000	$75,243	Complete
LED lighting retrofit	Energy	02/06/26	Q2 2027	$857,000	$512,487	In progress
Sewer line repair	Energy	03/20/24	Q4 2027	$449,000	$309,095	Complete
Parking lot resurfacing	Interior	09/19/25	Q1 2027	$517,000	$330,106	Bidding
Roof replacement - Bldg B	Interior	09/01/26	Q3 2026	$257,000	$40,441	In progress
Lobby renovation	Energy	06/01/26	Q2 2027	$772,000	$762,386	Deferred
Roof replacement - Bldg A	Energy	03/13/26	Q2 2027	$71,000	$42,584	Deferred
Landscape / irrigation	Site	11/27/26	Q3 2026	$489,000	$471,007	Bidding
Exterior paint	Interior	12/20/23	Q4 2026	$585,000	$235,951	Bidding
Lobby renovation	Interior	11/20/25	Q1 2026	$673,000	$451,376	Deferred
Amenity renovation	Interior	02/22/26	Q3 2025	$309,000	$79,669	Approved
HVAC replacement	Building	05/21/24	Q4 2026	$303,000	$246,265	In progress
Door hardware	Site	11/15/24	Q3 2025	$778,000	$544,227	Bidding
Exterior paint	Building	06/20/24	Q1 2025	$712,000	$741,315	Deferred
Fence replacement	Site	05/12/26	Q1 2027	$513,000	$347,311	Complete
Water heater replacement	Life Safety	02/25/25	Q2 2026	$698,000	$162,748	Approved

Report generated 05/12/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 11 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $37,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $303,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 6 months.

Business Plan Progress

The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns. The project combines ground-floor retail and restaurant space with upper-level residential and office components. Percentage rent and CAM reimbursements are tracked separately for the commercial component. Distributions to investors for the quarter were paid at an annualized rate of 4.5% on contributed capital.

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The property is walkable to transit, with 36 structured parking spaces shared between uses. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 28 months. Elevators were last modernized 12 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $416,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 6 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Risk Considerations

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Distributions to investors for the quarter were paid at an annualized rate of 6.1% on contributed capital. Percentage rent and CAM reimbursements are tracked separately for the commercial component. The project combines ground-floor retail and restaurant space with upper-level residential and office components.

Projected levered IRR is 6.4% with an equity multiple of 1.16x over the hold period. Distributions to investors for the quarter were paid at an annualized rate of 5.5% on contributed capital. Percentage rent and CAM reimbursements are tracked separately for the commercial component. The project combines ground-floor retail and restaurant space with upper-level residential and office components. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 6 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 9 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 31 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Fire alarm panel upgrade	Interior	05/07/25	Q1 2026	$106,000	$61,958	Complete
ADA compliance	Interior	04/26/26	Q4 2025	$52,000	$13,555	Complete
Elevator modernization	Life Safety	12/29/26	Q4 2026	$420,000	$34,477	In progress
Door hardware	Interior	07/03/26	Q1 2025	$498,000	$430,191	In progress
Roof replacement - Bldg C	Site	11/14/26	Q4 2026	$323,000	$24,275	In progress
LED lighting retrofit	Building	12/19/26	Q1 2026	$575,000	$265,964	Approved
Unit interior upgrades	Interior	04/11/24	Q3 2027	$664,000	$203,836	Complete
Security camera upgrade	Life Safety	01/13/23	Q1 2027	$626,000	$243,850	Approved
HVAC replacement	Building	06/19/24	Q2 2026	$371,000	$246,622	In progress
Storefront glazing	Building	01/11/26	Q4 2025	$631,000	$132,150	Bidding
ADA compliance	Energy	10/01/23	Q4 2026	$661,000	$238,248	In progress
Signage / monument	Life Safety	09/26/26	Q3 2026	$128,000	$44,588	Approved
Exterior paint	Interior	06/29/26	Q3 2025	$885,000	$254,099	Bidding
Exterior paint	Life Safety	07/17/24	Q4 2026	$256,000	$101,740	Bidding
Unit interior upgrades	Life Safety	08/21/23	Q1 2027	$170,000	$103,233	Complete
Storefront glazing	Energy	06/06/25	Q2 2027	$810,000	$38,829	In progress
LED lighting retrofit	Site	08/06/24	Q1 2026	$785,000	$197,141	In progress
Storefront glazing	Building	06/13/23	Q2 2025	$36,000	$15,568	Complete
Lobby renovation	Energy	07/17/23	Q3 2025	$335,000	$16,528	In progress
Water heater replacement	Life Safety	12/29/25	Q2 2026	$751,000	$766,058	Approved
Sewer line repair	Life Safety	04/28/23	Q2 2026	$615,000	$454,412	Deferred
Door hardware	Building	01/07/26	Q1 2027	$445,000	$238,536	Complete
Roof replacement - Bldg C	Site	04/23/24	Q4 2027	$888,000	$355,056	Bidding
Pool resurfacing	Life Safety	02/02/24	Q2 2026	$382,000	$297,025	Approved
LED lighting retrofit	Life Safety	12/28/24	Q2 2027	$900,000	$379,947	Bidding
Elevator modernization	Site	04/21/25	Q2 2025	$397,000	$279,177	Bidding
Exterior paint	Energy	08/01/24	Q1 2027	$39,000	$26,199	In progress
Security camera upgrade	Life Safety	06/28/26	Q2 2026	$875,000	$686,788	Complete
Security camera upgrade	Site	03/20/24	Q1 2026	$590,000	$110,266	Complete
ADA compliance	Building	09/24/26	Q1 2026	$379,000	$322,994	In progress
Unit interior upgrades	Interior	01/24/25	Q2 2025	$404,000	$284,550	Deferred
Fence replacement	Site	01/13/23	Q2 2025	$225,000	$200,398	Deferred
Water heater replacement	Building	10/22/25	Q3 2025	$568,000	$285,618	Bidding
Unit interior upgrades	Site	09/13/24	Q4 2026	$701,000	$319,800	In progress
HVAC replacement	Site	12/17/23	Q4 2027	$232,000	$9,254	In progress
LED lighting retrofit	Interior	03/03/23	Q2 2025	$693,000	$424,058	Approved
Roof replacement - Bldg C	Life Safety	03/27/23	Q4 2025	$519,000	$108,404	Complete
HVAC replacement	Site	01/13/23	Q1 2025	$389,000	$393,820	Approved
Door hardware	Building	06/29/23	Q3 2025	$231,000	$148,439	Approved
Storefront glazing	Life Safety	09/01/26	Q1 2025	$814,000	$549,719	In progress

Report generated 05/12/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only