PHASE I ENVIRONMENTAL SITE ASSESSMENT

Falcon Gardens | Memphis, TN

Site	Falcon Gardens
Address	5955 Station Parkway, Memphis, TN 92868
Prepared For	Keel & Compass Properties
Report Date	September 15, 2022
Standard	ASTM E1527-21

Site Description

The site contains approximately 16.16 acres and is generally level with frontage along Station Parkway. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 8 curb cuts and the property is served by municipal water and sanitary sewer.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 5.5 acres and is generally level with frontage along Station Parkway. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Site Reconnaissance

A former dry cleaner located 8 blocks to the north is listed as a closed case and is not expected to impact the site. No recognized environmental conditions (RECs) were identified in connection with the subject property. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Vapor encroachment screening did not identify a condition requiring further evaluation. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 6 blocks to the north is listed as a closed case and is not expected to impact the site. No recognized environmental conditions (RECs) were identified in connection with the subject property.

Site Description

Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 8.8 acres and is generally level with frontage along Station Parkway. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Access and Utilities

The site contains approximately 12.12 acres and is generally level with frontage along Station Parkway. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 40 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 41 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 45.45 acres and is generally level with frontage along Station Parkway.

Records Review

Historical sources indicate the site was previously used for agricultural and light commercial purposes. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

Historical sources indicate the site was previously used for agricultural and light commercial purposes. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Access and Utilities

Access to the site is provided by 42 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 38.38 acres and is generally level with frontage along Station Parkway.

The site contains approximately 37.37 acres and is generally level with frontage along Station Parkway. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 27 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Site Reconnaissance

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Vapor encroachment screening did not identify a condition requiring further evaluation.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Regulatory Database Search Results

Database	Search Radius (mi	Sites Within Radius	Subject Property?	Further Evaluation
NPL (Superfund)	0.25	1	No	None
CERCLIS / SEMS	0.25	2	No	None
RCRA - Generators	0.25	1	No	Reviewed - no acti
RCRA - TSD	0.25	0	No	None
LUST	0.5	2	No	None
UST	1.0	0	No	Reviewed - no acti
State Hazardous Waste Sites	0.25	0	No	None
Brownfields	0.25	0	No	None
Engineering Controls	0.25	4	No	Reviewed - no acti
Institutional Controls	1.0	4	No	None
ERNS	0.5	2	No	None
Drycleaner Facilities	0.25	0	No	None
Solid Waste Landfills	0.25	7	No	None
Voluntary Cleanup	0.25	0	No	None
Historical Auto Stations	0.25	4	No	None
NPL (Superfund)	1.0	0	No	None
CERCLIS / SEMS	0.5	4	No	None
RCRA - Generators	0.5	2	No	None
RCRA - TSD	0.5	7	No	Reviewed - no acti
LUST	0.5	4	No	Reviewed - no acti
UST	0.25	1	No	None
State Hazardous Waste Sites	0.25	0	No	None
Brownfields	0.25	0	No	None
Engineering Controls	1.0	0	No	None
Institutional Controls	0.5	2	No	None
ERNS	1.0	1	No	None
Drycleaner Facilities	1.0	1	No	None
Solid Waste Landfills	1.0	0	No	None
Voluntary Cleanup	0.5	4	No	None
Historical Auto Stations	0.5	4	No	None

Report generated 09/15/2022. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Historical Use

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Vapor encroachment screening did not identify a condition requiring further evaluation. No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

Historical Use

A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation. No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

Records Review

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Access and Utilities

The site contains approximately 16.16 acres and is generally level with frontage along Station Parkway. Access to the site is provided by 37 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 12.12 acres and is generally level with frontage along Station Parkway. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Historical Use

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property.

A former dry cleaner located 1 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Site Description

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 46.46 acres and is generally level with frontage along Station Parkway. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 2 curb cuts and the property is served by municipal water and sanitary sewer.

Access to the site is provided by 4 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Site Reconnaissance

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Regulatory Database Search Results

Database	Search Radius (mi	Sites Within Radius	Subject Property?	Further Evaluation
NPL (Superfund)	0.5	1	No	Reviewed - no acti
CERCLIS / SEMS	0.25	1	No	None
RCRA - Generators	0.5	0	No	Reviewed - no acti
RCRA - TSD	0.5	1	No	Reviewed - no acti
LUST	0.5	0	No	None
UST	0.25	4	No	Reviewed - no acti
State Hazardous Waste Sites	1.0	1	No	None
Brownfields	1.0	0	No	None
Engineering Controls	1.0	1	No	None
Institutional Controls	0.25	7	No	None
ERNS	0.25	1	No	None
Drycleaner Facilities	0.25	7	No	None
Solid Waste Landfills	1.0	0	No	None
Voluntary Cleanup	1.0	0	No	None
Historical Auto Stations	1.0	4	No	None
NPL (Superfund)	1.0	0	No	None
CERCLIS / SEMS	1.0	0	No	None
RCRA - Generators	0.25	1	No	Reviewed - no acti
RCRA - TSD	0.5	7	No	None
LUST	1.0	2	No	None
UST	0.25	0	No	None
State Hazardous Waste Sites	1.0	0	No	None
Brownfields	0.5	0	No	Reviewed - no acti
Engineering Controls	0.25	4	No	None
Institutional Controls	0.25	7	No	None
ERNS	1.0	1	No	None
Drycleaner Facilities	0.25	4	No	Reviewed - no acti
Solid Waste Landfills	0.25	2	No	None
Voluntary Cleanup	0.25	4	No	None
Historical Auto Stations	0.25	0	No	Reviewed - no acti

Report generated 09/15/2022. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Historical Use

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 3 blocks to the north is listed as a closed case and is not expected to impact the site. No recognized environmental conditions (RECs) were identified in connection with the subject property.

Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property. Vapor encroachment screening did not identify a condition requiring further evaluation.

Records Review

No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property.

Findings and Opinions

Vapor encroachment screening did not identify a condition requiring further evaluation. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

Historical sources indicate the site was previously used for agricultural and light commercial purposes. No recognized environmental conditions (RECs) were identified in connection with the subject property. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A former dry cleaner located 3 blocks to the north is listed as a closed case and is not expected to impact the site. Vapor encroachment screening did not identify a condition requiring further evaluation. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Access and Utilities

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 48.48 acres and is generally level with frontage along Station Parkway. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 39 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 13.13 acres and is generally level with frontage along Station Parkway. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 30 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Historical Use

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 3 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation. No recognized environmental conditions (RECs) were identified in connection with the subject property. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 5 blocks to the north is listed as a closed case and is not expected to impact the site. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Site Description

Access to the site is provided by 20 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 37.37 acres and is generally level with frontage along Station Parkway.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 33.33 acres and is generally level with frontage along Station Parkway.

Historical Use

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only