CAPITAL IMPROVEMENT PLAN

Heritage Scholars Hall | Columbus, OH

Property	Heritage Scholars Hall
Plan Date	March 2, 2026
Prepared For	Anchorage Meadow Partners
Total Plan Budget	$417,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Elevator modernization	Building	12/07/24	Q4 2027	$673,000	$463,755	Bidding
Door hardware	Site	12/21/24	Q4 2027	$97,000	$48,076	In progress
Elevator modernization	Interior	01/30/25	Q4 2026	$531,000	$195,428	Approved
LED lighting retrofit	Life Safety	01/26/23	Q4 2027	$127,000	$60,053	Bidding
LED lighting retrofit	Building	11/15/24	Q3 2027	$853,000	$6,065	Deferred
Signage / monument	Building	01/24/25	Q3 2027	$492,000	$165,569	Complete
Sewer line repair	Site	05/01/23	Q1 2026	$442,000	$225,722	Approved
ADA compliance	Building	12/12/24	Q4 2025	$636,000	$256,413	Deferred
Landscape / irrigation	Site	09/30/23	Q3 2026	$108,000	$16,465	Bidding
Security camera upgrade	Life Safety	03/10/24	Q4 2025	$222,000	$88,993	Bidding
Signage / monument	Interior	05/01/25	Q3 2027	$246,000	$130,681	Complete
Pool resurfacing	Building	03/16/26	Q3 2027	$883,000	$677,832	Approved
Lobby renovation	Life Safety	06/16/25	Q3 2025	$139,000	$95,143	In progress
Sewer line repair	Interior	04/13/25	Q2 2025	$817,000	$846,244	Deferred
HVAC replacement	Life Safety	03/09/25	Q4 2025	$442,000	$414,479	Bidding
Elevator modernization	Building	10/02/23	Q1 2025	$621,000	$187,606	Complete
Fire alarm panel upgrade	Building	02/23/23	Q3 2027	$50,000	$18,862	Complete
Door hardware	Site	10/17/25	Q3 2027	$502,000	$213,885	Bidding
Lobby renovation	Site	09/02/26	Q3 2026	$59,000	$39,944	In progress
Landscape / irrigation	Energy	10/23/25	Q4 2026	$661,000	$271,658	Deferred
Water heater replacement	Site	01/04/25	Q2 2027	$620,000	$538,403	In progress
Exterior paint	Energy	06/08/23	Q2 2027	$760,000	$65,537	In progress
Exterior paint	Building	01/05/24	Q3 2027	$192,000	$140,708	In progress

Report generated 03/02/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Sewer line repair	Site	03/24/23	Q3 2025	$646,000	$197,485	In progress
Amenity renovation	Energy	11/19/25	Q3 2026	$386,000	$125,144	Bidding
Signage / monument	Life Safety	02/10/23	Q2 2026	$126,000	$119,662	Approved
Landscape / irrigation	Interior	02/18/25	Q2 2025	$462,000	$233,970	Bidding
Unit interior upgrades	Site	06/06/24	Q1 2027	$707,000	$459,583	Deferred
Exterior paint	Interior	01/11/26	Q3 2027	$23,000	$21,183	Complete
Fence replacement	Site	07/17/23	Q4 2027	$483,000	$2,381	In progress
Storefront glazing	Life Safety	03/15/23	Q4 2026	$453,000	$66,191	Complete
Security camera upgrade	Interior	09/09/23	Q1 2025	$197,000	$115,704	In progress
Roof replacement - Bldg D	Energy	04/03/25	Q2 2027	$176,000	$13,817	Deferred
Parking lot resurfacing	Energy	01/08/26	Q2 2027	$488,000	$29,043	Bidding
Fire alarm panel upgrade	Life Safety	01/15/25	Q3 2026	$608,000	$24,794	Deferred
Security camera upgrade	Site	03/13/23	Q3 2026	$603,000	$587,389	Deferred
Fence replacement	Interior	05/07/25	Q3 2026	$603,000	$552,490	Bidding
LED lighting retrofit	Interior	05/31/26	Q4 2025	$500,000	$422,395	Approved
Security camera upgrade	Energy	12/03/24	Q1 2027	$137,000	$88,227	Deferred
Unit interior upgrades	Energy	11/01/26	Q4 2027	$672,000	$105,942	Deferred
Water heater replacement	Energy	08/29/24	Q3 2026	$792,000	$355,896	Bidding
Lobby renovation	Site	11/23/26	Q2 2027	$712,000	$483,016	In progress
Signage / monument	Interior	08/14/26	Q1 2025	$268,000	$265,221	Approved
Lobby renovation	Interior	06/19/23	Q1 2027	$702,000	$272,421	Complete
Exterior paint	Site	06/30/23	Q2 2027	$724,000	$558,877	Approved
Lobby renovation	Energy	04/19/25	Q4 2026	$744,000	$237,383	Approved
Fence replacement	Site	10/01/23	Q1 2027	$462,000	$390,379	Complete
Exterior paint	Building	11/06/25	Q4 2025	$502,000	$92,478	Deferred
Fence replacement	Site	05/23/24	Q1 2025	$711,000	$728,428	Bidding
Fire alarm panel upgrade	Energy	07/01/25	Q2 2025	$421,000	$244,061	Complete
Door hardware	Life Safety	06/16/25	Q1 2027	$129,000	$64,888	Approved
Door hardware	Building	10/07/24	Q4 2027	$223,000	$195,001	Deferred
Elevator modernization	Building	01/10/25	Q3 2027	$548,000	$359,985	Bidding
Water heater replacement	Building	01/26/26	Q2 2027	$17,000	$15,858	Deferred
Pool resurfacing	Life Safety	06/08/24	Q2 2027	$439,000	$31,291	Deferred
Security camera upgrade	Building	11/20/23	Q4 2025	$35,000	$25,617	Complete
Pool resurfacing	Building	01/22/24	Q1 2026	$418,000	$8,750	Approved
Security camera upgrade	Interior	09/28/24	Q1 2025	$545,000	$307,171	In progress
Security camera upgrade	Site	07/05/24	Q4 2026	$275,000	$27,970	Deferred
Security camera upgrade	Interior	09/22/23	Q4 2026	$483,000	$185,471	Deferred
ADA compliance	Site	02/23/24	Q1 2026	$524,000	$72,237	Deferred
Door hardware	Site	03/05/26	Q4 2025	$583,000	$219,575	Bidding
ADA compliance	Interior	05/30/23	Q3 2026	$93,000	$43,945	Approved

Report generated 03/02/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Elevators were last modernized 5 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 33 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $440,000.

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $327,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Risk Considerations

The property is located 9 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Projected levered IRR is 13.6% with an equity multiple of 1.8x over the hold period. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room.

The community is leased by the bed on individual lease liability with parent guaranties and furnished units. The business plan contemplates a hold period of 11 years with disposition upon achievement of target returns. The property is located 5 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Projected levered IRR is 4.8% with an equity multiple of 1.32x over the hold period.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $363,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 34 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 6 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months. Elevators were last modernized 4 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $87,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Risk Considerations

Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

The property is located 8 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Distributions to investors for the quarter were paid at an annualized rate of 7.2% on contributed capital. The business plan contemplates a hold period of 11 years with disposition upon achievement of target returns.

Observed Conditions

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 8 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $319,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Elevator modernization	Interior	10/03/25	Q2 2026	$552,000	$123,796	Deferred
LED lighting retrofit	Site	09/08/26	Q2 2026	$649,000	$269,846	Bidding
Parking lot resurfacing	Life Safety	08/09/25	Q2 2026	$525,000	$338,491	In progress
Exterior paint	Interior	09/19/24	Q2 2025	$258,000	$243,616	Bidding
Pool resurfacing	Life Safety	07/10/25	Q3 2027	$531,000	$140,378	Approved
Amenity renovation	Life Safety	02/20/23	Q3 2025	$347,000	$319,866	Bidding
Security camera upgrade	Interior	03/21/24	Q1 2026	$198,000	$106,031	Deferred
Storefront glazing	Interior	08/11/25	Q3 2026	$47,000	$4,417	In progress
Water heater replacement	Building	11/25/23	Q2 2025	$185,000	$66,523	Complete
Exterior paint	Interior	03/03/25	Q4 2026	$722,000	$513,973	Approved
Water heater replacement	Energy	10/03/25	Q2 2025	$209,000	$214,401	Approved
ADA compliance	Energy	03/31/25	Q3 2026	$57,000	$42,884	Approved
Signage / monument	Site	11/30/24	Q3 2025	$771,000	$154,713	Complete
Amenity renovation	Interior	09/24/26	Q2 2026	$505,000	$259,825	Deferred
Amenity renovation	Life Safety	07/05/24	Q4 2025	$387,000	$124,218	Bidding
Landscape / irrigation	Interior	11/02/24	Q2 2025	$97,000	$58,267	Approved
Unit interior upgrades	Life Safety	08/06/23	Q2 2026	$118,000	$76,005	Complete
Sewer line repair	Energy	11/11/26	Q4 2026	$491,000	$41,199	In progress
Parking lot resurfacing	Site	06/24/25	Q3 2027	$739,000	$630,311	Deferred
Roof replacement - Bldg D	Energy	10/02/24	Q1 2026	$578,000	$99,797	Complete
Security camera upgrade	Building	04/02/26	Q1 2027	$680,000	$275,566	Complete
Roof replacement - Bldg A	Interior	04/12/25	Q4 2025	$613,000	$307,312	Approved
Storefront glazing	Life Safety	09/26/24	Q3 2025	$275,000	$139,235	Deferred
LED lighting retrofit	Building	09/26/25	Q4 2025	$615,000	$555,732	In progress
Exterior paint	Site	08/04/25	Q3 2025	$461,000	$158,527	Bidding
Exterior paint	Energy	11/18/25	Q3 2027	$224,000	$133,268	Complete
Security camera upgrade	Site	02/15/26	Q3 2025	$794,000	$337,919	In progress
Fence replacement	Life Safety	03/14/25	Q1 2025	$350,000	$23,910	Deferred
Fence replacement	Energy	12/12/25	Q4 2025	$109,000	$9,779	Approved
Unit interior upgrades	Energy	05/10/25	Q4 2026	$840,000	$102,304	Bidding
Storefront glazing	Life Safety	06/08/26	Q3 2025	$362,000	$144,373	Bidding
HVAC replacement	Energy	08/30/24	Q4 2026	$870,000	$630,574	In progress
Exterior paint	Site	08/22/23	Q1 2027	$71,000	$7,318	Bidding
Parking lot resurfacing	Building	04/06/23	Q1 2027	$689,000	$43,777	Approved
Unit interior upgrades	Site	03/18/23	Q4 2025	$416,000	$427,348	Bidding
Fence replacement	Energy	09/21/24	Q2 2026	$663,000	$239,354	Deferred
Water heater replacement	Life Safety	02/14/25	Q4 2025	$357,000	$228,392	Bidding
Landscape / irrigation	Energy	01/29/24	Q2 2027	$660,000	$103,564	Deferred
Unit interior upgrades	Energy	08/17/26	Q3 2027	$625,000	$263,677	Complete
LED lighting retrofit	Site	11/11/24	Q4 2027	$232,000	$169,738	Approved

Report generated 03/02/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $290,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 10 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $64,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Business Plan Progress

Distributions to investors for the quarter were paid at an annualized rate of 4.2% on contributed capital. Pre-leasing for the coming academic year stands at 93.1% with rental rates per bed averaging $1,299. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. The property is located 9 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Distributions to investors for the quarter were paid at an annualized rate of 5.8% on contributed capital. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Pre-leasing for the coming academic year stands at 95.3% with rental rates per bed averaging $1,299.

Observed Conditions

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 3 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $155,000.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 4 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $319,000.

Investment Overview

The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Pre-leasing for the coming academic year stands at 89.4% with rental rates per bed averaging $1,299.

Projected levered IRR is 3.2% with an equity multiple of 1.46x over the hold period. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Observed Conditions

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Unit interior upgrades	Building	02/09/26	Q4 2025	$607,000	$126,373	Deferred
HVAC replacement	Building	12/15/24	Q2 2027	$684,000	$661,374	Bidding
Lobby renovation	Energy	01/29/25	Q2 2026	$407,000	$389,977	Complete
Sewer line repair	Site	03/31/25	Q2 2026	$632,000	$380,481	Bidding
Lobby renovation	Energy	12/16/23	Q1 2027	$715,000	$669,552	Deferred
ADA compliance	Energy	09/13/23	Q1 2025	$513,000	$427,639	Complete
Fire alarm panel upgrade	Site	04/04/24	Q3 2026	$53,000	$16,571	In progress
Door hardware	Interior	12/02/25	Q1 2025	$593,000	$58,115	Deferred
Roof replacement - Bldg D	Energy	11/19/26	Q1 2025	$888,000	$790,098	Complete
Pool resurfacing	Life Safety	03/15/26	Q2 2027	$379,000	$189,746	Deferred
Storefront glazing	Life Safety	11/11/23	Q1 2026	$429,000	$42,410	Approved
Pool resurfacing	Site	10/03/24	Q2 2025	$894,000	$631,560	Approved
Storefront glazing	Life Safety	12/12/26	Q1 2026	$149,000	$6,077	Bidding
Security camera upgrade	Building	02/09/25	Q4 2025	$776,000	$146,359	Bidding
Amenity renovation	Site	01/24/24	Q4 2026	$445,000	$295,267	Bidding
HVAC replacement	Energy	10/19/26	Q4 2025	$772,000	$778,397	In progress
Water heater replacement	Building	10/28/23	Q1 2027	$477,000	$304,368	Deferred
Fire alarm panel upgrade	Life Safety	04/11/24	Q1 2026	$840,000	$793,796	Deferred
Lobby renovation	Interior	05/18/23	Q1 2026	$689,000	$409,079	Complete
Lobby renovation	Building	04/11/25	Q4 2025	$100,000	$85,896	Approved
Elevator modernization	Interior	11/06/24	Q2 2026	$709,000	$287,889	In progress
Unit interior upgrades	Site	05/11/24	Q3 2025	$340,000	$63,536	Deferred
LED lighting retrofit	Interior	09/08/25	Q2 2025	$231,000	$137,556	Bidding
Water heater replacement	Energy	01/13/25	Q1 2027	$85,000	$77,746	In progress
Elevator modernization	Building	06/09/23	Q1 2025	$557,000	$572,509	Bidding
Landscape / irrigation	Energy	11/15/24	Q2 2026	$361,000	$229,124	In progress
Elevator modernization	Energy	02/22/26	Q2 2025	$712,000	$590,428	Bidding
Signage / monument	Life Safety	02/03/26	Q1 2026	$629,000	$19,617	Bidding
Roof replacement - Bldg A	Site	03/10/23	Q3 2025	$260,000	$115,763	Complete
Landscape / irrigation	Life Safety	09/01/26	Q3 2025	$61,000	$53,878	Deferred
ADA compliance	Interior	11/22/26	Q1 2027	$455,000	$70,818	Bidding
ADA compliance	Interior	01/27/26	Q3 2027	$375,000	$143,354	Complete
LED lighting retrofit	Site	06/09/24	Q1 2025	$684,000	$188,325	In progress
LED lighting retrofit	Life Safety	04/04/26	Q2 2027	$306,000	$33,408	Deferred
Security camera upgrade	Energy	06/20/25	Q3 2027	$610,000	$105,566	Deferred
Security camera upgrade	Energy	05/26/26	Q3 2025	$733,000	$729,997	Bidding
Door hardware	Energy	10/26/25	Q3 2025	$645,000	$286,954	Deferred
Elevator modernization	Site	07/21/24	Q1 2025	$709,000	$587,201	Deferred
Pool resurfacing	Energy	04/04/23	Q1 2027	$269,000	$150,725	Approved
Pool resurfacing	Site	10/31/26	Q2 2026	$543,000	$108,403	In progress
Amenity renovation	Building	06/20/25	Q4 2025	$138,000	$29,061	Approved

Report generated 03/02/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 10 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $366,000.

Elevators were last modernized 7 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 48 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Investment Overview

The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Pre-leasing for the coming academic year stands at 95.0% with rental rates per bed averaging $1,299. The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. Distributions to investors for the quarter were paid at an annualized rate of 3.7% on contributed capital. The property is located 3 blocks from the main campus with a dedicated shuttle serving fall and spring terms.

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The property is located 9 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Distributions to investors for the quarter were paid at an annualized rate of 6.4% on contributed capital.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $100,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 34 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $297,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Investor Distributions

The business plan contemplates a hold period of 10 years with disposition upon achievement of target returns. Pre-leasing for the coming academic year stands at 94.0% with rental rates per bed averaging $1,299. Projected levered IRR is 5.0% with an equity multiple of 1.16x over the hold period. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Pre-leasing for the coming academic year stands at 88.3% with rental rates per bed averaging $1,299. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. The property is located 4 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Distributions to investors for the quarter were paid at an annualized rate of 4.7% on contributed capital. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The business plan contemplates a hold period of 4 years with disposition upon achievement of target returns.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $382,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 20 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only