CAPITAL IMPROVEMENT PLAN

Cedar Whitaker Rental Homes | Naperville, IL

Property	Cedar Whitaker Rental Homes
Plan Date	June 6, 2025
Prepared For	Sunbelt Ridge Acquisitions
Total Plan Budget	$363,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Lobby renovation	Interior	06/24/24	Q1 2027	$528,000	$257,032	In progress
HVAC replacement	Building	09/08/25	Q3 2027	$197,000	$52,943	Approved
Door hardware	Interior	07/07/25	Q3 2025	$147,000	$18,973	In progress
Fire alarm panel upgrade	Building	02/17/25	Q1 2025	$897,000	$822,957	Deferred
Storefront glazing	Interior	09/29/24	Q3 2026	$84,000	$29,874	In progress
Pool resurfacing	Energy	06/18/23	Q3 2026	$765,000	$249,389	Deferred
Storefront glazing	Energy	06/28/24	Q1 2025	$404,000	$242,819	Complete
LED lighting retrofit	Site	07/01/24	Q3 2027	$272,000	$20,905	Bidding
Fire alarm panel upgrade	Site	05/26/26	Q4 2026	$209,000	$58,815	In progress
Signage / monument	Energy	07/18/25	Q1 2025	$111,000	$16,658	In progress
Parking lot resurfacing	Site	10/29/23	Q3 2027	$529,000	$261,150	In progress
Elevator modernization	Building	12/13/26	Q4 2027	$327,000	$251,997	Approved
ADA compliance	Interior	05/02/26	Q1 2025	$661,000	$347,103	Bidding
HVAC replacement	Building	04/20/25	Q2 2026	$237,000	$236,139	In progress
Pool resurfacing	Life Safety	11/01/25	Q2 2026	$386,000	$117,469	Deferred
Door hardware	Interior	03/13/25	Q4 2026	$713,000	$166,315	Deferred
Fence replacement	Interior	06/01/23	Q1 2027	$365,000	$125,288	Deferred
Fire alarm panel upgrade	Building	09/14/23	Q4 2026	$816,000	$402,778	Complete
LED lighting retrofit	Life Safety	12/20/25	Q1 2025	$46,000	$16,146	Bidding
Security camera upgrade	Site	11/29/24	Q1 2027	$79,000	$43,518	Deferred
Fence replacement	Life Safety	06/22/25	Q3 2025	$624,000	$539,303	Deferred
Lobby renovation	Site	02/06/26	Q3 2025	$147,000	$37,313	Deferred
Exterior paint	Life Safety	12/28/23	Q3 2026	$193,000	$103,664	In progress
Security camera upgrade	Life Safety	05/21/24	Q3 2025	$62,000	$1,401	In progress
Roof replacement - Bldg B	Site	10/09/26	Q3 2027	$620,000	$589,528	Bidding

Report generated 06/06/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
LED lighting retrofit	Building	03/17/24	Q3 2027	$260,000	$183,634	Bidding
Parking lot resurfacing	Energy	03/05/26	Q2 2027	$649,000	$102,602	Bidding
Landscape / irrigation	Site	04/24/26	Q3 2027	$137,000	$28,203	Deferred
Elevator modernization	Interior	03/15/25	Q2 2027	$593,000	$288,385	Deferred
Fire alarm panel upgrade	Building	07/17/23	Q3 2027	$541,000	$227,145	Deferred
Roof replacement - Bldg C	Energy	12/20/23	Q3 2027	$791,000	$531,881	Approved
Pool resurfacing	Interior	01/29/26	Q2 2026	$380,000	$161,212	Bidding
Fire alarm panel upgrade	Interior	10/15/23	Q3 2027	$204,000	$103,658	Approved
Roof replacement - Bldg C	Life Safety	04/02/26	Q1 2026	$798,000	$487,581	Approved
Exterior paint	Life Safety	08/26/26	Q3 2025	$575,000	$501,818	Complete
Fence replacement	Energy	09/10/24	Q2 2025	$521,000	$363,857	In progress
Lobby renovation	Life Safety	04/27/26	Q3 2025	$631,000	$214,369	Complete
Water heater replacement	Site	03/30/25	Q1 2025	$288,000	$32,285	Bidding
Sewer line repair	Energy	01/19/24	Q3 2026	$401,000	$244,148	Bidding
Landscape / irrigation	Interior	03/03/25	Q3 2027	$353,000	$165,433	Deferred
Roof replacement - Bldg B	Interior	11/27/24	Q2 2026	$128,000	$70,425	Approved
Signage / monument	Interior	04/22/25	Q4 2026	$665,000	$19,454	Bidding
Lobby renovation	Interior	06/11/25	Q2 2025	$270,000	$169,371	In progress
Parking lot resurfacing	Building	06/06/26	Q2 2027	$843,000	$107,232	Approved
Security camera upgrade	Site	03/16/26	Q2 2025	$800,000	$687,283	Deferred
Lobby renovation	Energy	03/09/26	Q1 2026	$793,000	$197,940	In progress
Lobby renovation	Interior	06/21/24	Q3 2026	$535,000	$335,082	Deferred
ADA compliance	Building	07/02/25	Q1 2025	$91,000	$94,129	Deferred
HVAC replacement	Building	05/01/23	Q2 2025	$841,000	$706,784	Deferred
Door hardware	Energy	02/20/26	Q2 2026	$739,000	$356,696	Deferred
Door hardware	Energy	05/04/26	Q3 2025	$788,000	$588,868	Approved
Lobby renovation	Energy	02/03/23	Q2 2026	$34,000	$24,229	In progress
Security camera upgrade	Building	08/19/25	Q2 2026	$327,000	$134,755	Bidding
Sewer line repair	Energy	12/15/24	Q4 2027	$168,000	$31,072	Approved
Amenity renovation	Life Safety	04/01/25	Q3 2025	$734,000	$507,205	Deferred
Security camera upgrade	Building	05/11/23	Q2 2026	$172,000	$75,704	Deferred
Security camera upgrade	Life Safety	01/02/26	Q3 2027	$213,000	$191,126	Deferred
Fire alarm panel upgrade	Site	02/10/24	Q1 2025	$730,000	$577,264	Bidding
Roof replacement - Bldg D	Interior	04/19/25	Q2 2027	$684,000	$80,061	Bidding
Unit interior upgrades	Energy	03/03/23	Q1 2025	$450,000	$347,984	Complete
Lobby renovation	Energy	12/25/26	Q3 2026	$639,000	$502,488	Deferred
Fence replacement	Energy	01/07/26	Q3 2025	$437,000	$33,100	Approved
Sewer line repair	Life Safety	10/23/23	Q3 2026	$260,000	$84,154	Bidding
Storefront glazing	Building	12/25/26	Q1 2027	$280,000	$243,783	Approved
Pool resurfacing	Life Safety	10/28/23	Q3 2026	$593,000	$172,225	In progress
Sewer line repair	Building	01/23/24	Q4 2026	$802,000	$162,361	Complete

Report generated 06/06/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $149,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Elevators were last modernized 3 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months.

Investment Overview

The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns. Homes average 1,701 square feet with average monthly rent of $1,845. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Projected levered IRR is 8.8% with an equity multiple of 1.16x over the hold period.

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Projected levered IRR is 5.6% with an equity multiple of 1.30x over the hold period. Turn costs average $36,000 per home, and the in-house maintenance team handles most work orders within 40 days. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $348,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 20 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 32 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $98,000.

Investment Overview

The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Homes average 1,701 square feet with average monthly rent of $1,845. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The business plan contemplates a hold period of 5 years with disposition upon achievement of target returns. Turn costs average $287,000 per home, and the in-house maintenance team handles most work orders within 25 days.

Distributions to investors for the quarter were paid at an annualized rate of 3.2% on contributed capital. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Projected levered IRR is 5.5% with an equity multiple of 1.8x over the hold period. Turn costs average $278,000 per home, and the in-house maintenance team handles most work orders within 20 days.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Parking lot resurfacing	Site	08/29/26	Q2 2026	$705,000	$248,738	Complete
Elevator modernization	Building	06/10/25	Q1 2026	$413,000	$27,566	Deferred
Elevator modernization	Building	07/25/24	Q3 2027	$849,000	$590,207	Complete
Unit interior upgrades	Interior	08/08/23	Q3 2026	$272,000	$25,690	Approved
Roof replacement - Bldg C	Site	09/18/23	Q3 2026	$606,000	$258,913	Deferred
HVAC replacement	Energy	05/19/23	Q3 2025	$281,000	$134,177	In progress
Signage / monument	Interior	10/24/23	Q2 2027	$160,000	$6,779	Approved
Pool resurfacing	Life Safety	09/16/25	Q3 2027	$315,000	$162,303	Bidding
Lobby renovation	Interior	01/06/24	Q4 2026	$327,000	$268,414	Bidding
ADA compliance	Energy	08/18/25	Q1 2027	$14,000	$8,815	Deferred
Door hardware	Energy	01/16/25	Q4 2025	$850,000	$159,227	In progress
Door hardware	Site	10/20/23	Q1 2026	$241,000	$193,563	In progress
ADA compliance	Site	02/07/24	Q2 2027	$47,000	$10,149	Bidding
Exterior paint	Interior	09/27/23	Q1 2027	$336,000	$271,069	Deferred
Fence replacement	Interior	01/30/23	Q1 2025	$186,000	$182,882	Approved
Signage / monument	Interior	04/29/25	Q4 2027	$515,000	$444,164	Complete
Unit interior upgrades	Building	12/07/24	Q3 2025	$713,000	$199,160	In progress
Storefront glazing	Interior	11/23/23	Q1 2026	$542,000	$204,298	Complete
HVAC replacement	Building	10/27/25	Q1 2027	$629,000	$192,767	Bidding
LED lighting retrofit	Interior	01/03/25	Q3 2026	$525,000	$11,693	Complete
LED lighting retrofit	Building	12/18/24	Q1 2025	$598,000	$458,947	Approved
Unit interior upgrades	Building	07/19/25	Q2 2025	$454,000	$177,325	Bidding
Water heater replacement	Interior	12/28/24	Q4 2027	$60,000	$38,951	In progress
Signage / monument	Energy	08/16/24	Q2 2026	$18,000	$2,196	Approved
Water heater replacement	Site	01/17/23	Q3 2027	$103,000	$6,827	Complete
Roof replacement - Bldg C	Site	08/15/23	Q2 2026	$680,000	$325,238	Bidding
Sewer line repair	Site	11/06/23	Q1 2027	$21,000	$12,410	Approved
Roof replacement - Bldg B	Site	09/19/26	Q1 2026	$666,000	$198,903	Bidding
Exterior paint	Life Safety	01/28/23	Q1 2025	$497,000	$183,822	Deferred
Sewer line repair	Energy	10/30/26	Q2 2026	$675,000	$277,663	Complete
Exterior paint	Building	09/08/23	Q4 2027	$634,000	$108,261	Approved
Storefront glazing	Energy	01/04/23	Q4 2027	$537,000	$126,165	Bidding
LED lighting retrofit	Interior	09/06/25	Q3 2025	$75,000	$78,354	Approved
ADA compliance	Site	03/26/26	Q3 2025	$857,000	$354,618	Bidding
HVAC replacement	Building	04/04/24	Q2 2025	$141,000	$115,194	Bidding
Lobby renovation	Energy	04/16/25	Q2 2026	$130,000	$75,413	Approved
Unit interior upgrades	Life Safety	07/30/25	Q3 2026	$112,000	$100,579	Complete
ADA compliance	Interior	02/13/23	Q3 2025	$503,000	$274,558	Approved
Roof replacement - Bldg B	Life Safety	10/29/23	Q4 2027	$441,000	$68,294	Bidding
Fence replacement	Site	06/01/26	Q3 2025	$603,000	$442,973	Bidding
Sewer line repair	Interior	02/06/25	Q4 2027	$57,000	$27,297	Deferred
Elevator modernization	Site	11/23/24	Q3 2025	$136,000	$48,631	Complete

Report generated 06/06/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 12 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $61,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 12 months. Elevators were last modernized 9 years ago and are operating without deficiency.

Risk Considerations

Distributions to investors for the quarter were paid at an annualized rate of 5.6% on contributed capital. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The business plan contemplates a hold period of 10 years with disposition upon achievement of target returns. Turn costs average $376,000 per home, and the in-house maintenance team handles most work orders within 13 days. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Homes average 1,701 square feet with average monthly rent of $1,845.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 11 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $477,000. Elevators were last modernized 5 years ago and are operating without deficiency.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 3 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $73,000.

Investor Distributions

The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Turn costs average $314,000 per home, and the in-house maintenance team handles most work orders within 4 days. Projected levered IRR is 10.1% with an equity multiple of 1.28x over the hold period.

Projected levered IRR is 12.9% with an equity multiple of 1.41x over the hold period. The business plan contemplates a hold period of 9 years with disposition upon achievement of target returns. Turn costs average $392,000 per home, and the in-house maintenance team handles most work orders within 2 days. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
ADA compliance	Life Safety	06/26/25	Q3 2027	$107,000	$42,456	Deferred
Door hardware	Building	01/27/23	Q2 2027	$320,000	$71,771	In progress
Storefront glazing	Site	04/30/25	Q4 2025	$165,000	$16,906	Complete
Signage / monument	Building	05/19/24	Q4 2027	$589,000	$185,537	Bidding
Water heater replacement	Building	06/17/25	Q2 2027	$219,000	$28,859	Complete
LED lighting retrofit	Building	10/10/25	Q1 2026	$47,000	$22,592	Approved
Sewer line repair	Energy	11/10/24	Q3 2025	$884,000	$563,576	Complete
Unit interior upgrades	Life Safety	01/31/24	Q1 2025	$802,000	$350,792	Approved
Landscape / irrigation	Building	04/11/26	Q4 2026	$647,000	$314,217	Complete
Fence replacement	Site	01/25/25	Q4 2026	$669,000	$199,886	Approved
HVAC replacement	Site	03/31/24	Q4 2026	$14,000	$9,944	Deferred
Fire alarm panel upgrade	Interior	08/10/23	Q3 2025	$851,000	$530,981	Complete
HVAC replacement	Energy	06/24/23	Q3 2025	$717,000	$52,583	Deferred
ADA compliance	Energy	05/26/23	Q2 2026	$410,000	$256,518	In progress
Parking lot resurfacing	Interior	09/01/26	Q2 2025	$825,000	$212,213	Bidding
Lobby renovation	Site	02/01/23	Q1 2027	$118,000	$79,551	Deferred
Fence replacement	Building	03/13/24	Q3 2025	$433,000	$378,746	Deferred
Storefront glazing	Building	07/25/25	Q1 2026	$500,000	$194,213	In progress
Security camera upgrade	Building	07/23/23	Q2 2025	$372,000	$268,427	Bidding
Unit interior upgrades	Interior	04/26/25	Q3 2027	$553,000	$361,242	In progress
Parking lot resurfacing	Interior	09/21/23	Q4 2026	$737,000	$411,593	Complete
Parking lot resurfacing	Interior	07/01/25	Q3 2027	$589,000	$611,108	Bidding
Exterior paint	Building	10/14/26	Q1 2026	$892,000	$364,128	In progress
ADA compliance	Life Safety	11/08/23	Q2 2027	$408,000	$419,398	In progress
Water heater replacement	Site	06/18/23	Q3 2025	$142,000	$44,981	In progress
Sewer line repair	Energy	03/09/24	Q3 2027	$521,000	$202,836	Approved
Amenity renovation	Interior	04/06/23	Q4 2027	$146,000	$48,918	Approved
Elevator modernization	Life Safety	07/01/26	Q3 2026	$710,000	$513,375	Approved
Pool resurfacing	Building	11/16/24	Q3 2026	$73,000	$9,737	Deferred
Parking lot resurfacing	Building	08/05/26	Q1 2025	$720,000	$579,604	Deferred
LED lighting retrofit	Interior	12/02/23	Q2 2026	$835,000	$669,720	Bidding
Water heater replacement	Interior	04/25/24	Q3 2026	$713,000	$152,227	Approved
Roof replacement - Bldg A	Interior	04/03/24	Q1 2027	$551,000	$461,683	Deferred
Amenity renovation	Site	03/04/24	Q3 2026	$90,000	$75,380	Deferred
Fire alarm panel upgrade	Site	11/27/23	Q1 2026	$641,000	$89,735	Deferred
Exterior paint	Life Safety	03/29/25	Q1 2026	$244,000	$235,235	Complete
Parking lot resurfacing	Life Safety	02/25/24	Q3 2025	$754,000	$477,975	Bidding
Fence replacement	Building	03/07/24	Q2 2025	$42,000	$20,594	Complete
Amenity renovation	Building	08/03/26	Q3 2025	$462,000	$11,453	Complete
LED lighting retrofit	Interior	10/30/24	Q2 2025	$620,000	$650,460	Complete
Water heater replacement	Building	04/28/26	Q4 2027	$875,000	$730,272	Deferred
Exterior paint	Site	02/09/25	Q4 2026	$710,000	$413,808	Approved

Report generated 06/06/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $203,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $295,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Risk Considerations

The business plan contemplates a hold period of 12 years with disposition upon achievement of target returns. Distributions to investors for the quarter were paid at an annualized rate of 5.8% on contributed capital. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Homes average 1,701 square feet with average monthly rent of $1,845. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Homes average 1,701 square feet with average monthly rent of $1,845. The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. Distributions to investors for the quarter were paid at an annualized rate of 4.3% on contributed capital.

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 11 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $252,000. Elevators were last modernized 9 years ago and are operating without deficiency.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $40,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months.

Business Plan Progress

Projected levered IRR is 9.8% with an equity multiple of 1.9x over the hold period. Distributions to investors for the quarter were paid at an annualized rate of 3.9% on contributed capital. Turn costs average $192,000 per home, and the in-house maintenance team handles most work orders within 30 days. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. The business plan contemplates a hold period of 11 years with disposition upon achievement of target returns. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Unit interior upgrades	Site	01/27/24	Q2 2026	$103,000	$52,232	In progress
ADA compliance	Life Safety	07/22/23	Q1 2025	$195,000	$93,517	Complete
Amenity renovation	Building	11/07/23	Q3 2025	$596,000	$365,834	Approved
ADA compliance	Building	06/27/25	Q3 2025	$594,000	$258,778	Approved
HVAC replacement	Life Safety	12/04/23	Q4 2026	$443,000	$146,478	Bidding
Fire alarm panel upgrade	Life Safety	02/16/25	Q1 2025	$48,000	$29,944	In progress
Amenity renovation	Energy	01/14/23	Q1 2026	$470,000	$396,259	Bidding
Security camera upgrade	Site	05/18/26	Q2 2027	$710,000	$689,440	Approved
Landscape / irrigation	Building	03/31/23	Q1 2027	$48,000	$13,988	Bidding
Pool resurfacing	Energy	06/18/25	Q2 2026	$534,000	$43,536	Bidding
Security camera upgrade	Energy	11/19/23	Q1 2025	$748,000	$9,200	Approved
Water heater replacement	Interior	09/28/25	Q2 2026	$177,000	$4,168	Deferred
Landscape / irrigation	Life Safety	05/21/26	Q4 2026	$304,000	$186,073	Complete
Exterior paint	Energy	03/22/24	Q3 2026	$15,000	$1,371	Complete
Parking lot resurfacing	Energy	11/07/26	Q3 2027	$615,000	$240,256	Approved
LED lighting retrofit	Interior	10/29/25	Q4 2025	$180,000	$132,469	Deferred
Sewer line repair	Site	10/11/23	Q3 2027	$781,000	$193,716	Bidding
Water heater replacement	Life Safety	08/21/23	Q3 2025	$739,000	$305,589	Bidding
Elevator modernization	Site	03/01/23	Q3 2027	$546,000	$108,989	Complete
Water heater replacement	Energy	04/11/25	Q3 2027	$627,000	$384,695	Complete
Pool resurfacing	Site	09/07/23	Q2 2027	$743,000	$41,763	Bidding
Exterior paint	Interior	10/21/24	Q3 2027	$599,000	$485,535	Approved
ADA compliance	Interior	06/10/26	Q1 2025	$276,000	$154,757	Deferred
Pool resurfacing	Interior	04/04/26	Q2 2026	$28,000	$11,684	In progress
Fire alarm panel upgrade	Building	09/20/24	Q3 2027	$125,000	$17,782	Complete
Signage / monument	Interior	07/05/26	Q3 2026	$273,000	$15,854	In progress
Storefront glazing	Energy	08/27/26	Q1 2027	$354,000	$65,850	Approved
Signage / monument	Site	04/07/26	Q3 2027	$188,000	$93,212	Deferred
Exterior paint	Energy	05/26/26	Q3 2026	$629,000	$440,607	Approved
Fire alarm panel upgrade	Life Safety	11/28/24	Q3 2027	$378,000	$161,567	In progress
Door hardware	Life Safety	06/21/25	Q1 2026	$90,000	$41,977	Deferred
LED lighting retrofit	Site	09/19/25	Q1 2026	$39,000	$21,176	Approved
Security camera upgrade	Interior	05/19/26	Q3 2026	$636,000	$496,837	Bidding
Signage / monument	Building	04/10/23	Q2 2026	$449,000	$72,543	Complete
Pool resurfacing	Building	08/28/24	Q3 2025	$796,000	$579,289	Approved
Sewer line repair	Site	09/24/23	Q4 2027	$186,000	$91,050	Bidding
Pool resurfacing	Life Safety	11/09/24	Q2 2027	$111,000	$52,278	Complete
Fence replacement	Energy	12/01/24	Q1 2025	$561,000	$206,177	Approved
Fence replacement	Energy	06/02/26	Q3 2027	$651,000	$465,941	Approved
Lobby renovation	Interior	03/14/24	Q4 2026	$874,000	$690,118	Approved

Report generated 06/06/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 12 months. Elevators were last modernized 10 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $232,000.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 7 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency.

Investment Overview

Distributions to investors for the quarter were paid at an annualized rate of 4.6% on contributed capital. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Turn costs average $109,000 per home, and the in-house maintenance team handles most work orders within 11 days. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Projected levered IRR is 2.4% with an equity multiple of 1.41x over the hold period. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Distributions to investors for the quarter were paid at an annualized rate of 6.5% on contributed capital.

Recommendations

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 4 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $277,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 7 months.

Business Plan Progress

Turn costs average $375,000 per home, and the in-house maintenance team handles most work orders within 42 days. Homes average 1,701 square feet with average monthly rent of $1,845. Distributions to investors for the quarter were paid at an annualized rate of 5.4% on contributed capital. The business plan contemplates a hold period of 5 years with disposition upon achievement of target returns.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Sewer line repair	Interior	07/13/23	Q1 2025	$664,000	$242,120	Bidding
Storefront glazing	Energy	06/19/24	Q2 2026	$363,000	$364,133	Approved
Landscape / irrigation	Interior	02/11/23	Q1 2026	$187,000	$51,870	Complete
Signage / monument	Life Safety	12/15/24	Q2 2026	$198,000	$8,912	Approved
Unit interior upgrades	Energy	02/05/24	Q1 2025	$396,000	$56,119	Complete
Landscape / irrigation	Building	12/05/25	Q2 2025	$393,000	$267,359	Deferred
Parking lot resurfacing	Interior	03/30/23	Q4 2025	$376,000	$118,296	Deferred
Door hardware	Energy	01/15/24	Q1 2027	$868,000	$665,660	Bidding
Fire alarm panel upgrade	Site	07/20/24	Q3 2026	$147,000	$105,521	In progress
Amenity renovation	Life Safety	01/15/26	Q2 2025	$352,000	$273,072	Complete
Door hardware	Site	03/05/25	Q3 2027	$867,000	$129,657	Bidding
Landscape / irrigation	Interior	05/30/25	Q1 2026	$555,000	$501,450	Bidding
Sewer line repair	Energy	01/29/25	Q3 2025	$896,000	$409,611	Deferred
Fire alarm panel upgrade	Building	01/30/26	Q4 2027	$196,000	$20,638	Bidding
Water heater replacement	Site	10/22/23	Q2 2025	$27,000	$5,786	In progress
Lobby renovation	Interior	01/27/25	Q3 2026	$299,000	$233,018	In progress
Elevator modernization	Site	01/03/26	Q1 2025	$742,000	$437,200	Deferred
HVAC replacement	Interior	02/21/26	Q2 2025	$342,000	$202,321	Complete
Parking lot resurfacing	Interior	04/29/26	Q3 2025	$434,000	$309,187	Complete
Signage / monument	Energy	06/09/26	Q2 2026	$372,000	$264,777	In progress
Unit interior upgrades	Site	08/24/24	Q2 2025	$102,000	$11,410	Approved
Unit interior upgrades	Site	03/23/23	Q4 2026	$488,000	$301,265	Deferred
Lobby renovation	Interior	07/12/24	Q2 2027	$352,000	$162,933	Bidding
Elevator modernization	Site	05/14/23	Q3 2027	$557,000	$282,809	Bidding
Sewer line repair	Energy	12/27/25	Q3 2025	$796,000	$111,767	In progress
HVAC replacement	Interior	02/04/25	Q1 2025	$877,000	$897,404	Deferred
Elevator modernization	Energy	07/12/26	Q1 2025	$86,000	$24,227	Complete
Water heater replacement	Site	07/15/24	Q2 2027	$827,000	$359,857	Deferred
Pool resurfacing	Interior	01/26/24	Q3 2027	$180,000	$94,264	In progress
LED lighting retrofit	Site	01/17/26	Q3 2027	$47,000	$24,412	Complete
Fence replacement	Interior	06/29/23	Q4 2027	$345,000	$9,849	Approved
Water heater replacement	Building	06/12/23	Q3 2026	$188,000	$166,658	Deferred
Landscape / irrigation	Energy	08/16/24	Q1 2025	$105,000	$32,387	Deferred
Roof replacement - Bldg C	Life Safety	11/17/23	Q2 2026	$261,000	$150,973	In progress
Landscape / irrigation	Energy	09/28/24	Q3 2026	$846,000	$119,600	Approved
Parking lot resurfacing	Energy	08/06/23	Q2 2025	$13,000	$7,587	Complete
Pool resurfacing	Interior	09/04/26	Q2 2026	$48,000	$20,954	Bidding
Roof replacement - Bldg B	Site	12/06/25	Q2 2026	$738,000	$388,030	Bidding
Security camera upgrade	Interior	02/28/25	Q3 2025	$597,000	$548,873	Deferred
Amenity renovation	Energy	10/28/24	Q3 2026	$619,000	$166,831	Complete

Report generated 06/06/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $171,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. Elevators were last modernized 12 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Elevators were last modernized 8 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 47 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $374,000.

Risk Considerations

Homes average 1,701 square feet with average monthly rent of $1,845. Distributions to investors for the quarter were paid at an annualized rate of 3.2% on contributed capital. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Turn costs average $261,000 per home, and the in-house maintenance team handles most work orders within 40 days.

Homes average 1,701 square feet with average monthly rent of $1,845. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Turn costs average $262,000 per home, and the in-house maintenance team handles most work orders within 48 days. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 7 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 24 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $171,000.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $431,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 28 months.

Investor Distributions

Projected levered IRR is 8.4% with an equity multiple of 1.24x over the hold period. The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. Distributions to investors for the quarter were paid at an annualized rate of 3.5% on contributed capital. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Projected levered IRR is 12.0% with an equity multiple of 1.18x over the hold period. Turn costs average $321,000 per home, and the in-house maintenance team handles most work orders within 40 days. Homes average 1,701 square feet with average monthly rent of $1,845. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Pool resurfacing	Building	04/26/26	Q1 2025	$50,000	$12,524	Deferred
Exterior paint	Life Safety	04/30/26	Q2 2026	$542,000	$284,706	Deferred
HVAC replacement	Energy	10/12/23	Q1 2025	$344,000	$92,608	In progress
Unit interior upgrades	Site	07/21/23	Q1 2025	$874,000	$917,115	Deferred
Amenity renovation	Building	09/04/23	Q1 2026	$646,000	$168,412	Bidding
Roof replacement - Bldg C	Life Safety	09/12/26	Q3 2025	$866,000	$640,365	Bidding
Door hardware	Site	07/28/23	Q3 2026	$784,000	$681,526	In progress
LED lighting retrofit	Building	02/24/23	Q3 2026	$559,000	$75,281	Bidding
Signage / monument	Life Safety	04/30/24	Q1 2026	$739,000	$67,410	Bidding
Exterior paint	Building	12/13/24	Q3 2027	$126,000	$9,732	In progress
Signage / monument	Building	04/22/23	Q3 2026	$867,000	$55,396	In progress
Roof replacement - Bldg B	Interior	12/13/26	Q1 2025	$786,000	$203,397	Approved
Door hardware	Interior	08/02/26	Q4 2026	$806,000	$365,358	Bidding
Amenity renovation	Life Safety	09/03/24	Q3 2025	$59,000	$26,612	In progress
Security camera upgrade	Energy	02/04/25	Q2 2025	$638,000	$226,125	Deferred
Exterior paint	Life Safety	01/19/26	Q4 2026	$691,000	$61,858	Complete
Landscape / irrigation	Energy	12/05/26	Q3 2025	$123,000	$44,288	Deferred
Landscape / irrigation	Building	06/28/26	Q3 2027	$693,000	$145,097	Complete
Storefront glazing	Life Safety	06/30/24	Q2 2027	$744,000	$106,211	Deferred
Lobby renovation	Energy	12/24/25	Q4 2027	$710,000	$511,410	Complete
Lobby renovation	Interior	12/04/24	Q2 2025	$721,000	$29,774	Complete
Signage / monument	Energy	02/12/26	Q2 2025	$429,000	$52,100	Approved
Fence replacement	Building	09/03/23	Q4 2025	$568,000	$520,019	In progress
Fire alarm panel upgrade	Interior	09/01/24	Q4 2025	$320,000	$126,659	Approved
Security camera upgrade	Interior	08/11/25	Q4 2025	$860,000	$540,282	Deferred
Security camera upgrade	Interior	07/27/24	Q2 2026	$524,000	$456,670	Approved
Elevator modernization	Life Safety	08/21/24	Q4 2025	$223,000	$178,881	Bidding
Pool resurfacing	Energy	09/08/26	Q3 2027	$526,000	$387,608	Bidding
Security camera upgrade	Interior	05/14/24	Q3 2025	$100,000	$19,121	Deferred
ADA compliance	Energy	07/21/25	Q1 2027	$520,000	$195,170	In progress
Water heater replacement	Energy	09/02/24	Q1 2025	$692,000	$452,232	Bidding
Lobby renovation	Energy	10/30/26	Q1 2026	$232,000	$10,147	Complete
Fire alarm panel upgrade	Site	09/03/23	Q4 2025	$117,000	$122,392	Bidding
Elevator modernization	Site	06/15/23	Q1 2027	$849,000	$814,455	Deferred
Water heater replacement	Site	02/25/25	Q2 2026	$307,000	$65,099	Approved
Security camera upgrade	Site	02/13/23	Q3 2025	$445,000	$398,225	Deferred
Landscape / irrigation	Life Safety	09/02/26	Q2 2025	$290,000	$181,026	Deferred
HVAC replacement	Building	01/20/24	Q1 2025	$781,000	$112,630	In progress
Parking lot resurfacing	Site	09/17/24	Q1 2027	$269,000	$218,787	Deferred
HVAC replacement	Life Safety	02/04/25	Q3 2026	$850,000	$867,830	Deferred
Roof replacement - Bldg D	Life Safety	11/23/25	Q2 2026	$593,000	$81,938	Deferred

Report generated 06/06/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $74,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 28 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $333,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Risk Considerations

Homes average 1,701 square feet with average monthly rent of $1,845. Projected levered IRR is 11.9% with an equity multiple of 1.24x over the hold period. Distributions to investors for the quarter were paid at an annualized rate of 6.0% on contributed capital. Turn costs average $335,000 per home, and the in-house maintenance team handles most work orders within 32 days. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Turn costs average $465,000 per home, and the in-house maintenance team handles most work orders within 22 days. Homes average 1,701 square feet with average monthly rent of $1,845. The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

Observed Conditions

Elevators were last modernized 7 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $319,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $20,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 7 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 34 months.

Business Plan Progress

Projected levered IRR is 2.2% with an equity multiple of 1.14x over the hold period. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Turn costs average $458,000 per home, and the in-house maintenance team handles most work orders within 11 days. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Homes average 1,701 square feet with average monthly rent of $1,845.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Summary and Notes

Valuation Discussion

Debt service coverage ratio was 7.94x on a trailing basis against a covenant minimum of 1.20x. Effective gross income for the trailing period was $389,000, representing a 4.3% increase over the prior year. Homes average 1,701 square feet with average monthly rent of $1,845. Turn costs average $309,000 per home, and the in-house maintenance team handles most work orders within 19 days.

A reserve for replacements of $250 per unit has been underwritten in the cash flow below net operating income. Effective gross income for the trailing period was $157,000, representing a 13.6% increase over the prior year. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Operating expenses totaled $288,000 or approximately 29.93 per square foot, with real estate taxes representing the largest line item.

Management Commentary

Preventive maintenance schedules for HVAC, elevators and life-safety systems were completed on time during the period. Homes average 1,701 square feet with average monthly rent of $1,845. Marketing efforts include digital listings, signage, broker outreach and a resident referral program. The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. Turn costs average $376,000 per home, and the in-house maintenance team handles most work orders within 22 days. The manager completes a monthly walk of the property and submits a variance report to the owner by the 40th business day.

The portfolio consists of detached single-family homes in a scattered-site pattern, each with attached garage and fenced yard. The manager completes a monthly walk of the property and submits a variance report to the owner by the 33th business day. Turn costs average $474,000 per home, and the in-house maintenance team handles most work orders within 30 days. Service requests are tracked through a work-order system with an average completion time of 4 hours. Homes average 1,701 square feet with average monthly rent of $1,845. Marketing efforts include digital listings, signage, broker outreach and a resident referral program.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only