PROPERTY CONDITION ASSESSMENT

Beacon Self Storage | Buffalo, NY

Property	Beacon Self Storage
Address	2378 Station Parkway, Buffalo, NY 33880
Site Visit Date	October 19, 2022
Client	Cascadia Rock Capital
Immediate Repairs	$59,000

Building Systems

Beacon Self Storage was originally constructed in 1973 and consists of 622 storage units in a building of 45 stories. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Unit sizes range from 5x5 to 10x30 and the property is managed by an on-site team with online rental capability. Common area interiors have been refreshed within the last 3 years and are in average to good condition.

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Common area interiors have been refreshed within the last 5 years and are in average to good condition. Unit sizes range from 5x5 to 10x30 and the property is managed by an on-site team with online rental capability. The roof is a 33-year membrane system with an estimated remaining useful life of 5 years. Physical occupancy is 92.7% and the average in-place rent is $105 per unit per month. The facility offers climate-controlled and drive-up units, a manager's office, keypad gate access and video surveillance.

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $309,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $480,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Building Systems

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The facility offers climate-controlled and drive-up units, a manager's office, keypad gate access and video surveillance. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Unit sizes range from 5x5 to 10x30 and the property is managed by an on-site team with online rental capability. Mechanical systems include rooftop package units and central plant equipment of varying age. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

Ancillary income includes tenant insurance, merchandise sales and truck rental commissions. The roof is a 42-year membrane system with an estimated remaining useful life of 4 years. Physical occupancy is 94.1% and the average in-place rent is $105 per unit per month. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 6 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $403,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Construction Details

Mechanical systems include rooftop package units and central plant equipment of varying age. The facility offers climate-controlled and drive-up units, a manager's office, keypad gate access and video surveillance. Common area interiors have been refreshed within the last 5 years and are in average to good condition. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

The roof is a 6-year membrane system with an estimated remaining useful life of 6 years. Physical occupancy is 95.8% and the average in-place rent is $105 per unit per month. The facility offers climate-controlled and drive-up units, a manager's office, keypad gate access and video surveillance. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Unit sizes range from 5x5 to 10x30 and the property is managed by an on-site team with online rental capability. Ancillary income includes tenant insurance, merchandise sales and truck rental commissions.

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $152,000. Elevators were last modernized 3 years ago and are operating without deficiency.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $346,000. Elevators were last modernized 6 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Improvements Description

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Common area interiors have been refreshed within the last 9 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age. Ancillary income includes tenant insurance, merchandise sales and truck rental commissions. The facility offers climate-controlled and drive-up units, a manager's office, keypad gate access and video surveillance. The roof is a 35-year membrane system with an estimated remaining useful life of 4 years.

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The facility offers climate-controlled and drive-up units, a manager's office, keypad gate access and video surveillance. Unit sizes range from 5x5 to 10x30 and the property is managed by an on-site team with online rental capability. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Beacon Self Storage was originally constructed in 1973 and consists of 622 storage units in a building of 20 stories.

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 6 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $369,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Elevators were last modernized 3 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $268,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 38 months.

Building Systems

Physical occupancy is 94.1% and the average in-place rent is $105 per unit per month. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Beacon Self Storage was originally constructed in 1973 and consists of 622 storage units in a building of 22 stories. Ancillary income includes tenant insurance, merchandise sales and truck rental commissions.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Beacon Self Storage and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on September 28, 2022.

_____

Olivia Dixon, MAI

Keystone Building Consultants

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only