CAPITAL IMPROVEMENT PLAN

Kingsley Industrial Park | Columbus, OH

Property	Kingsley Industrial Park
Plan Date	May 27, 2026
Prepared For	Anchorage Meadow Partners
Total Plan Budget	$262,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Water heater replacement	Site	11/08/24	Q2 2027	$606,000	$596,650	Approved
Lobby renovation	Building	02/08/23	Q4 2025	$590,000	$323,760	Deferred
Exterior paint	Interior	12/03/24	Q1 2025	$725,000	$101,147	Complete
Parking lot resurfacing	Interior	01/30/25	Q4 2027	$34,000	$24,074	In progress
Storefront glazing	Site	02/27/26	Q4 2027	$579,000	$466,173	Complete
LED lighting retrofit	Life Safety	10/11/23	Q3 2026	$483,000	$182,655	In progress
HVAC replacement	Interior	04/17/23	Q3 2025	$654,000	$644,919	Approved
Door hardware	Life Safety	07/28/24	Q2 2026	$887,000	$260,449	In progress
Roof replacement - Bldg A	Interior	02/25/23	Q4 2026	$48,000	$9,235	Bidding
ADA compliance	Site	07/27/23	Q2 2025	$703,000	$494,824	Deferred
Storefront glazing	Energy	02/11/25	Q1 2026	$561,000	$405,406	Approved
Security camera upgrade	Interior	12/13/25	Q1 2026	$619,000	$261,696	Deferred
HVAC replacement	Building	05/14/25	Q3 2026	$272,000	$17,246	Approved
Unit interior upgrades	Interior	06/11/25	Q4 2027	$792,000	$758,176	Deferred
Security camera upgrade	Building	03/15/24	Q1 2025	$596,000	$510,701	In progress
Door hardware	Energy	12/28/24	Q2 2025	$574,000	$446,374	Approved
Lobby renovation	Energy	02/09/24	Q2 2026	$81,000	$8,663	Bidding
Amenity renovation	Energy	02/04/24	Q1 2025	$189,000	$65,279	Approved
Water heater replacement	Life Safety	07/17/23	Q3 2027	$593,000	$467,352	In progress
LED lighting retrofit	Energy	01/30/23	Q2 2025	$760,000	$758,663	Deferred
Door hardware	Energy	02/14/25	Q2 2026	$419,000	$14,757	Deferred
Landscape / irrigation	Energy	02/09/25	Q2 2027	$320,000	$229,878	Complete
Exterior paint	Life Safety	09/02/23	Q1 2025	$111,000	$116,477	In progress
Fire alarm panel upgrade	Site	06/12/23	Q2 2026	$560,000	$189,770	In progress

Report generated 05/27/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Signage / monument	Energy	11/26/26	Q3 2026	$541,000	$53,930	Deferred
LED lighting retrofit	Building	10/19/24	Q3 2025	$69,000	$4,336	In progress
Storefront glazing	Life Safety	07/29/23	Q3 2025	$620,000	$268,508	Deferred
Unit interior upgrades	Energy	12/09/26	Q1 2025	$302,000	$188,425	In progress
Fire alarm panel upgrade	Energy	05/11/25	Q3 2025	$438,000	$104,536	Bidding
Storefront glazing	Site	11/18/25	Q1 2026	$66,000	$58,861	In progress
Security camera upgrade	Life Safety	09/20/26	Q2 2027	$274,000	$191,316	Approved
LED lighting retrofit	Interior	06/05/23	Q3 2027	$893,000	$374,369	Deferred
Storefront glazing	Building	07/27/26	Q1 2025	$94,000	$4,390	Bidding
Landscape / irrigation	Building	07/17/26	Q3 2027	$892,000	$733,395	Deferred
Fence replacement	Energy	11/26/23	Q1 2026	$642,000	$528,090	Approved
Lobby renovation	Life Safety	12/23/23	Q3 2026	$330,000	$101,901	In progress
Lobby renovation	Life Safety	02/05/25	Q4 2026	$801,000	$477,488	Deferred
Sewer line repair	Energy	05/26/26	Q3 2026	$557,000	$506,350	Deferred
Unit interior upgrades	Building	01/28/24	Q1 2026	$201,000	$108,967	Bidding
Lobby renovation	Site	08/19/23	Q2 2027	$319,000	$197,580	Complete
Unit interior upgrades	Interior	12/08/25	Q4 2026	$189,000	$132,549	In progress
Pool resurfacing	Energy	11/13/26	Q1 2026	$552,000	$76,566	Complete
Door hardware	Energy	04/08/23	Q3 2027	$690,000	$102,837	Bidding
Pool resurfacing	Life Safety	05/09/26	Q1 2027	$213,000	$129,874	Approved
LED lighting retrofit	Building	04/08/25	Q3 2027	$376,000	$213,014	Bidding
Fence replacement	Building	08/06/23	Q1 2026	$647,000	$111,483	Approved
ADA compliance	Interior	10/23/24	Q1 2025	$108,000	$54,445	In progress
Fire alarm panel upgrade	Interior	06/20/24	Q3 2026	$519,000	$136,657	Approved
Landscape / irrigation	Site	07/09/25	Q4 2025	$38,000	$38,768	Bidding
Fence replacement	Site	06/17/23	Q2 2027	$51,000	$10,595	In progress
Fire alarm panel upgrade	Site	07/22/25	Q2 2025	$505,000	$522,600	Deferred
Security camera upgrade	Energy	09/14/26	Q3 2025	$423,000	$58,636	Deferred
Unit interior upgrades	Site	04/16/25	Q1 2026	$726,000	$269,772	Bidding
Elevator modernization	Life Safety	05/26/23	Q2 2027	$524,000	$245,657	In progress
LED lighting retrofit	Building	03/27/26	Q3 2026	$873,000	$35,638	In progress
Fence replacement	Site	08/23/23	Q3 2025	$267,000	$199,599	In progress
Water heater replacement	Energy	04/02/24	Q3 2027	$631,000	$441,910	Bidding
Water heater replacement	Site	02/28/26	Q1 2025	$62,000	$13,098	Deferred
Exterior paint	Life Safety	08/06/23	Q1 2025	$251,000	$129,698	Approved
Elevator modernization	Site	07/13/26	Q1 2027	$637,000	$84,069	Deferred
Water heater replacement	Interior	03/22/25	Q3 2025	$200,000	$76,330	In progress
Sewer line repair	Interior	07/29/25	Q2 2027	$752,000	$140,785	In progress
Pool resurfacing	Life Safety	10/27/24	Q4 2027	$331,000	$613	Approved
Unit interior upgrades	Interior	11/22/24	Q2 2027	$328,000	$308,920	Approved

Report generated 05/27/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $255,000.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Investor Distributions

Distributions to investors for the quarter were paid at an annualized rate of 6.1% on contributed capital. Projected levered IRR is 3.6% with an equity multiple of 1.42x over the hold period. The facility is located 4 miles from the interstate with access to a regional intermodal terminal. In-place rents average $10 per square foot triple net with 3% annual escalations. Cross-dock and rear-load configurations allow for flexible multi-tenant demising.

Projected levered IRR is 9.4% with an equity multiple of 1.4x over the hold period. The business plan contemplates a hold period of 4 years with disposition upon achievement of target returns. In-place rents average $10 per square foot triple net with 3% annual escalations. The facility is located 3 miles from the interstate with access to a regional intermodal terminal.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months. Elevators were last modernized 11 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Business Plan Progress

The facility is located 7 miles from the interstate with access to a regional intermodal terminal. In-place rents average $10 per square foot triple net with 3% annual escalations. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

Projected levered IRR is 4.1% with an equity multiple of 1.22x over the hold period. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. In-place rents average $10 per square foot triple net with 3% annual escalations. The facility is located 5 miles from the interstate with access to a regional intermodal terminal. The building offers 45' clear height, ESFR sprinklers, dock-high and drive-in doors, and a secured truck court with trailer parking. The business plan contemplates a hold period of 10 years with disposition upon achievement of target returns.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 12 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $271,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $350,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 9 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 42 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Unit interior upgrades	Life Safety	07/01/25	Q1 2026	$802,000	$489,717	Approved
Exterior paint	Energy	04/28/24	Q2 2025	$125,000	$91,474	Complete
Roof replacement - Bldg A	Energy	11/15/25	Q4 2027	$823,000	$165,562	In progress
Security camera upgrade	Site	07/07/23	Q2 2026	$238,000	$249,860	Complete
Pool resurfacing	Life Safety	10/28/24	Q2 2027	$770,000	$531,062	Deferred
Landscape / irrigation	Life Safety	06/21/25	Q1 2027	$121,000	$58,494	Complete
Security camera upgrade	Site	04/11/25	Q1 2025	$200,000	$138,868	Deferred
Pool resurfacing	Site	01/31/23	Q1 2026	$250,000	$9,843	In progress
Fire alarm panel upgrade	Interior	05/06/26	Q2 2025	$659,000	$226,300	Deferred
HVAC replacement	Interior	05/25/25	Q4 2026	$23,000	$5,441	Complete
Pool resurfacing	Site	08/23/24	Q1 2027	$181,000	$186,977	Bidding
Parking lot resurfacing	Site	09/27/24	Q1 2027	$387,000	$241,786	Bidding
Unit interior upgrades	Building	11/18/25	Q2 2027	$765,000	$256,438	Deferred
Pool resurfacing	Building	03/17/26	Q1 2025	$882,000	$784,812	Approved
ADA compliance	Site	10/06/23	Q4 2027	$107,000	$39,840	Bidding
Lobby renovation	Building	05/05/26	Q3 2025	$176,000	$65,337	Bidding
Security camera upgrade	Energy	04/09/25	Q2 2025	$136,000	$51,781	In progress
Signage / monument	Building	04/17/23	Q1 2025	$639,000	$347,103	Approved
Amenity renovation	Site	07/08/24	Q2 2026	$611,000	$632,725	Complete
Fence replacement	Energy	11/07/26	Q1 2026	$448,000	$35,284	Complete
Lobby renovation	Building	03/18/25	Q2 2025	$267,000	$204,829	Deferred
Pool resurfacing	Interior	11/06/25	Q3 2027	$489,000	$397,690	Deferred
Amenity renovation	Interior	03/17/24	Q3 2026	$254,000	$171,717	Approved
LED lighting retrofit	Building	04/18/26	Q1 2025	$261,000	$37,031	In progress
Water heater replacement	Building	08/26/24	Q1 2027	$52,000	$1,474	In progress
Water heater replacement	Site	07/28/26	Q4 2026	$704,000	$719,241	Approved
HVAC replacement	Energy	04/12/23	Q1 2026	$857,000	$745,900	In progress
Amenity renovation	Life Safety	01/06/25	Q1 2025	$621,000	$266,933	Approved
Lobby renovation	Building	08/12/26	Q1 2027	$392,000	$169,794	Complete
LED lighting retrofit	Life Safety	03/14/26	Q1 2026	$717,000	$270,311	In progress
Sewer line repair	Interior	03/22/23	Q3 2025	$61,000	$53,460	Approved
Lobby renovation	Site	01/31/23	Q1 2025	$856,000	$277,279	In progress
ADA compliance	Building	02/25/24	Q3 2025	$373,000	$288,117	Bidding
Elevator modernization	Building	06/28/24	Q1 2025	$405,000	$118,257	Bidding
Fence replacement	Building	01/01/25	Q2 2025	$852,000	$305,745	In progress
Sewer line repair	Energy	01/21/23	Q4 2025	$508,000	$210,937	Approved
Fence replacement	Interior	01/23/23	Q1 2026	$711,000	$85,726	In progress
ADA compliance	Site	04/25/24	Q1 2026	$436,000	$12,545	Approved
Signage / monument	Building	04/16/24	Q4 2025	$469,000	$395,026	Deferred
Fire alarm panel upgrade	Interior	02/11/23	Q4 2027	$490,000	$166,971	Complete
Pool resurfacing	Life Safety	04/22/24	Q2 2027	$787,000	$576,514	In progress

Report generated 05/27/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $256,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 11 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Investment Overview

The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns. In-place rents average $10 per square foot triple net with 3% annual escalations. Distributions to investors for the quarter were paid at an annualized rate of 6.0% on contributed capital. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. The building offers 37' clear height, ESFR sprinklers, dock-high and drive-in doors, and a secured truck court with trailer parking. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 33 months. Elevators were last modernized 8 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $242,000.

Business Plan Progress

Cross-dock and rear-load configurations allow for flexible multi-tenant demising. In-place rents average $10 per square foot triple net with 3% annual escalations. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

The business plan contemplates a hold period of 8 years with disposition upon achievement of target returns. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The building offers 5' clear height, ESFR sprinklers, dock-high and drive-in doors, and a secured truck court with trailer parking. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Observed Conditions

Elevators were last modernized 9 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $454,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Unit interior upgrades	Life Safety	08/24/26	Q3 2025	$79,000	$46,460	In progress
Lobby renovation	Building	10/04/23	Q3 2027	$119,000	$29,755	Complete
Security camera upgrade	Interior	07/16/24	Q1 2025	$34,000	$12,084	Bidding
Parking lot resurfacing	Building	12/23/25	Q4 2027	$647,000	$444,811	In progress
Signage / monument	Interior	07/27/25	Q1 2027	$691,000	$595,474	Approved
LED lighting retrofit	Life Safety	02/15/23	Q4 2025	$410,000	$173,678	In progress
Security camera upgrade	Interior	09/02/26	Q1 2027	$284,000	$203,887	Approved
Roof replacement - Bldg B	Life Safety	07/31/25	Q1 2025	$415,000	$193,757	Bidding
LED lighting retrofit	Site	10/09/25	Q4 2026	$319,000	$237,037	Complete
HVAC replacement	Site	02/22/24	Q3 2027	$203,000	$18,908	Approved
Door hardware	Site	10/31/26	Q2 2026	$169,000	$98,134	Approved
Fire alarm panel upgrade	Site	11/27/24	Q1 2027	$437,000	$294,467	Approved
Fire alarm panel upgrade	Building	09/05/26	Q1 2025	$518,000	$430,911	Complete
Unit interior upgrades	Interior	11/19/25	Q1 2027	$189,000	$183,110	Approved
Security camera upgrade	Interior	10/28/24	Q2 2026	$354,000	$44,993	In progress
Sewer line repair	Energy	02/20/24	Q3 2027	$718,000	$460,855	Approved
Security camera upgrade	Building	08/19/24	Q1 2026	$64,000	$33,807	In progress
Fence replacement	Life Safety	07/28/24	Q4 2026	$785,000	$166,510	Complete
Door hardware	Interior	10/24/26	Q4 2026	$679,000	$324,572	Bidding
Water heater replacement	Site	02/16/26	Q2 2027	$284,000	$213,848	Complete
Elevator modernization	Interior	02/21/23	Q2 2026	$644,000	$417,876	Deferred
Door hardware	Interior	09/14/26	Q3 2025	$450,000	$43,339	In progress
LED lighting retrofit	Interior	11/20/25	Q4 2027	$548,000	$154,047	Deferred
Signage / monument	Life Safety	11/21/24	Q3 2027	$358,000	$197,354	Complete
Signage / monument	Building	10/24/26	Q4 2027	$469,000	$90,776	Approved
Pool resurfacing	Site	05/17/26	Q3 2026	$519,000	$395,954	Bidding
Lobby renovation	Building	07/04/23	Q4 2027	$256,000	$65,674	Bidding
Fire alarm panel upgrade	Building	07/12/26	Q2 2027	$458,000	$155,399	Approved
Water heater replacement	Life Safety	09/13/23	Q4 2026	$793,000	$822,080	Approved
ADA compliance	Building	05/25/24	Q3 2027	$360,000	$139,089	Complete
ADA compliance	Building	05/21/24	Q3 2027	$222,000	$41,150	Complete
Security camera upgrade	Interior	09/23/24	Q3 2025	$402,000	$18,603	Bidding
Roof replacement - Bldg A	Site	03/06/24	Q2 2027	$135,000	$29,957	Approved
Signage / monument	Life Safety	01/14/26	Q2 2027	$214,000	$82,326	Deferred
HVAC replacement	Site	10/17/23	Q4 2025	$361,000	$296,641	Complete
Exterior paint	Interior	05/15/26	Q2 2026	$654,000	$526,612	Approved
Signage / monument	Life Safety	05/08/26	Q1 2027	$438,000	$49,445	Complete
Pool resurfacing	Life Safety	11/24/25	Q2 2027	$636,000	$377,678	Bidding
Sewer line repair	Building	07/14/25	Q3 2025	$480,000	$261,445	Deferred
Water heater replacement	Site	12/20/23	Q3 2026	$392,000	$251,390	Approved
LED lighting retrofit	Building	04/19/25	Q2 2026	$385,000	$362,224	Complete

Report generated 05/27/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $310,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 20 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 4 years ago and are operating without deficiency.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $28,000. Elevators were last modernized 5 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 37 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Investor Distributions

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Cross-dock and rear-load configurations allow for flexible multi-tenant demising. Distributions to investors for the quarter were paid at an annualized rate of 5.2% on contributed capital. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

The building offers 27' clear height, ESFR sprinklers, dock-high and drive-in doors, and a secured truck court with trailer parking. Cross-dock and rear-load configurations allow for flexible multi-tenant demising. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The facility is located 7 miles from the interstate with access to a regional intermodal terminal. In-place rents average $10 per square foot triple net with 3% annual escalations. Distributions to investors for the quarter were paid at an annualized rate of 6.0% on contributed capital.

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 7 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Elevators were last modernized 8 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $186,000.

Business Plan Progress

Distributions to investors for the quarter were paid at an annualized rate of 3.0% on contributed capital. The building offers 26' clear height, ESFR sprinklers, dock-high and drive-in doors, and a secured truck court with trailer parking. Cross-dock and rear-load configurations allow for flexible multi-tenant demising. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The facility is located 7 miles from the interstate with access to a regional intermodal terminal.

Cross-dock and rear-load configurations allow for flexible multi-tenant demising. The building offers 29' clear height, ESFR sprinklers, dock-high and drive-in doors, and a secured truck court with trailer parking. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The facility is located 7 miles from the interstate with access to a regional intermodal terminal.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 8 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 5 years ago and are operating without deficiency.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 18 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only