PROPERTY CONDITION ASSESSMENT

Indigo Apartments | Pittsburgh, PA

Property	Indigo Apartments
Address	2656 Highland Parkway, Pittsburgh, PA 86934
Site Visit Date	September 23, 2020
Client	Whitfield Park Capital
Immediate Repairs	$147,000

Improvements Description

Resident turnover has averaged 3.2% annually with renewal retention above 95.8%. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Mechanical systems include rooftop package units and central plant equipment of varying age. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 40 stories. Average in-place rent is $1,852 per month against an average unit size of 721 square feet. The roof is a 42-year membrane system with an estimated remaining useful life of 3 years.

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Mechanical systems include rooftop package units and central plant equipment of varying age. Common area interiors have been refreshed within the last 9 years and are in average to good condition. The roof is a 19-year membrane system with an estimated remaining useful life of 9 years. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes.

Deferred Maintenance

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 6 months. Elevators were last modernized 9 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Elevators were last modernized 8 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $232,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 39 months.

Improvements Description

Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 25 stories. The roof is a 37-year membrane system with an estimated remaining useful life of 6 years. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Common area interiors have been refreshed within the last 7 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Average in-place rent is $1,852 per month against an average unit size of 721 square feet.

Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 27 stories. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Average in-place rent is $1,852 per month against an average unit size of 721 square feet. The roof is a 24-year membrane system with an estimated remaining useful life of 7 years.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 9 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 3 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

Mechanical systems include rooftop package units and central plant equipment of varying age. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Common area interiors have been refreshed within the last 7 years and are in average to good condition. Average in-place rent is $1,852 per month against an average unit size of 721 square feet. Resident turnover has averaged 6.7% annually with renewal retention above 95.7%. The roof is a 26-year membrane system with an estimated remaining useful life of 8 years.

Mechanical systems include rooftop package units and central plant equipment of varying age. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Resident turnover has averaged 5.2% annually with renewal retention above 95.9%.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Elevators were last modernized 5 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $283,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 6 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Building Systems

Mechanical systems include rooftop package units and central plant equipment of varying age. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 44 stories. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Average in-place rent is $1,852 per month against an average unit size of 721 square feet. Common area interiors have been refreshed within the last 8 years and are in average to good condition. Resident turnover has averaged 7.9% annually with renewal retention above 94.8%.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Average in-place rent is $1,852 per month against an average unit size of 721 square feet. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Resident turnover has averaged 11.5% annually with renewal retention above 93.5%.

Recommendations

Elevators were last modernized 7 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $89,000.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $342,000. Elevators were last modernized 10 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Improvements Description

The roof is a 46-year membrane system with an estimated remaining useful life of 5 years. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Common area interiors have been refreshed within the last 7 years and are in average to good condition. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 9 stories. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Common area interiors have been refreshed within the last 3 years and are in average to good condition. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Resident turnover has averaged 4.3% annually with renewal retention above 90.7%.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	13	33	20	Poor	$30,000	$245,000
Paving	18	19	1	Good	$32,000	$128,000
HVAC	15	25	10	Poor	$22,000	$75,000
Plumbing	16	33	17	Fair	$3,000	$155,000
Electrical	9	13	4	Fair	$27,000	$157,000
Elevators	3	26	23	Poor	$9,000	$53,000
Fire/Life Safety	8	31	23	Fair	$7,000	$24,000
Windows	14	29	15	Fair	$32,000	$135,000
Siding/Facade	12	20	8	Fair	$27,000	$240,000
Flooring	17	24	7	Good	$19,000	$8,000
Appliances	11	32	21	Fair	$39,000	$251,000
Landscaping	5	22	17	Poor	$4,000	$114,000
Pool/Amenity	32	37	5	Poor	$22,000	$65,000
Signage	17	27	10	Poor	$16,000	$71,000
Fencing	15	37	22	Fair	$2,000	$254,000
Roof (2)	14	36	22	Fair	$31,000	$204,000
Paving (2)	6	34	28	Good	$37,000	$50,000
HVAC (2)	3	10	7	Fair	$8,000	$16,000
Plumbing (2)	12	17	5	Fair	$35,000	$253,000
Electrical (2)	13	27	14	Good	$34,000	$137,000
Elevators (2)	21	23	2	Poor	$38,000	$21,000
Fire/Life Safety (2)	1	19	18	Fair	$0	$257,000
Windows (2)	6	24	18	Fair	$35,000	$20,000
Siding/Facade (2)	11	30	19	Fair	$1,000	$153,000
Flooring (2)	5	30	25	Poor	$27,000	$43,000
Appliances (2)	8	16	8	Good	$29,000	$168,000
Landscaping (2)	20	32	12	Good	$40,000	$55,000
Pool/Amenity (2)	31	37	6	Poor	$26,000	$161,000
Signage (2)	12	20	8	Fair	$3,000	$118,000
Fencing (2)	12	12	0	Fair	$15,000	$175,000

Report generated 09/23/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Handrail	Roof	Loose	Secure	Year 2-5	$83,500
Window sealant	Bldg B	Failed	Re-caulk	Reserve	$37,500
Sidewalk	Common	Trip hazards	Grind / replace	Year 1	$78,000
Window sealant	Common	Failed	Re-caulk	Year 2-5	$13,500
Water heater	Bldg B	Corrosion	Replace	Year 1	$5,000
Roof membrane	Common	Ponding / seams	Re-seal and repair	Year 1	$76,000
Handrail	Site	Loose	Secure	Reserve	$35,000
Window sealant	Site	Failed	Re-caulk	Immediate	$58,500
Handrail	Common	Loose	Secure	Year 1	$69,500
Handrail	Site	Loose	Secure	Year 2-5	$500
Sprinkler heads	Site	Painted heads	Replace	Year 1	$29,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 1	$37,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Immediate	$13,500
Handrail	Bldg A	Loose	Secure	Immediate	$26,000
Window sealant	Bldg B	Failed	Re-caulk	Immediate	$61,500
Sidewalk	Bldg A	Trip hazards	Grind / replace	Year 2-5	$81,000
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Immediate	$21,000
Window sealant	Bldg A	Failed	Re-caulk	Reserve	$86,000
Sidewalk	Bldg A	Trip hazards	Grind / replace	Immediate	$25,500
Sprinkler heads	Site	Painted heads	Replace	Year 1	$42,000
Dumpster enclosure	Mechanical	Damaged gate	Repair	Reserve	$82,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Reserve	$38,000
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Year 2-5	$1,500
Roof membrane	Common	Ponding / seams	Re-seal and repair	Year 1	$88,000
Stair treads	Common	Worn / loose	Replace treads	Year 1	$10,500
Dumpster enclosure	Site	Damaged gate	Repair	Year 2-5	$20,000
Water heater	Bldg A	Corrosion	Replace	Immediate	$28,000
Window sealant	Roof	Failed	Re-caulk	Reserve	$74,000
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Immediate	$79,000
Sidewalk	Common	Trip hazards	Grind / replace	Year 1	$34,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Reserve	$27,500
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Reserve	$69,500
Water heater	Common	Corrosion	Replace	Year 2-5	$40,500
Fire extinguishers	Mechanical	Expired tags	Service	Immediate	$13,000
Handrail	Bldg A	Loose	Secure	Reserve	$83,500
Fire extinguishers	Bldg B	Expired tags	Service	Year 1	$29,500
HVAC unit	Common	Beyond useful life	Replace RTU	Immediate	$77,500
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Immediate	$4,500
Sidewalk	Bldg A	Trip hazards	Grind / replace	Immediate	$21,000
Water heater	Bldg B	Corrosion	Replace	Immediate	$84,500
Fire extinguishers	Site	Expired tags	Service	Year 2-5	$38,500

Report generated 09/23/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $64,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 7 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 9 years ago and are operating without deficiency.

Deferred Maintenance

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $25,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $86,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 6 years ago and are operating without deficiency.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 11 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $34,000. Elevators were last modernized 8 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Construction Details

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Average in-place rent is $1,852 per month against an average unit size of 721 square feet. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 19 stories.

Resident turnover has averaged 13.9% annually with renewal retention above 88.5%. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 23 stories. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park.

Observed Conditions

Elevators were last modernized 8 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $106,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 33 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $249,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 6 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Building Systems

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Average in-place rent is $1,852 per month against an average unit size of 721 square feet. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 44 stories. Mechanical systems include rooftop package units and central plant equipment of varying age. Resident turnover has averaged 5.1% annually with renewal retention above 94.5%. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

The roof is a 31-year membrane system with an estimated remaining useful life of 7 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Resident turnover has averaged 5.6% annually with renewal retention above 93.7%. Common area interiors have been refreshed within the last 5 years and are in average to good condition. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 5 years ago and are operating without deficiency.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 4 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 47 months.

Construction Details

Mechanical systems include rooftop package units and central plant equipment of varying age. The roof is a 45-year membrane system with an estimated remaining useful life of 11 years. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Resident turnover has averaged 10.0% annually with renewal retention above 91.2%. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 43 stories. Average in-place rent is $1,852 per month against an average unit size of 721 square feet.

Recommendations

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	29	31	2	Fair	$29,000	$131,000
Paving	3	11	8	Fair	$31,000	$273,000
HVAC	14	18	4	Fair	$20,000	$277,000
Plumbing	10	25	15	Fair	$8,000	$231,000
Electrical	24	25	1	Fair	$30,000	$119,000
Elevators	16	25	9	Fair	$40,000	$47,000
Fire/Life Safety	24	37	13	Fair	$21,000	$150,000
Windows	9	25	16	Poor	$32,000	$118,000
Siding/Facade	5	15	10	Poor	$8,000	$30,000
Flooring	9	40	31	Fair	$28,000	$109,000
Appliances	28	34	6	Good	$19,000	$99,000
Landscaping	18	32	14	Fair	$0	$231,000
Pool/Amenity	1	14	13	Fair	$24,000	$145,000
Signage	13	17	4	Fair	$25,000	$253,000
Fencing	15	15	0	Good	$10,000	$66,000
Roof (2)	19	29	10	Fair	$12,000	$271,000
Paving (2)	32	37	5	Good	$9,000	$183,000
HVAC (2)	7	36	29	Good	$30,000	$105,000
Plumbing (2)	15	15	0	Poor	$19,000	$55,000
Electrical (2)	8	28	20	Fair	$28,000	$38,000
Elevators (2)	9	33	24	Good	$31,000	$187,000
Fire/Life Safety (2)	28	33	5	Good	$20,000	$96,000
Windows (2)	12	33	21	Fair	$40,000	$167,000
Siding/Facade (2)	23	30	7	Poor	$5,000	$199,000
Flooring (2)	34	36	2	Poor	$27,000	$198,000
Appliances (2)	10	12	2	Fair	$37,000	$93,000
Landscaping (2)	5	25	20	Fair	$27,000	$113,000
Pool/Amenity (2)	16	40	24	Good	$6,000	$246,000
Signage (2)	25	30	5	Poor	$24,000	$209,000
Fencing (2)	11	18	7	Fair	$15,000	$105,000

Report generated 09/23/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Handrail	Mechanical	Loose	Secure	Year 2-5	$69,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 1	$58,000
Stair treads	Common	Worn / loose	Replace treads	Year 1	$65,500
Sprinkler heads	Roof	Painted heads	Replace	Reserve	$44,500
Dumpster enclosure	Roof	Damaged gate	Repair	Year 2-5	$39,000
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Year 2-5	$67,500
Handrail	Bldg A	Loose	Secure	Year 2-5	$49,000
Handrail	Bldg A	Loose	Secure	Immediate	$49,000
Fire extinguishers	Bldg A	Expired tags	Service	Immediate	$24,000
Window sealant	Bldg A	Failed	Re-caulk	Reserve	$24,500
Dumpster enclosure	Site	Damaged gate	Repair	Year 2-5	$40,500
Fire extinguishers	Site	Expired tags	Service	Reserve	$32,000
Fire extinguishers	Common	Expired tags	Service	Reserve	$78,000
Handrail	Bldg A	Loose	Secure	Reserve	$8,000
Window sealant	Common	Failed	Re-caulk	Year 2-5	$24,000
Window sealant	Bldg B	Failed	Re-caulk	Year 2-5	$89,500
Water heater	Bldg B	Corrosion	Replace	Year 1	$73,000
Sidewalk	Bldg B	Trip hazards	Grind / replace	Year 2-5	$85,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 1	$64,000
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Year 1	$47,000
Dumpster enclosure	Bldg A	Damaged gate	Repair	Year 2-5	$83,500
Dumpster enclosure	Common	Damaged gate	Repair	Reserve	$70,000
Fire extinguishers	Common	Expired tags	Service	Reserve	$85,500
Dumpster enclosure	Roof	Damaged gate	Repair	Immediate	$75,500
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 1	$79,000
Dumpster enclosure	Roof	Damaged gate	Repair	Reserve	$84,000
Handrail	Roof	Loose	Secure	Year 2-5	$10,500
Dumpster enclosure	Roof	Damaged gate	Repair	Year 1	$57,000
Sidewalk	Site	Trip hazards	Grind / replace	Year 1	$30,000
Stair treads	Site	Worn / loose	Replace treads	Reserve	$90,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 2-5	$42,500
Sidewalk	Site	Trip hazards	Grind / replace	Year 1	$72,000
Fire extinguishers	Site	Expired tags	Service	Year 1	$79,000
Dumpster enclosure	Bldg A	Damaged gate	Repair	Reserve	$18,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Year 2-5	$52,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Reserve	$38,500
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Year 1	$500
Stair treads	Common	Worn / loose	Replace treads	Year 2-5	$56,000
Handrail	Mechanical	Loose	Secure	Immediate	$24,000
Asphalt paving	Site	Alligator cracking	Mill and overlay	Year 1	$81,000
Window sealant	Bldg B	Failed	Re-caulk	Reserve	$55,000
Fire extinguishers	Common	Expired tags	Service	Year 1	$44,000
Handrail	Site	Loose	Secure	Immediate	$13,000

Report generated 09/23/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Elevators were last modernized 11 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 24 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $305,000.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $16,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. Elevators were last modernized 8 years ago and are operating without deficiency.

Elevators were last modernized 7 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $239,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 11 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 12 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 43 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Construction Details

Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. The roof is a 41-year membrane system with an estimated remaining useful life of 10 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park.

The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Resident turnover has averaged 4.4% annually with renewal retention above 88.1%. The roof is a 23-year membrane system with an estimated remaining useful life of 9 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months.

Elevators were last modernized 11 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $57,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Building Systems

Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 20 stories. The roof is a 40-year membrane system with an estimated remaining useful life of 4 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Common area interiors have been refreshed within the last 10 years and are in average to good condition. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Mechanical systems include rooftop package units and central plant equipment of varying age. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $277,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Elevators were last modernized 6 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $172,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Building Systems

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 24 stories. Mechanical systems include rooftop package units and central plant equipment of varying age. The roof is a 47-year membrane system with an estimated remaining useful life of 9 years. Common area interiors have been refreshed within the last 4 years and are in average to good condition.

The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Average in-place rent is $1,852 per month against an average unit size of 721 square feet. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Indigo Apartments was originally constructed in 1967 and consists of 255 apartment homes in a building of 24 stories.

Recommendations

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Indigo Apartments and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on September 3, 2020.

Kevin Thompson, RPLS

Northbridge Inspection Services

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only