PROPERTY CONDITION ASSESSMENT

Eastlake Health Center | Buffalo, NY

Property	Eastlake Health Center
Address	3408 Peachtree Boulevard, Buffalo, NY 44465
Site Visit Date	November 20, 2019
Client	Granite Lane Realty
Immediate Repairs	$51,000

Construction Details

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The building is configured for physician practices with plumbing in every suite, imaging-ready floor loads and dedicated medical waste storage. The property is located adjacent to a regional hospital campus and benefits from referral-driven tenancy. The roof is a 5-year membrane system with an estimated remaining useful life of 5 years. Patient parking and ADA-compliant access are provided at a ratio of 18 spaces per 1,000 square feet.

The property is located adjacent to a regional hospital campus and benefits from referral-driven tenancy. Mechanical systems include rooftop package units and central plant equipment of varying age. Patient parking and ADA-compliant access are provided at a ratio of 29 spaces per 1,000 square feet. The roof is a 42-year membrane system with an estimated remaining useful life of 11 years.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 43 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $454,000. Elevators were last modernized 10 years ago and are operating without deficiency.

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $51,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Building Systems

Mechanical systems include rooftop package units and central plant equipment of varying age. Common area interiors have been refreshed within the last 8 years and are in average to good condition. The building is configured for physician practices with plumbing in every suite, imaging-ready floor loads and dedicated medical waste storage. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Patient parking and ADA-compliant access are provided at a ratio of 40 spaces per 1,000 square feet.

The property is located adjacent to a regional hospital campus and benefits from referral-driven tenancy. The building is configured for physician practices with plumbing in every suite, imaging-ready floor loads and dedicated medical waste storage. Patient parking and ADA-compliant access are provided at a ratio of 33 spaces per 1,000 square feet. Eastlake Health Center was originally constructed in 1980 and consists of 153,972 SF in a building of 23 stories.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $139,000. Elevators were last modernized 12 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Common area interiors have been refreshed within the last 8 years and are in average to good condition. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The property is located adjacent to a regional hospital campus and benefits from referral-driven tenancy. Eastlake Health Center was originally constructed in 1980 and consists of 153,972 SF in a building of 18 stories.

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 29-year membrane system with an estimated remaining useful life of 4 years. Rents average $30 per square foot modified gross and leases include tenant improvement allowances for specialized buildout. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 9 months. Elevators were last modernized 4 years ago and are operating without deficiency.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 41 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 7 years ago and are operating without deficiency.

Improvements Description

Patient parking and ADA-compliant access are provided at a ratio of 42 spaces per 1,000 square feet. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 26-year membrane system with an estimated remaining useful life of 9 years. The building is configured for physician practices with plumbing in every suite, imaging-ready floor loads and dedicated medical waste storage. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Common area interiors have been refreshed within the last 9 years and are in average to good condition.

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The property is located adjacent to a regional hospital campus and benefits from referral-driven tenancy. Common area interiors have been refreshed within the last 11 years and are in average to good condition. The building is configured for physician practices with plumbing in every suite, imaging-ready floor loads and dedicated medical waste storage.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $374,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. Elevators were last modernized 12 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $336,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months.

Construction Details

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	14	22	8	Good	$9,000	$260,000
Paving	6	29	23	Poor	$33,000	$236,000
HVAC	24	37	13	Poor	$34,000	$73,000
Plumbing	14	29	15	Fair	$40,000	$131,000
Electrical	9	17	8	Poor	$16,000	$225,000
Elevators	2	18	16	Fair	$19,000	$102,000
Fire/Life Safety	10	33	23	Fair	$32,000	$117,000
Windows	35	39	4	Poor	$2,000	$215,000
Siding/Facade	7	11	4	Fair	$9,000	$64,000
Flooring	10	21	11	Good	$23,000	$30,000
Appliances	21	35	14	Fair	$40,000	$141,000
Landscaping	15	20	5	Good	$9,000	$10,000
Pool/Amenity	6	29	23	Poor	$38,000	$91,000
Signage	12	19	7	Fair	$14,000	$51,000
Fencing	25	30	5	Good	$17,000	$136,000
Roof (2)	3	13	10	Fair	$14,000	$35,000
Paving (2)	10	29	19	Poor	$22,000	$74,000
HVAC (2)	16	27	11	Fair	$23,000	$115,000
Plumbing (2)	6	34	28	Poor	$7,000	$169,000
Electrical (2)	8	14	6	Fair	$26,000	$225,000
Elevators (2)	5	16	11	Fair	$39,000	$278,000
Fire/Life Safety (2)	27	30	3	Fair	$16,000	$138,000
Windows (2)	9	11	2	Fair	$22,000	$175,000
Siding/Facade (2)	6	17	11	Good	$37,000	$148,000
Flooring (2)	16	23	7	Good	$18,000	$59,000
Appliances (2)	16	40	24	Poor	$40,000	$12,000
Landscaping (2)	34	40	6	Poor	$15,000	$267,000
Pool/Amenity (2)	6	30	24	Fair	$24,000	$39,000
Signage (2)	27	39	12	Fair	$0	$22,000
Fencing (2)	1	20	19	Good	$36,000	$5,000

Report generated 11/20/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Window sealant	Common	Failed	Re-caulk	Reserve	$15,000
HVAC unit	Site	Beyond useful life	Replace RTU	Year 1	$3,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Immediate	$4,500
Dumpster enclosure	Roof	Damaged gate	Repair	Reserve	$36,000
Sidewalk	Bldg B	Trip hazards	Grind / replace	Year 2-5	$22,000
Water heater	Bldg B	Corrosion	Replace	Immediate	$73,500
Sprinkler heads	Site	Painted heads	Replace	Reserve	$46,500
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$87,000
Sidewalk	Bldg A	Trip hazards	Grind / replace	Year 2-5	$39,500
Sprinkler heads	Mechanical	Painted heads	Replace	Reserve	$26,500
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Year 1	$41,000
Dumpster enclosure	Roof	Damaged gate	Repair	Reserve	$83,500
Handrail	Bldg A	Loose	Secure	Immediate	$20,500
Dumpster enclosure	Common	Damaged gate	Repair	Year 2-5	$53,500
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Year 2-5	$56,500
Sprinkler heads	Site	Painted heads	Replace	Year 1	$66,500
Fire extinguishers	Common	Expired tags	Service	Year 2-5	$62,500
Window sealant	Mechanical	Failed	Re-caulk	Year 1	$39,500
Sidewalk	Mechanical	Trip hazards	Grind / replace	Immediate	$75,000
Window sealant	Common	Failed	Re-caulk	Year 2-5	$68,500
Window sealant	Site	Failed	Re-caulk	Year 2-5	$8,000
Asphalt paving	Site	Alligator cracking	Mill and overlay	Reserve	$40,000
Water heater	Site	Corrosion	Replace	Year 2-5	$21,500
Dumpster enclosure	Common	Damaged gate	Repair	Year 1	$11,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 2-5	$88,500
Fire extinguishers	Common	Expired tags	Service	Immediate	$20,000
Fire extinguishers	Bldg B	Expired tags	Service	Year 1	$3,000
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Year 1	$80,000
Sidewalk	Site	Trip hazards	Grind / replace	Year 2-5	$57,000
Handrail	Roof	Loose	Secure	Reserve	$32,500
Stair treads	Roof	Worn / loose	Replace treads	Reserve	$50,000
Fire extinguishers	Site	Expired tags	Service	Immediate	$69,500
Water heater	Bldg B	Corrosion	Replace	Reserve	$47,000
Water heater	Common	Corrosion	Replace	Immediate	$50,000
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Immediate	$47,500
Sprinkler heads	Common	Painted heads	Replace	Immediate	$86,500
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Immediate	$2,000
Window sealant	Bldg A	Failed	Re-caulk	Year 1	$35,000
Sidewalk	Bldg A	Trip hazards	Grind / replace	Immediate	$89,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Immediate	$1,500

Report generated 11/20/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Eastlake Health Center and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on October 22, 2019.

_____

Olivia Ito, CPG

Harmon & Pike Engineering

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only